
## **Landmarks Presentation**


January 09, 2018

520 & 550 Clinton Avenue Brooklyn, NY












DEVELOPMENT RIGHTS TRANSFER PARCELS

LI.SALTZMAN ARCHITECTS, PC



ARCHITECTURE AND PRESERVATION

TRANSFER PARCELS R6A LOT10 26200 SQ. FT ZONING DISTRICT BOUNDARY CHURCH OF ST. LUKE & ST. MATTHEW ZONING LOT LINE TAX LOT LINE LOT 7501 (F/K/A 7 & 8) 3750 SQ. FT LOT 51 LOT 7502 3283 SQ. FT (F/K/A 5) 3546 SQ FT LOT 52 10'-0" 2730 SQ. FT C6-3A ON WEST SIDE OF **VANDERBILT** LOT 53 6780 SQ. FT. LOCATION OF LOT 1 PROPOSED DISTRICT 8506 SQ. FT. BOUNDARY TO BE LOT 56 CONFIRMED BY DCP 2690 SQ. FT. 5 2332 SQ. 2332 SQ. FT. **DEVELOPMENT** SITE LOT 59 12561 SQ. FT. ATLANTIC AVE **Proposed Zoning** Development Site Area: 21,068 sf Maximum Permitted FAR 8.0

(with Inclusionary Housing):

Maximum Permitted Floor Area: 168,544 sf

**Development Rights Transfers** 

Proposed Residential Floor Area:

from Church and Other Lots: 70,000 sf (approx) \*

202,041 sf

**Total Allowable Floor Area:** 238,544 sf Proposed Commercial Floor Area: 34,258 sf

Proposed Common Floor Area: 1,682 sf

Total Proposed Floor Area: 237,981 sf


\* Requires Special Permit per 74-711 to transfer floor area across zoning district boundary. Approx. 60,000 sf from church.

NOT TO SCALE





DEVELOPMENT RIGHTS







Constructed 1888-1891; John Welch, Architect / Damaged by fire 1914

1927 photo showing post-fire reconstruction; Dodge & Morrison, Architects

520 & 550 Clinton Avenue, Brooklyn / Landmarks Presentation / January 09, 2018




## PROPOSED DESIGN

- 29 Stories
- 52'-0" Base Height
- 312' Tower Height


## A. Zoning Waivers Requested per ZR 74-711 Special Permit


- a. Transfer of floor area from development rights parcels across district boundary
- b. Non-complying commercial rear yard on second floor per ZR 33-292
- c. Non-complying residential rear yard on floors 3 and above 23-52(b)(2)
- d. Non-complying inner court on floors 3-4 per ZR 23-851(b)
- e. Non-complying window to lot line on floors 3-4 and 6-29 per ZR 23-861
- f. Non-complying lot coverage on interior lot per ZR 23-16(a)
- g. Non-complying street wall height per 23-651(b)(2)
- h. Non-complying tower floor area below 150'-0" per 23-651(a)(3)

B. Residential Parking Waiver Requested per ZR 74-533 Special Permit







































































































**EXISTING** 

**PROPOSED** 

AS-OF-RIGHT






22'-0" TYPICAL BAY


8'-6"

2'-6" 3'-0" 2'-6" 3'-0" 2'-6"


PLAN

PRECAST CONCRETE































С

В



520 & 550 Clinton Avenue, Brooklyn / Landmarks Presentation / January 09, 2018







# APPENDIX












BROWNSTONE SANDSTONE

GRANITE COPPER CAST STONE












BROWNSTONE PATCH- EROSION & MATERIAL LOSS











REPAIR BROWNSTONE CRACK WITH COMPOSITE MORTAR










BROWNSTONE INCOMPATIBLE PATCH REMOVAL AND REPLACEMENT










BROWNSTONE REPLACEMENT
WITH NEW CAST STONE TO
MATCH ORIGINAL BROWNSTONE










REPOINT DETERIORATE BROWNSTONE JOINTS WITH NEW MORTAR TO MATCH ORIGINAL. INSTALL WEATHER CAPS AT ROOF LEVEL.












REPLACE DAMAGED COPPER GUTTER WITH NEW COPPER GUTTER TO MATCH ORIGINAL. REPLACE DAMAGED SHEET METAL CROSS AND FLASHING ON BELFRY WITH NEW COPPER CROSS AND FLASHING.











COATING REMOVAL, REPAIR, AND REPOINTING OF SANDSTONE







SANDSTONE AND GRANITE PATCH REPAIR










SCRAPE, PRIME, REPAINT, AND SEAL SHEET METAL WHEEL WINDOW. SAND AND REPAINT WOOD TURRET LOUVERS









REMOVE AND REPLACE DAMAGED PROTECTIVE GLAZING. SCRAPE AND PAINT DETERIORATED WOOD WINDOW FRAMES. PROVIDE NEW CAULKING AT WINDOW PERIMETER.








REPLACE DAMAGED COPING STONES WITH NEW CAST STONE COPING STONES. REPAIR BRICK CRACKS ON CHIMNEY



58





REPLACE BELFRY ROOF WITH NEW SLATE TO MATCH EXISTING SLATE PRESENT ON CLOISTER ROOF. SELECTIVE REPLACEMENT OF SLATE SHINGLES AT CLOISTER ROOF, ASSUME 10%.




# CHURCH


### **MASONRY SCOPE OF WORK:**

- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Retool or Composite Patch Deteriorated Stone
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Remove Ferrous Materials at Former Plaque Location
- Stabilize Entry Landing Substructure, Remove and Reinstall Tiles.

## **WINDOW SCOPE OF WORK:**

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter
- Scrape and Repaint Sheet Metal Wheel Window









LI.SALTZMAN ARCHITECTS, PC

# **CLOISTER**

### **MASONRY SCOPE OF WORK:**


- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Replace Brownstone Colonette Shaft
- Stabilize Entry Landing Substructure, Remove and Reinstall Tiles.


### **ROOF SCOPE OF WORK:**

• Repair/Replace Gutter

### WINDOW SCOPE OF WORK: (SELECTIVE WINDOWS)

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter Repair Second Floor Stained Glass Windows










# CHAPEL


### MASONRY SCOPE OF WORK:

- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Retool or Composite Patch Deteriorated Stone
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Replace Missing Stone Cross

### WINDOW SCOPE OF WORK:

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter








LI.SALTZMAN ARCHITECTS, PC


### **MASONRY SCOPE OF WORK:**

- Create Structurally Stable Conditions
- Facade Cleaning
- Rebuild Deteriorated Brownstone to Match Original
- Rebuild Deteriorated Brick to Match Original
- Repair Cracks in Brownstone
- Remove Incompatible Patching
- Patch Brownstone/Sandstone to Match Original
- Repoint Deteriorated Masonry Joints to Match Original Mortar

### **ROOF/WATERPROOFING SCOPE OF WORK:**


- Replace Roofing to Match Historic Material
- Repair Beaded Board Wood Ceiling
- Add new Infill Substrate, Pitched to Drain, and Flashing with Drip Edge at Juncture of Stone Exterior and Belfry Floor








- DETAILS:E4 Repair Crack in BrownstoneE5 Repair Crack in Brownstone




- <u>DETAILS:</u>
   E11 Repair Beaded Board Wood Ceiling
- E12 Repoint Deteriorated Masonry Joints to Match Original Mortar



- <u>DETAILS:</u>

   E13 Provide Structural Reinforcement at Floor Level
- E14 Rebuild Deteriorated Brick Pier Create Structurally Stable Conditions





LI-SALTZMAN ARCHITECTS, PC ARCHITECTURE AND PRESERVATION


# COURTYARD

### **DETAILS:**

- F47 Repoint Deteriorated Masonry Joints
   F54 Restore Drainage System From Church Roof to Courtyard Pavers
   F58 Major Restoration Work Required at Sanctuary Window 113
   F59 Repair and Secure All Operable Windows in Parish Hall













VIEW FROM LOWER COURTYARD AREA

LI.SALTZMAN ARCHITECTS, PC

# **COURTYARD**

- <u>DETAILS:</u>

   F49 Provide New Roof /Concrete on Elevated Area Adjacent to Sanctuary
  • F56 Seal Openings Along Exterior Wall
- F57 Stained Glass Windows in Sanctuary Facing Courtyard to Receive Protective Glazing








LI.SALTZMAN ARCHITECTS, PC



# CHANCEL

### MASONRY SCOPE OF WORK:

- Patch Brownstone Match OriginalRebuild Brownstone to Match Original



LI·SALTZMAN ARCHITECTS, PC







# CHANCEL


### DETAILS:

• F5 Rebuild Areas of Deteriorated Brownstone

• F6 Patch Brownstone to Match Original








## NORTH TRANSEPT

#### DETAILS:

• F8 General Facade Cleaning/Remove Graffiti




## RECTORY (Vanderbilt Avenue)

#### MASONRY SCOPE OF WORK:

- Patch Brownstone Match Original
- Repair Cracks in Brownstone

#### DOOR SCOPE OF WORK:

Replace Metal Door with Historically Appropriate Wood Door









# RECTORY

#### **DETAILS**:

- F24 Patch Brownstone to Match Original
- F26 Patch Brownstone to Match Original



## **RECTORY**



					RESTO	ATION A	ND REPAIR SCHEDULE					
	woo	(WD)				TAG		TREATMENT	DWG. REF.	PHOTO REF.	SPEC. REF. NOTES	
		WD-1 BEADED BOARD WOOD CEILING REPAIR	INSPECT AND REPAIR BEADED BOARD WOOD CEILING OF BELFRY AS REQUIRED.		GENER		CLEANING (CL) FACADE CLEANING	CLEAN FACADE ELEMENTS BASED ON RESULTS	N/A		040310	
		WD-2 WOOD WINDOW SILL REPLACEMENT	REPLACE DAMAGED AND DETERIORATED WOOD WINDOW SILL WITH NEW TO MATCH ORIGINAL			CL-2	GRAFFITI REMOVAL	OF TESTING  REMOVE GRAFFITI BASED ON RESULTS OF	N/A		040310	
		WD-3 WOOD DOOR REPLACEMENT	REPLACE EXISTING HOLLOW METAL DOOR WITH NEW HISTORIC STYLE WOOD DOOR SET WITHIN EXISTING		BROWN	STONE (ST1	1)	TESTING				
			HISTORIC WOOD FRAME. DESIGN TO BE PROVIDED BY THE ARCHITECT.			ST1-1	BROWNSTONE PATCH PATCHING — EROSION REPAIR	REPLACE AREAS OF EROSION WITH NEW COMPOSITE PATCH TO MATCH ORIGINAL TOOLING			040342	
		WD-4 WOOD FRAMED FLOOR REPAIR	STRUCTURAL ENGINEER TO INSPECT EXISTING WOOD FRAMED FLOOR OF BELFRY. REPAIR OR REPLACE AS PER ENGINEER'S RECOMMENDATIONS.			ST1-2	BROWNSTONE PATCH PATCHING -	REPLACE AREAS OF MATERIAL LOSS WITH NEW COMPOSITE PATCH TO MATCH ORIGINAL. REPLICATE	:		040342	
	ROOF	NG (R)	INSPECT ENTIRE ROOF FOR DAMAGED OR	073126		(ST1-3)	MATERIAL LOSS REPAIR	ORIGINAL TOOLING AS REQUIRED.  REMOVE AREAS OF INCOMPATIBLE PATCHING AND REPLACE WITH NEW COMPOSITE PATCH TO MATCH	+		040342	
		R-1 SLATE SHINGLE REPLACEMENT	IMPROPERLY INSTALLED SLATE SHINGLES. REPLACE SHINGLES AS NEEDED, INCLUDING REPLACING	075120			REMOVAL	ADJACENT ORIGINAL BROWNSTONE. REPLICATE ORIGINAL TOOLING AS REQUIRED.				
			UNDERLAYMENT AS REQUIRED. SLATE TO MATCH HISTORIC GRAY SLATE ON CLOISTER ROOF.			ST1-4	BROWNSTONE REPOINTING	REPOINT WITH MORTAR MATCHING ORIGINAL.			040343	
		R-2 NEW FLUID-APPLIED MEMBRANE ROOF	INSTALL NEW COLD FLUID APPLIED ROOF SYSTEM			ST1-5)	BROWNSTONE REPLACEMENT	REMOVE EXISTING DETERIORATED BROWNSTONE AND REPLACE WITH NEW TO MATCH ORIGINAL IN SIZE, SHAPE, APPEARANCE, AND TEXTURE			040342	
	GLAZ	NG (GZ)  GZ-1 STAINED GLASS WINDOW	INSPECT DAMAGED STAINED GLASS WINDOW WITH			ST1-6	BROWNSTONE CRACK REPAIR	REPAIR CRACK WITH COMPOSITE MORTAR PATCH. MATCH ADJACENT BROWNSTONE COLOR & TOOLING			040342	
		REPAIR AND CONSERVATION	STAINED GLASS RESTORATION SPECIALIST. SCOPE OF REPAIR/CONSERVATION WORK TO BE			ST1-7		REMOVE EXISTING FERROUS MATERIAL EMBEDDED WITHIN BROWNSTONE. DETERGENT CLEAN	1		040342	
		GZ-2 GLAZING PANEL	DETERMINED BASED ON FINDINGS  REPLACE MISSING GLASS PANEL WITH NEW TO			(ST1-8)	BROWNSTONE BROWNSTONE SILL	BROWNSTONE UNIT TO REMOVE STAINING  REMOVE EXISTING DETERIORATED BROWNSTONE SILL	_		040342	
		REPLACEMENT  GZ-3 STAINED GLASS IN-SITU	MATCH ORIGINAL  REPAIR STAINED GLASS WINDOW IN SITU IN ORDER				COURSE REPLACEMENT	COURSE AND REPLACE WITH NEW TO MATCH EXISTING IN SIZE, SHAPE, PROFILE, AND TEXTURE. SHORE AS REQUIRED.				
		REPAIR	TO RESTORE FULL OPERABILITY AND RE-LEAD AS REQUIRED. SEE FEMENELLA & ASSOCIATES REPORT FOR SPECIFIC SCOPE OF WORK PER WINDOW.		SANDS	ONE (ST2)					T040747	_
	PROT	ECTIVE GLAZING (W)  CLOISTER PROTECTIVE	REMOVE EXISTING PROTECTIVE GLAZING AND			ST2-1	SANDSTONE COATING REMOVAL AND REPOINTING	REMOVE EXISTING COATING ON SANDSTONE SURFACE BASED ON TESTING TO EXPOSE ORIGINAL COLOR AND TEXTURE. REPOINT JOINTS 100%.			040343 040310	
<u> </u>		GLAZING TYPE 1 REPLACEMENT	REPLACE WITH NEW TO MATCH ORIGINAL			(ST2-2)	RUSTICATED SANDSTONE EROSION REPAIR	CHIP FLAKING SANDSTONE BACK TO SOUND STONE IF APPROPRIATE PATCH STONE TO MATCH ORIGINAL RUSTICATED APPEARANCE	-		040342	
		W-2 CLOISTER PROTECTIVE GLAZING TYPE 2 REPLACEMENT	REMOVE EXISTING PROTECTIVE GLAZING AND REPLACE WITH NEW TO MATCH ORIGINAL			ST2-3	SANDSTONE PATCH PATCHING -	REPLACE AREAS OF MATERIAL LOSS WITH NEW COMPOSITE PATCH TO MATCH ORIGINAL. REPLICATE			040342	
		W-3 CHAPEL PROTECTIVE GLAZING TYPE 1	REMOVE EXISTING PROTECTIVE GLAZING AND REPLACE WITH NEW TO MATCH ORIGINAL			(ST2-4)	MATERIAL LOSS REPAIR SANDSTONE	ORIGINAL TOOLING OR PROFILES AS REQUIRED.  REMOVE AREAS OF INCOMPATIBLE PATCHING AND	+		040342	
		REPLACEMENT  CHAPEL PROTECTIVE GLAZING TYPE 2	REMOVE EXISTING PROTECTIVE GLAZING AND			(3124)	INCOMPATIBLE PATCH REMOVAL	REPLACE WITH NEW COMPOSITE PATCH TO MATCH ADJACENT. REPLICATE ORIGINAL TOOLING AS REQUIRED				
		REPLACEMENT CHAPEL PROTECTIVE	REPLACE WITH NEW TO MATCH ORIGINAL  REMOVE EXISTING PROTECTIVE GLAZING AND			ST2-5	SANDSTONE CRACK REPAIR	REPAIR CRACK WITH COMPOSITE MORTAR PATCH. MATCH ADJACENT SANDSTONE COLOR & TOOLING.			040342	
		W-5 GLAZING TYPE 3 REPLACEMENT	REPLACE WITH NEW TO MATCH ORIGINAL			ST2-5	SANDSTONE COLUMN BASE REPOINTING	REMOVE EXISTING MORTAR AND REPOINT WITH MORTAR MATCHING ORIGINAL AT TOP AND BOTTOM			040343	
		W-6 CHAPEL PROTECTIVE GLAZING TYPE 4 REPLACEMENT	REMOVE EXISTING PROTECTIVE GLAZING AND REPLACE WITH NEW TO MATCH ORIGINAL			ST2-6	SANDSTONE COLUMN BASE REPLACEMENT	JOINTS OF SANDSTONE COLUMN BASE  REMOVE EXISTING DETERIORATED SANDSTONE COLUMN BASE ELEMENT IN SIZE, SHAPE,	+		040342	
		W-7 CHAPEL PROTECTIVE GLAZING TYPE 5	REMOVE EXISTING PROTECTIVE GLAZING AND REPLACE WITH NEW TO MATCH ORIGINAL			(ST2-7)		APPEARANCE, AND TEXTURE  REMOVE EXISTING DETERIORATED SANDSTONE	+		040342	
1,454,		REPLACEMENT  INTERIOR COURTYARD PROTECTIVE GLAZING	INSTALL NEW PROTECTIVE GLAZING UNITS AT SIDE AISLE WINDOWS FACING THE INTERIOR COURTYARD				ELEMENT REPLACEMENT	COLUMN ELEMENT IN SIZE, SHAPE, APPEARANCE, AND TEXTURE				
		INSTALLATION	THE		GRANIT	(ST3)	GRANITE PATCHING -	REPLACE AREAS OF MATERIAL LOSS WITH NEW	$\overline{}$		040342	
			^		0.07	(ST3-1)	MATERIAL LOSS REPAIR	COMPOSITE PATCH TO MATCH ORIGINAL. REPLICATE ORIGINAL TOOLING AND PROFILES AS REQUIRED.				
			식 는		CAST	TONE (CS)	CHIMNEY COPING STONE REPLACEMENT	REMOVE EXISTING CHIMNEY COPING STONES AND REPLACE WITH NEW CAST STONE COPING STONES	T		047200	_
			Ħ		BRICK	(B)	STONE REPLACEMENT	TO MATCH ORIGINAL IN SIZE, SHAPE, AND PROFILE	<u>:</u>			
		Q	A A				BRICK REPOINTING	REPOINT EXISTING BRICK MORTAR JOINTS TO MATCH ORIGINAL. ASSUME 60% OF FACADE	T		040323	
		$\mathcal{A}$		4				INCLUSIVE OF LOCATED AREAS INDICATED ON DRAWINGS			0.40700	
						(B-2)	BRICK CRACK REPAIR  MISCELLANEOUS BRICK	REPLACE CRACKED BRICK UNIT(S) TO MATCH ORIGINAL REPLACE DAMAGED OR MISSING BRICK UNIT(S) TO			040322	
<del></del>						(B-3)	REPLACEMENT	MATCH ORIGINAL  REMOVE LOOSE PARGING VIA MECHANICAL MEANS	+		040322	
<u></u>					CONCR	ETE (C)	BRICK	TO EXPOSE BRICK FACE				
						C-1	CONCRETE SLAB REPLACEMENT	REMOVE EXISTING CONCRETE SLAB IN INTERIOR COURTYARD AND REPLACE WITH NEW 6" THICK				
					STUCC	) (S)		CONCRETE SLAB. PITCH TO DRAIN				
	**********					(S-1)	ONE OR TWO-COAT STUCCO REPLACEMENT	REMOVE AND REPLACE LOOSE, CRACKED, OR BLISTERED STUCCO AT INTERIOR COURTYARD WALL			092400	
					SHEET	METAL/COP	GUTTER REPLACEMENT	REMOVE EXISTING GUTTER & INSTALL COPPER	$\top$			
						(SM1-1)	111 020101211 11001	GUTTER, INCLUDING NEW DRAIN OUTLETS AND GUTTER SCREENS. MATCH EXISTING PROFILES				
	<del>┦</del> <del>╸</del> <del>┦╸┩╸┩╸┩╸┩╸┩╸┩</del>			<b>#</b>		SM1-2	BELFRY LEDGE FLASHING INSTALLATION	INSTALL NEW INFILL SUBSTRATE, PITCHED TO DRAIN, AND COPPER FLASHING WITH DRIP EDGE AT JUNCTURE OF EXTERIOR STONE AND BELFRY				
						(014.0)	. COPPER CROSS	FLOOR REMOVE EXISTING DAMAGED SHEET METAL CROSS	+			
	<u>╶</u> ┼╀╾╂┤ <u>╶┼</u> ║┣═╢╟═╢┼╴┼╂═╂╴					(SM1-3)	REPLACEMENT	AT BELFRY AND INSTALL NEW COPPER CROSS. REPLICATE ORIGINAL.				
TO THE MEMORY OF AN ONLY CHILD						SM1-4	COPPER LEADER REPLACEMENT	REMOVE EXISTING LEADER AND REPLACE WITH NEW COPPER LEADER TO MATCH ORIGINAL				
				五 月		(SM1-5)	NEW COPPER LEADER	INSTALL NEW COPPER LEADER	+		+ +	
				<b>對</b>		SM1-6)	COPPER GUTTER REPLACEMENT	INSTALL NEW COPPER GUTTER INCLUDING NEW DRAIN OUTLETS	+		+ +	
				相 日田		_	COPPER GUTTER	INSPECT EXISTING COPPER GUTTER AND REMOVE	+	<del>                                     </del>	+	
				日   日		(SM1-7)	INSPECTION AND DEBRIS REMOVAL	ANY DEBRIS FOUND TO ENSURE PROPER WATER FLOW AND DRAINAGE				
					SHEET	METAL/STEE (SM2-1)	SHEET METAL WHEEL	SCRAPE, PRIME, & PAINT SHEET METAL WHEEL	T		040310	
±43'-6"	±33'-0"		±58'-6"		-		WINDOW PRIME & PAINTING	WINDOW	$\perp$			




CHURCH OF ST.LUKE & ST.MATTHEW ELEVATION KEY

LI.SALTZMAN ARCHITECTS, PC

ARCHITECTURE AND PRESERVATION





PAINT EXISTING WOOD OR SHEET METAL WINDOW FRAME WITH BENJAMIN MOORE "BROWNSTONE




CLINTON AVENUE ELEVATION - CHURCH AND CLOISTER

A-200 SCALE: 1/4"-1"-1"






CLINTON AVENUE ELEVATION - CHAPEL










LI.SALTZMAN ARCHITECTS, PC


ARCHITECTURE AND PRESERVATION


















1 VANDERBILT AVENUE ELEVATION

A-206 SCALE: 1/4'=1'.0'

LI.SALTZMAN ARCHITECTS, PC

ARCHITECTURE AND PRESERVATION

