
Landmarks Presentation

March 13, 2018


520 & 550 Clinton Avenue Brooklyn, NY














Constructed 1888-1891; John Welch, Architect / Damaged by fire 1914

1927 photo showing post-fire reconstruction; Dodge & Morrison, Architects















520 & 550 Clinton Avenue, Brooklyn / Landmarks Presentation / March 13, 2018









COMPOSITE PATCHING:

1. WHEN SCAFFOLDING IS IN PLACE, THE CONTRACTOR IS TO PROVIDE A HANDS-ON SOUNDING OF ALL MASONRY AND REPORT FINDINGS TO THE ARCHITECT AND STRUCTURAL ENGINEER.

2. REPLACE AREAS OF MATERIAL LOSS WITH NEW COMPOSITE PATCHING TO MATCH THE ORIGINAL IN APPEARANCE, PROFILE, AND TOOLING.








BROWNSTONE RETOOLING:

- 1. WHEN SCAFFOLDING IS IN PLACE, THE CONTRACTOR IS TO PROVIDE A HANDS-ON SOUNDING OF ALL MASONRY AND REPORT FINDINGS TO THE ARCHITECT AND STRUCTURAL ENGINEER.
- 2. REMOVE PREVIOUS NON-MATCHING PATCHES AND DETERIORATED BROWNSTONE BACK TO SOUND STONE AND RETOOL ORIGINAL STONE.
- 3. IF RETOOLING CREATES A SHELF CONDITION THAT WOULD NOT SHED WATER, PROVIDE DUTCHMAN OR COMPOSITE PATCH TO ENSURE THE SHEDDING OF WATER. NO COMPOSITE PATCH SHALL BE GREATER THAN 1-1/2" IN DEPTH.











DUTCHMAN REPAIR:

- 1. WHEN SCAFFOLDING IS IN PLACE, THE CONTRACTOR IS TO PROVIDE A HANDS-ON SOUNDING OF ALL MASONRY AND REPORT FINDINGS TO THE ARCHITECT AND STRUCTURAL ENGINEER.
- 2. REMOVE DETERIORATED AREA OF EXISTING BROWNSTONE UNIT BACK TO STABLE STONE AND REPAIR WITH DUTCHMAN TO MATCH ORIGINAL BROWNSTONE IN APPEARANCE, PROFILE, AND TOOLING














REPLACEMENT IN CAST STONE:

- 1. WHEN SCAFFOLDING IS IN PLACE, THE CONTRACTOR IS TO PROVIDE A HANDS-ON SOUNDING OF ALL MASONRY AND REPORT FINDINGS TO THE ARCHITECT AND STRUCTURAL ENGINEER.
- 2. REPLACE SEVERELY DETERIORATED BROWNSTONE COLONETTE SHAFTS WITH NEW CAST STONE UNITS TO MATCH ORIGINAL IN APPEARANCE, PROFILE, AND TOOLING











































































APPENDIX





Maximum Permitted FAR (with Inclusionary Housing):

8.0 Maximum Permitted Floor Area: 168,544 sf

Development Rights Transfers

from Church and Other Lots: 70,000 sf (approx) *

Total Allowable Floor Area: 238,544 sf Proposed Commercial Floor Area: 34,258 sf


Proposed Residential Floor Area: 202,041 sf

Proposed Common Floor Area: 1,682 sf

Total Proposed Floor Area: 237,981 sf

* Requires Special Permit per 74-711 to transfer floor area across zoning district boundary. Approx. 60,000 sf from church.

35





DEVELOPMENT RIGHTS TRANSFER PARCELS

PROPOSED ZONING LOT

PROJECT SITE


PACIFIC PARK (PROPOSED & UNDER CONSTRUCTION)


LI.SALTZMAN ARCHITECTS, PC





















PROPOSED

AS-OF-RIGHT
















































PRECAST CONCRETE










ELEVATION






CHURCH


MASONRY SCOPE OF WORK:

- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Retool or Composite Patch Deteriorated Stone
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Remove Ferrous Materials at Former Plaque Location
- Stabilize Entry Landing Substructure, Remove and Reinstall Tiles.

WINDOW SCOPE OF WORK:

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter
- Scrape and Repaint Sheet Metal Wheel Window







CLOISTER

MASONRY SCOPE OF WORK:


- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Replace Brownstone Colonette Shaft
- Stabilize Entry Landing Substructure, Remove and Reinstall Tiles.


ROOF SCOPE OF WORK:

• Repair/Replace Gutter

WINDOW SCOPE OF WORK: (SELECTIVE WINDOWS)

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter Repair Second Floor Stained Glass Windows










CHAPEL


MASONRY SCOPE OF WORK:

- Clean Facade
- Repoint Deteriorated Masonry Joints to Match Original Mortar
- Remove Incompatible Patching
- Retool or Composite Patch Deteriorated Stone
- Patch Brownstone/Sandstone to Match Original
- Repair Cracks in Brownstone
- Repair Granite Columns
- Replace Missing Stone Cross

WINDOW SCOPE OF WORK:

- Clean Windows
- Scrape and Paint Deteriorated Window Frames
- Replace Damaged Protective Glazing
- Provide New Caulking at Window Perimeter









MASONRY SCOPE OF WORK:

- Create Structurally Stable Conditions
- Facade Cleaning
- Rebuild Deteriorated Brownstone to Match Original
- Rebuild Deteriorated Brick to Match Original
- Repair Cracks in Brownstone
- Remove Incompatible Patching
- Patch Brownstone/Sandstone to Match Original
- Repoint Deteriorated Masonry Joints to Match Original Mortar

ROOF/WATERPROOFING SCOPE OF WORK:

- Replace Roofing to Match Historic Material
- Repair Beaded Board Wood Ceiling
- Add new Infill Substrate, Pitched to Drain, and Flashing with Drip Edge at Juncture of Stone Exterior and Belfry Floor









LI.SALTZMAN ARCHITECTS, PC

- DETAILS:E4 Repair Crack in BrownstoneE5 Repair Crack in Brownstone




- <u>DETAILS:</u>
 E11 Repair Beaded Board Wood Ceiling
- E12 Repoint Deteriorated Masonry Joints to Match Original Mortar



LI-SALTZMAN ARCHITECTS, PC ARCHITECTURE AND PRESERVATION

- <u>DETAILS:</u>

 E13 Provide Structural Reinforcement at Floor Level
- E14 Rebuild Deteriorated Brick Pier Create Structurally Stable Conditions




LI-SALTZMAN ARCHITECTS, PC ARCHITECTURE AND PRESERVATION


COURTYARD

DETAILS:

- F47 Repoint Deteriorated Masonry Joints
 F54 Restore Drainage System From Church Roof to Courtyard Pavers
 F58 Major Restoration Work Required at Sanctuary Window 113
 F59 Repair and Secure All Operable Windows in Parish Hall


















COURTYARD

- <u>DETAILS:</u>


 F49 Provide New Roof /Concrete on Elevated Area Adjacent to Sanctuary
 • F56 Seal Openings Along Exterior Wall
- F57 Stained Glass Windows in Sanctuary Facing Courtyard to Receive Protective Glazing








LI.SALTZMAN ARCHITECTS, PC



CHANCEL

MASONRY SCOPE OF WORK:

- Patch Brownstone Match OriginalRebuild Brownstone to Match Original








CHANCEL


DETAILS:


• F5 Rebuild Areas of Deteriorated Brownstone

• F6 Patch Brownstone to Match Original



LI·SALTZMAN ARCHITECTS, PC ARCHITECTURE AND PRESERVATION






NORTH TRANSEPT

DETAILS:

• F8 General Facade Cleaning/Remove Graffiti




RECTORY (Vanderbilt Avenue)

MASONRY SCOPE OF WORK:

- Patch Brownstone Match Original
- Repair Cracks in Brownstone

DOOR SCOPE OF WORK:

Replace Metal Door with Historically Appropriate Wood Door









RECTORY

DETAILS:

- F24 Patch Brownstone to Match Original
- F26 Patch Brownstone to Match Original



RECTORY





LI·SALTZMAN ARCHITECTS, PC