THE ORIGINAL WINDOW CONFIGURATION SHOWN IN THE PHOTOGRAPH FROM THE ARCHIVES OF LANDMARKS PRESERVATION COMMISSION SHOW ELONGATED WINDOWS WITH A DECORATIVE BALCONY AT THE SECOND FLOOR.



Archive # 1247-126

THE NEXT PHOTO FROM THE PERIOD OF THE LANDMARKS DESIGNATION IN 2012 SHOWS A RADICALLY ALTERED SECOND FLOOR WINDOW CONFIGURATION-MUCH SMALLER AND WITH THE DECORATIVE BALCONY REMOVED.




THE CURRENT COLOR PHOTOGRAPH SHOWS A VIEW SIMILAR TO THE 2012 DESIGNATION ERA PHOTOGRAPH REGARDING THE SECOND FLOOR WINDOWS. THE 8 OVER 8 WINDOW PANE CONFIGURATION REMAINS, AND THE OWNER IS WILLING TO REPLACE THE INTERIOR WINDOW MUNTINS WITH EXTERIOR MUNTINS.



309 West 85 Street, New York, NY 10024 FULL COLOR VIEW OF STREET FAÇADE WITH NEWLY INSTALLED ALUMINUM WINDOWS.






SCALE: 3/4"=1'-0"

309 West 85 Street, New York, NY 10024

SHEET A



EXISTING **BRICK WALL**

WINDOW STONE SILL

WOOD FRAME


MUNTIN ON EXTERIOR OF GLASS


SINGLE PANE

EXISTING METAL LINTEL

INTERIOR

SHEET B







EXISTING **BRICK WALL**

WINDOW STONE SILL

EXTRUDED ALUMINUM FRAME

MUNTIN ON EXTERIOR OF GLASS

EXISTING METAL LINTEL

SHEET C