

cident Date	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	13	EAST 7 STREET	0	1 The New York City Police Department propried that an exterminator feel link o as ix foot deep excavation in the basement. A DOB inspector reported that the worker suffered minor ingrises and was taken to Bellevue Hospital and that there was unpermitted excavation work being performed in the basement. An Agravated Level 2 ECB Violation was issued for a failure to safeguard and work without a permit. A full Stop Work Order was issued.	ECB Violation	35309613X		No Permit	No Permit	Worker Fell	TRIAD CAPITAL, LLC	No Permit
2018	Manhattan	269		0	The Site Safety Manager reported that a worker was cleaning a platform from a multipoint scaffold when he slipped and fell five feet onto the ground, hitting his right elbow. An ambulance was on site. Four ECB Violations and a partial Stop Work Order were issued.		35285606Y, 35285607X, 35285608H, 35285609J				Worker Fell	RIVERVIEW OPERATING CO., LLC	Leeding Builders Group LLC
2018	Manhattan	430	EAST 58 STREET	0	The Site Safety Manager reported that a worker got his hand stuck between a steel plate and a frame and got two of his fingers crushed. The worker was sent to Bellevue Hospital.	No Dispatch					Other Construction Related Incidents	SUTTON 58 HOLDING COMPANY LLC	
2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was loading garbage into a truck when he slipped on snow and hurt his arm. The worker walked to urgent care.	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
2018	Manhattan	301	FREEDOM PLACE SOUTH	0	The Site Safety Coordinator reported that a worker was unloading glass from a crate when a piece of glass fell and injured his leg. The worker was taken to a hospital. The extent of the worker's injuries was not known.	No Dispatch			NEW BUILDING	121192501-01-NB	Worker Fell	301 FREEDOM PLACE SOUTH, LLC	SCIAME CONSTRUCTION LLC
/2018	Queens	22-44	JACKSON AVENUE	0	1 The Site Safety Manager reported that a worker on the twenty fourth floor slipped on a patch of ice and hurth is shoulder. An amoutance was called to the site. A DOS shoulder. An amoutance was called to the site. A DOS diamond plates on the outside of a hoist had water and ice on them, which caused the worker to slip. An ECB Violation and a DOB Violation were issued.	ECB Violation	35301051R	010818BS02DH03			Worker Fell	G & M REALTY, L.P.	
/2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that a worker slipped on a second floor concrete deck, landed on his back and hurt his shoulder. The worker slipped because of snow. The worker walked to a City MD. A DOB inspector wisted the site and confirmed that the deck was covere with snow, which caused the worker to fall. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	,	35301164N	010918BS02VP01			Worker Fell	40-56 TENTH OWNER LLC	
2018	Manhattan	400	WEST 33 STREET	0	1 The Site Safety Manager reported that a worker was handing down a screw-jack to another worker when the screw-jack slipped out of his hands and hit the other worker. The worker suffered a minor injury and went to hospital by ambulance for a cheek up. A DOB inspect hospital by ambulance for a cheek up. A DOB inspect hospital by ambulance for a cheek up. A DOB inspect of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of state of state of state of state stat		35301055Y	010918BS04DH03			Material Fell	BOP NE LLC	
0/2018	Staten Island	55	RICHMOND TERRACE	0	The Site Safety Manager reported that a worker slipped on ice. An ambulance was called. A DOB inspector reported that the worker slipped on ice that was located in an area that was closed off and where there was no work in progress. No enforcement action necessary.	No Action Necessary					Worker Fell	ST. GEORGE OUTLET DEV LLC	
0/2018	Queens	27-17	42 ROAD	0	The Side Safety Manager reported that a worker was installing sheet rock when he cut his left hand on a metal duct. The worker went to urgent care with another worker.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
0/2018	Manhattan	130	EAST 82 STREET	0	If The Site Safety Coordinator reported that an electrician was pulling cables in a box when he pulled his hand back and cut it on a piece of Chicago Bar. The incident occurred on 170/2018, but was not reported until 1/11/2018. The worker went to a doctor on his own.	No Dispatch			NEW BUILDING	121328027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
0/2018	Manhattan	118	FULTON STREET	0	1 A DOB inspector reported that a worker attempted to move an "A"-Frame cart that was loaded with about twenty flat stock metal sheets when the metal sheets fel onto his leg. The worker may have possibly suffered a broken leg. An EMT was on site. An ECB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Means and Methods for safe operations.		35300526R				Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	
1/2018	Manhattan	118	FULTON STREET	0	1 The Site Safety Manager and a DOB inspector reported that a carpenter was standing on an "A" Frame ladder to remove the door frame from an electrical closes the Stat Boor when a piece of plywood that was behind the door frame came loose and in thim in the shoulder, compained of back pain and was transported to a complained of back pain and was transported to a hospital by ambulance. A DOB inspector reported that there were no unsafe or hazardous conditions at the working area. No enforcement action was necessary.				New Building	121333440	Worker Fell	CP V TS FULTON OWNER, LLC	CP V TS FULTON OWNER LLC
1/2018	Manhattan	151	MAIDEN LANE	0	1 A DOB inspector reported that a worker was using an "A'-Frame cart to move scaffolding elements when he wisted his wist while pulling the cart. The worker did not want to go in an ambulance and went to see a doctor on his own. There were no unsafe of hazardous conditions at the work area. No enforcement action was necessary.	No Action Necessary			New Building	121186769	Other Construction Related Incidents	151 MAIDEN LLC	PIZZAROTTI IBC LLC



ncident Date	Borough	Address Number	Street	Fatalities Iniu	ries EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/11/2018	Manhattan	305	EAST 61 STREET	0	1 The Site Safety Manager reported that a worker tripped over a board that was on the floor and twisted his right ankle. An ambulance was called to the site and took the worker to a hospital.	No Dispatch					Worker Fell	305 EAST 61ST STREET GROUP LLC	
/11/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that a pedestrian stepped on a piece of plywood under the upper sidewall and slipped, injuring his right ankle. The pedestrian wen to see a doctor on his own. An ECB Violation was issued.	ECB Violation	35300326M	011118BS05MA03			Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	
11/2018	Queens	27-13	21 STREET	0	1 The Site Safety Manager reported that a carpenter was hitting a nail when the nail popped out and hit the worke in the face. The worker has no visible out or injuries. An ambulance transported the worker to a hospital for a check up.	No Dispatch			NEW BUILDING	420993740	Other Construction Related Incidents	NEWTOWN RESIDENCE LLC	DISANO DEMOLITION CO, INC
12/2018	Manhattan	45	PARK PLACE	0	1 The Site Safety Manager reported that a worker was pumping concrete into a wheebarrow when the concrete pump shifted and snagged his finger between the pump clamp and the concrete cleaning basin, causing a large cut. The worker was taken to a hospital. A DOB inspector proported that according to the inspection of the logs, the injured worker did not attend the concrete pre- pump meeting and did not know why he was part of the operations. An Aggravated 2 ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	9	35263168X	011218CERMR01	NEW BUILDING	121185635-01-NB	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
15/2018	Manhattan	590	EAST 83 STREET	0	The Site Safety Manager repoted that a worker was performing waterproofing work inside of a high concrete tank. When the worker was using a chemical seelant to waterproof the inside of the tank, he became overwhelmed by the fumes and passed out. The worker was taken to a hospital by an amulance. An ECB Violation, a DOB Violation, and a partial Stop Work Order were issued.	ECB Violation	35294740J	011518CERFC01	Alt 1 NB	121190987	Other Construction Related Incidents	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
15/2018	Manhattan	53	WEST 53 STREET	0	The Site Safety Manager reported that a worker pulled his groin while lifting a pipe. The worker went to a MedRite.	No Dispatch			alt 1 NB	121327224	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	LEND LEASE (US) CONSTRUCT
15/2018	Manhattan	130	EAST 82 STREET	0	The Site Safety Manager reported that a worker was cutting a piece of aluminum with a saw when the aluminum got caught in the saw and pierced his hand. The worker took a cab to a hospital.	No Dispatch			alt 1 NB	121325027	Other Construction Related Incidents	134 EAST 82 LLC	MC GOWAN BUILDERS INC
16/2018	Brooklyn	179	THROOP AVENUE	0		No Dispatch					Other Construction Related Incidents	NYC HHC	
17/2018	Manhattan	125	GREENWICH STREET	0	The Site Safety Manager reported that a piece of plywood fell onto a worker's hand during a stripping operation. There were two workers working one above the other, and the piece of plywood fell from above onto the worker below. An ambulance was called. An ECB Violation and a partial Stop Work Order were issued. The General Contractor at the site is to provide a Meant and Methods.	ECB Violation	35300553M				Other Construction Related Incidents	VS 125 LLC	
17/2018	Manhattan	42	WEST 33 STREET	0	1 The Site Safety Manager reported that an iron worker was using a grinder to cut a piece of metal bar when the grinder kicked back and caused a cut to the worker's thumb. The grinder had all of its safety jourds in place.  The worker went to an urgent care facility for treatment.	No Dispatch			NEW BUILDING	121186849	Mechanical Construction Equipment	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC
17/2018	Queens	22-44	JACKSON AVENUE	0	The Site Safety Manager reported that a worker was unpacking windows from a crate and was using a 2 X 4 piece of wood as a lever to move the crate when the piece of wood sa napped and hit him in the head, causing a scratch. An ambulance was called and the worker walked to the ambulance to go for a check up.				NEW BUILDING	420651912	Other Construction Related Incidents	G & M REALTY, LP.	G & M REALTY L.P
18/2018	Brooklyn	1601	KINGS HIGHWAY	0	2 A DOB inspector reported that a vehicle struck a manifi- with two workers in it that was parked in an occupied lane. The yockcles were not filled with water and a languer was not present. The manifit was not damaged and the worker was chook up by the incident. Both of the other worker was chook up by the incident. Both of the workers were sent to a hospital for a check-up. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35300560K				Other Construction Related Incidents	KINGSWAY REALTY LLC	
18/2018	Manhattan	200	AMSTERDAM AVENUE	0	The Site Safety Manager reported that a worker was unbooking the chair from an excavator that was filting oxygen tanks when his gloves of stack between the chain and the excavator's book, pinching the worker's lingst. The worker was taken to a bugslably by a worker was taken to a bugslably by a worker was taken to a bugslably by a worker was the worker was taken to be some the worker was the was directed by DB inspector to provide a Means and Methods to perform lifting operations.		3530559M 353055		NB	122887224	Mechanical Construction Equipment	AMSTERDAM AVENUE REDEVELOPMENT	Marc Depaul
18/2018	Manhattan	650	5 AVENUE	0	The Site Safety Manager reported that a flagger was almost struck by a vehicle in the middle of the street and that he twisted his right ankle while moving out of the way. The flagger went to a hospital.	No Dispatch					Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
19/2018	Manhattan	445	WEST 35 STREET	0	The Site Safety Manager reported that a worker was moving a wooden plank while taking down a single frame scaffold when he twisted his knee and	No Dispatch					Other Construction Related Incidents	CARE REALTY CORP.	



cident Date	Borough	Address Number	Street	Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
19/2018	Brooklyn	3003	WEST 21 STREET	0	The Site Safety Manager reported that a worker twisted						Other Construction Related Incidents	CONCERN SURF VETS PLACE HOUSIN	
					her ankle while pushing a mini-dumpster. An ambulance was called and took the worker to a hospital.								
					was called and took the worker to a nospital.								
018	Brooklyn	19	KENT AVENUE	0	1 The Site Safety Manager reported that a worker was	ECB Violation	3505625p, 26r, 27z, 28k, 29m		CRANE NOTICE	871 17	Mechanical Construction Equipment	19 KENT ACQUISITION LLC	ALL ISLAN MASONRY & CONCRETE
					setting up a mobile crane when his finger got pinched between the hook of the crane and a road barrier.								
					causing the finger to detach. A co-worker took him to a								
					hospital. Five ECB Violations and a partial Stop Work								
0040	Bronx	140	EAST 204 STREET		Order were issued.	N. Branch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
2018	Bronx	16	EAST 204 STREET	0	The Site Safety Manager reported that a worker slipped and burt his back at the job site. An ambulance was	No Dispatch					Worker Fell	HP VILLA GARDENS HDFC, INC.	
					called and took the worker to a hospital.								
2018			ANN STREET								Worker Fell	143 FULTON STREET DEVELOPMENT	
2018	Manhattan	26	ANN STREET	0	The Site Safety Manager reported that a worker hurt his hand while taping and spackling on the ninteenth floor.	No Dispatch					Worker Fell	143 FULTON STREET DEVELOPMENT	
					The worker went to urgent care.								
2018	Queens	29-22	NORTHERN BOULEVARD	0	A DOB inspector reported that a worker was pushing an     "A"-Frame cart that was loaded with stone when the cart	ECB Violation	35289063P				Material Fell	QSB NORTHERN LLC	
					overturned, causing stone to fall onto the worker's foot								
					and possibly breaking the foot. An EMT was on site. An								
					ECB Violation and a partial Stop Work order were issued. The General Contractor is to provide a Means								
					and Methods and a Tool Box Talk.								
2018	Brooklyn	109	2 AVENUE	0	1 The Construction Superintendent reported that a worker cut his finger while cutting a piece of rebar. EMS was	No Dispatch			ALTERATION TYPE 1	321185953-01-AL	Worker Fell	THE SALVATION ARMY	SD BUILDERS AND CONSTRUCT
					called. The worker was found conscious and was taken								
					to an area hospital.								
2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker was doing form work with while he had his peligan hook	No Dispatch					Other Construction Related Incidents	NYC HPD	
					attached to himself. When the worker was climbing								
					down a ladder, the peligan hook fell and hit his right ear.								
					The worker went to a City MD. An ambulance was not called. This incident was the result of a worker error.								
					motorit was the result of a worker entit.								
2018	Manhattan	111	EAST 24 STREET	1	0 A DOB inspecor reported that an elevator foreman was	DOB Violation		012318BS0501BG	NB	121192798	Worker Fell	DEMETRIOS & FANIA SAMUEL, LLC	TRINITY BUILDERS INC
					working on a platform for installing an elevator inside the								
					elevator shaft at the sixth floor when the platform started drifting upwards uncontrollably and would not stop. The								
					worker tried to jump to the machine room on the other								
					platform at the ninth floor, but he fell backwards down the shaft to the cellar floor, where he succumbed to his								
					injuries. The elevator foreman did not have a safety								
					harness on and was not tied to anything. There were no								
					safety lines found at the site. A DOB Violation and a full Stop Work Order were issued.								
					otop Work Order Water Issued.								
/2018	Queens	62-98	SAUNDERS STREET	1	0 The New York City Police Department reported that a	ECB Violation	35308671J, 35308670H	012318CERTQ01, 02			Worker Fell	NOT ON FILE	
					worker was standing on a window sill of a sixth floor			·					
					apartment when he fell from the sixth floor to the ground. The worker was transported to North Shore University.								
					The worker was transported to North Shore University Hospital, but was found dead on arrival by the NYPD. A								
					DOB inspector inspected the site and reported that there was work present that consisted of a gut renovation to	'							
					the bathroom, the installation of new electrical wiring								
					and box, and the installation of new sheetrock, without a permit. Two ECB Violations, two DOB Violations, and a								
					Stop Work Order were issued.								
/2018	Staten Island	546	GULF AVENUE	0	1 The Site Safety Manager reported that a worker got	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
					concrete in his eyes during a concrete pour operation. The worker went to a hospital and returned to work.								
					nonce work to a nospital and returned to WORK.								
/2018	Manhattan	280	PARK AVENUE	0	1 The Construction Superintendent reported that an	ECB Violation	35312686Y	012918EE105FM1			Other Construction Related Incidents	BROADWAY 280 PARK FEE LLC	
					electrician was working on a live splice box when he was shocked and got two of his fingers burned. The								
					worker went to a hospital. This incident took place on								
					January 24, 2018, but the Department Of Buildings was								
					not notified until January 29, 2018. An ECB Violation was issued for electrical work being performed without a								
					permit. A DOB Violation was also issued.								
/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reports that a flagger was	No Dispatch					Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	
					directing traffic when he was side-swiped by a vehicle. The driver did not want to listen to the flagger. The								
					flagger was okay, but was taken to a hospital by an								
					ambulance for a checkup.								
2018	Manhattan	2	PARK PLACE	0	1 The Site Safety Manager reported that a worker was	No Dispatch			ALTERATION TYPE 1	121333413-01-AL	Worker Fell	NOT ON FILE	CNY CONSTRUCTION LLC
					cutting rebar when he slipped and cut his finger. The worker drove himself to a first med for precaution.								
2018	Manhattan	102	West 188 Street	0	1 A DOB inspector reported that a worker was climbing up	ECB Violation	35310351n		ALT	122917503	Worker Fell		allba services
					an "A"-Frame ladder from the first floor to the second floor when a rung on the ladder snapped, causing the								
					worker to fall ten feet and land on his back. The worker								
					was found conscious and was taken to the hospital by								
					EMT personnel. An ECB Violation and a full Stop Work Order were issued. The site will received a full audit due								
					to site conditions.								
			UNION SQUARE	0	1 The Site Safety Manager reported that a worker at a	No Dispatch					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
2018	Manhattan	44	DIVION SQUARE	0							Olifor Conditaction (Colated molderite		
018	Manhattan	44	UNION SQUARE		concrete truck had a miscommunication with the driver						Outer Constitution (Control		
/2018	Manhattan	44	UNION SQUARE		concrete truck had a miscommunication with the driver and the shoot came down and hit the worker on the hand. The worker suffered a minor injury and an ambulance was called.						Carlo Company (Carlo Moderno		



26/2018	Borough	Address Number		Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Manhattan	450	WEST 33 STREET	0	A DOB inspector reported that during a demolition operation on the first floor of the HVAC conduits and	ECB Violation	35310356M		Alteration 2	140188767	Material Fell	450 PARTNERS LLC	Tishman Construction Corp
					utilities lines, a construction worker was cleaning								
					demolition debris on the first floor when a pipe section								
					fell approximately four feet and hit the worker in the head. The pipe section fell because another worker cut								
					a strap pipe that was holding the pipe section. The								
					worker who was hit by the pipe section initially refused medical attention, but wasn't feeling well after a few								
					medical attention, but wasn't feeling well after a few hours and called EMS. The worker was taken to a								
					hospital by ambulance. A Construction Superintendent								
					hospital by ambulance. A Construction Superintendent was not required at the site. An ECB Violation and a full								
					Stop Work Order were issued. The General Contractor								
					must provide a Means and Methods for the demolition of the remaining HVAC conduits.								
					are remaining TVAC conduits.								
2018	Manhattan	500	WEST 33 STREET	0	1 A DOB inspector reported that an electrician was in the process of erecting a shanty while climbing an eight foot	No Action Necessary			NEW BUILDING	121186251-01-NB	Worker Fell	NOT ON FILE	TISHMAN CONSTRUCTION CORF
					ladder when he missed a rung of the ladder and fell								
					three feet. The worker was taken to Bellevue Hospital. A								
					DOB inspector visited the site and reported that no enforcement action was deemed necessary.								
					chiorectricit determined recessary.								
/2018	Brooklyn	404	11 STREET	0	1 A DOB inspector reported that workers were receiving a	ECB Violation	35310458N		Alteration	321190858	Other Construction Related Incidents	404 11TH ST NY CORP	SUN SUN Contracting
					load of concrete masonry unit (CMU) brick on the third								
					floor when the third floor C-Joists towads the rear of a								
					new extension partially collapse due to excessive weight and because the C-Joists were not properly secured to								
					the CMU wals. The collapse also caused the second								
					and first floors to collapse into the cellar. One worker								
					sustained minor injuries and was taken to Brooklyn Presbyterian Hospital, An Aggravated Level 2 FCB								
					Violation and a full Stop Work Order were issued for a								
					failure to safeguard. A sidewalk shed has been								
					requested to be immediately installed at exposure four. DOB will remain on site until the sidewalk shed is								
					installed. The site will be referring to DOB's Interior								
					Demolition Engineering Unit for audit and approval of all								
					temprary shoring.								
2018	Brooklyn	422	FULTON STREET	0	1 The Site Safety Manager reported that a worker fell	No Action Necessary					Worker Fell	NOT ON FILE	
					through the interior opening for a tower crane installation from the ninth floor to the eighth floor. The worker was	1							
					taken to a hospital, where he was eventually released								
					with no injuries. The worker did attend a safety								
					orientation meeting at the start of his shift. A DOB inspector visited the site and reported that there was								
					proper signage and a proper guardrail system present at								
					the perimeter of the slab opening, but that the worker								
					disregarded all safety measures provided to prevent								
					falling hazards. No enforcement action was necessary.								
/2018	Manhattan				1 The Site Safety Manager reported that a worker was	No Dispatch			ALTERATION TYPE 1	121724946-01-AL	Worker Fell	227 EAST 19TH STREET OWNER, LL	GRAMERCY SQUARE LLC
		209	EAST 19 STREET	0	uning a grinder to cut an angle when the grinder immed								
		209	EAST 19 STREET	0	using a grinder to cut an angle when the grinder jumped								
		209	EAST 19 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on								
				0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.								
/2018	Manhattan	500	WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
/2018	Manhattan			0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
)/2018 )/2018	Manhattan Manhattan			0	using a grinder to cut an angle when the grinder jumped and cut his fight leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurt his arm. An ambulance was called.		35299847M				Other Construction Related Incidents  Material Fell	NOT ON FILE  NY STOCK EXCHANGE BLDG, CO.	
			WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was bushing a debits cant when one of the wheels of the cart	ECB Violation	35299847M						
			WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut bl for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart procke off and clicosed the worker's foot. The worker was procked that of the control of the wheels of the cart.	ECB Violation	3529847M						
			WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut bl for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart procke off and clicosed the worker's foot. The worker was procked that of the control of the wheels of the cart.	ECB Violation	35299847M						
			WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the curb for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was bushing a debits cant when one of the wheels of the cart	ECB Violation	35299847M						
/2018			WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debtos cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Manhattan	\$00 20	WEST 33 STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut hot for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ESS Vollation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third was installing form work at the second floor for a third was installing form work at the second floor for a third	ECB Violation	35299847M						
	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut bf or the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker was troke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was costioned below the	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a ginder to cut an angle when the ginder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cown.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker fout. The worker want to the emergency room. An ECB Violation and a partial Slept Work Corter were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was	ECB Violation	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut bf or the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for at third floor column. One worker was positioned below the second worker, holding him in place while he was installing cham. While securing the clamp, the clamp installing a loan. While securing the clamp, the clamp installing a loan. While securing the clamp, the clamp installing a loan. While securing the clamp, the clamp installing a loan. While securing the clamp, the clamp installing a loan. While securing the clamp, the clamp	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut bit for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart proke off and clipped the worker's foot. The worker want to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third was installing form work at the second floor for a third was installing form work at the second floor for a third was installing form work at the second floor for a third was installing form work at the second floor for a third was installing form work at the second floor for a third was installing a claring. While security the clamp, the clamp fell and hit the below worker in the face. The worker was taken to a hospically where it was recorted that the	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuto for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker 5 foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker we second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second by the property of the	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumpe and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Salety Manager reported that a worker tripped on the cuth for the machine room and hurth his arm. An ambulance was called.  1 The Site Salety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work forder were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While security the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was held overnight for observation. No enforcement action was deemed necessary, as this	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuto for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker 5 foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker we second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second by the property of the	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0	using a grinder to cut an angle when the grinder jumpe and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Salety Manager reported that a worker tripped on the cuth for the machine room and hurth his arm. An ambulance was called.  1 The Site Salety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work forder were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While security the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was held overnight for observation. No enforcement action was deemed necessary, as this	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
/2018	Menhattan  Brooklyn	500	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET	0	using a ginder to cut an angle when the ginder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECS Violation and a partial Step Work Offorer were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third second worker. I have the second floor for a third second worker, holding him in place while he was installing a clamp. While securing the clamp, the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.	ECB Violation  No Action Necessary	35299847M				Material Fell  Material Fell	NY STOCK EXCHANGE BLDG. CO.  NYC HPD	
2018	Manhattan	\$00 20	WEST 33 STREET BROAD STREET	0 0	using a ginder to cut an angle when the ginder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECS Violation and a partial Stopt Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third second worker. I have the second floor for a third second worker holding him in place while he was installing a clamp. While securing the clamp, the clamp left and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, loss his	ECB Violation  No Action Necessary	35299847M				Material Fell	NY STOCK EXCHANGE BLDG. CO.	
2018	Menhattan  Brooklyn	500	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET	0 0	using a grinder to cut an angle when the grinder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cutof for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work forder were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a long. While security the clamp fell and hit the below worker in the face. The worker was taken to a hospitally where it was reported that the worker suffered a scratch, but not a concussion. The worker was feld overnight for observation. No enforcement action was deemed necessary, as this righty occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker was balance, and fell on his rear. The worker was balance, and fell on his rear. The worker was balance, and fell on his rear. The worker was held on his rear. The worker was held on his rear. The worker was held on his rear. The worker was deed to a worker was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker was held on his rear. The worker was held on his rear. The worker wasked to a	ECB Violation  No Action Necessary	3529847M				Material Fell  Material Fell	NY STOCK EXCHANGE BLDG. CO.  NYC HPD	
2018	Manhattan  Brooklyn  Manhattan	500 20 138	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE	0	using a ginder to cut an angle when the ginder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cwn.  1 The Sies Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Sies Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECS Violation and a partial Step Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third second worker worker was been seen to be seen	ECB Violation  No Action Necessary  No Dispatch	35298847M				Material Fell  Material Fell  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN	
/2018	Menhattan  Brooklyn	500	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET	0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work forder were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While security the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was tead or verying the clamp. The clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was tead to everight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, jost his balance, and fell on his rear. The worker was the balance, and fell on his rear. The worker hurt his	ECB Violation  No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell	NY STOCK EXCHANGE BLDG. CO.  NYC HPD	
/2018	Manhattan  Brooklyn  Manhattan	500 20 138	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE	0	using a ginder to cut an angle when the ginder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cwn.  1 The Sies Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Sies Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECS Violation and a partial Step Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third second worker worker was been seen to be seen	ECB Violation  No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN	
/2018	Manhattan  Brooklyn  Manhattan	500 20 138	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE	0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cown.  1 The Site Safety Manager reported that a worker tripped on the cutof for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke of and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the installing a clamp. While securing the clamp, the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was tended a scratch, but not a concussion. The worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, loss this balance, and fell on his rear. The worker wasked to a City MD for a check up.  1 The Site Safety Manager reported that a worker was no clipt MD for a check up.  1 The Site Safety Manager reported that a worker was no for the check up.	ECB Violation  No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN	
2018	Manhattan  Brooklyn  Manhattan	500 20 138	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE	0 0 0	using a grinder to cut an angle when the grinder jumpa and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work forder were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a long. While security the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was the of the overlight for observation. No worker was provided that the worker was the overlight for observation. No worker was provided that the worker was the overlight for observation. No included with the worker was the overlight for observation. No included with the worker was the overlight for observation. No included with the worker was the owner was on a ladder when he tripped on the fourth step, lost his balance, and fell on his rear. The worker warked to a City MD on a check up.  1 The Site Safety Manager reported that a worker hall be unloading pipes from a delivery truck. The worker walked to a city MD on its own.	No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN	
2018	Manhattan  Brooklyn  Manhattan  Manhattan	500 20 139 1283	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0	using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker were second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second worker, holding him in place while he was second and the worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was not a ladder when he tripped on the fourth step, lost his balainea, and fell on his rear. The worker walked to a City MD on check up.  1 The Site Safety Manager reported that a worker hust his finger while unioading pipes from a delivery truck. The worker went to a City MD on his own.	No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL	
2018	Manhattan  Brooklyn  Manhattan  Manhattan	500 20 139 1283	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0	using a grinder to cut an angle when the grinder jumps al and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a lome. While security the clamp flet and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker was taken to a hospital, where it was reported that the worker was taken to a hospital, where it was reported that the worker was telled overnight for observation. No enforcement action was deemed necessary, as this nignary occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, jost his balance, and fell on his rear. The worker was the balance, and fell on his rear. The worker while unloading pipes from a delivery truck. The worker while unloading pipes from a delivery truck. The worker while unloading pipes from a delivery truck. The worker while unloading pipes from a delivery truck. The worker while unloading pipes from a delivery truck. The permanent flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his foot. An experiment flight of stairs and hur his f	No Action Necessary  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL	
2018 2018 2018 2018 2018	Manhattan  Brooklyn  Manhattan  Manhattan  Manhattan	500 20 138 1283 209	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET		using a grinder to cut an angle when the grinder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cown.  1 The Site Safety Manager reported that a worker tripped on the cut for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker want to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the line of the worker was the second floor for a third floor column. One worker was positioned below the line of the worker was the column of the worker was the column of the worker was taken to a hospital, where it was reported that the worker was taken to a hospital, where it was reported that the worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, took his balance, and fell on his rear. The worker walked to a City MD on check up.  1 The Site Safety Manager reported that a worker was not a ladder when he tripped on the fourth step, took his balance, and fell on his rear. The worker walked to a City MD on his own.	No Action Necessary  No Dispatch  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL  NOT ON FILE	
2018 2018 2018 2018	Manhattan  Brooklyn  Manhattan  Manhattan	500 20 139 1283	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	using a grinder to cut an angle when the grinder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurth his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While security the clamp flet and hit the below worker in the face. The worker was taken to a hospitall, where it was reported that the worker was taken to a hospitall, where it was reported that the worker was taken to a hospitall, where it was reported that the worker was teld or verified for observation. No enforcement action was deemed necessary, as this nigney occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, jost his balance, and fell on his rear. The worker was the balance, and fell on his rear. The worker was the balance, and fell on his rear. The worker was the balance, and fell on his rear. The worker was the worker while unloading pipes from a delivery truck. The worker while or a city MD on his own.  1 The Construction Superintendent reported that a third party inspector missed the last step on his way down a permanent flight of statis and hurth his foot. An ambulance was called.	No Action Necessary  No Dispatch  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL	
2018 22018 22018	Manhattan  Brooklyn  Manhattan  Manhattan  Manhattan	500 20 138 1283 209	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	using a ginder to cut an angle when the ginder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cwn.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurt his arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and dispect the worker foot. The worker was pushing a debris cart when one of the wheels of the cart broke off and dispect the worker foot. The worker was possitioned to the worker was possitioned to the worker was stopped from work at the second floor for a high thin the was installing form work at the second floor for a high thin floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While securing the clamp, the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No unique to the proper of the fourth step, lost his balance, and full on his rear. The worker waked to a lost yellow of the fourth step, lost his balance, and full on his rear. The worker waked to a City MD for a check up.  1 The Site Safety Manager reported that a worker hurth his finger while unbedding piese from a delivery truck. The worker went to a City MD on his own amount of the order was called.  1 The Site Safety Manager reported that a worker slipped on melt pellets that were on the ground floor of the one beginned melting that does not not be premarent flight of stairs and hurth his foot. An ambulance was called.	No Action Necessary  No Dispatch  No Dispatch	35298847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL  NOT ON FILE	
2018	Manhattan  Brooklyn  Manhattan  Manhattan  Manhattan	500 20 138 1283 209	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	using a grinder to cut an angle when the grinder jumps and and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his own.  1 The Site Safety Manager reported that a worker tripped on the cuto for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and clipped the worker's foot. The worker went to the emergency room. An ECB Violation and a partial Stop Work Order were issued.  1 A DOB inspector reported that a team of two workers was installing form work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While security the clamp, the clamp installing a clamp. While security the clamp, the clamp worker was held overnight for observation. No enforcement action was deemed necessary, as this injury occurred due to a worker error.  1 The Site Safety Manager reported that a worker was on a ladder when he tripped on the fourth step, jost his balance, and fell on his ear. The worker walked to a Chy Mo on a chee, Jose from the worker while unloading plees from a delivery truck. The worker walked to a Chy Mo on a chee, Jose from the worker was considered and the second that a worker while unloading plees from a delivery truck. The worker walked to a Chy Mo on the worker was the worker was considered an idea of the second was called.  1 The Site Safety Manager reported that a worker hurt his finger while unloading plees from a delivery truck. The worker was considered and the last the worker was considered on its early Manager reported that a worker hurt his wire and his his. Dr. he ometically such worker hurt his worker hurt his wire and his his. Dr. he ometically such as the second floor of the construction such as the second floor of the construction and the second floor of the construction and the second floor of the construction and the sec	No Action Necessary  No Dispatch  No Dispatch  No Dispatch	35299847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL  NOT ON FILE	
D18 D18 D18 D18	Manhattan  Brooklyn  Manhattan  Manhattan  Manhattan	500 20 138 1283 209	WEST 33 STREET  BROAD STREET  WILLOUGHBY STREET  YORK AVENUE  EAST 19 STREET	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	using a ginder to cut an angle when the ginder jumped and cut his right leg above the knee. The cut was a minor cut. The worker walked to Beth Israel Hospital on his cwn.  1 The Site Safety Manager reported that a worker tripped on the cuth for the machine room and hurth is arm. An ambulance was called.  1 The Site Safety Manager reported that a worker was pushing a debris cart when one of the wheels of the cart broke off and dispect the worker foot. The worker was pushing a debris cart when one of the wheels of the cart broke off and dispect the worker foot. The worker was possitioned to the worker was possitioned to the worker was stopped from work at the second floor for a third floor column. One worker was positioned below the second worker, holding him in place while he was installing a clamp. While securing the clamp, the clamp fell and hit the below worker in the face. The worker was taken to a hospital, where it was reported that the worker suffered a scratch, but not a concussion. The worker was held overnight for observation. No unique to the control of the co	No Action Necessary  No Dispatch  No Dispatch  No Dispatch	35298847M				Material Fell  Material Fell  Other Construction Related Incidents  Other Construction Related Incidents  Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.  NYC HPD  THE NEW YORK AND PRESBYTERIAN  227 EAST 19TH STREET OWNER, LL  NOT ON FILE	



31/2018	Borough Manhattan	Address Number	r Street WEST 29 STREET	Fatalities Injuries	s EOC Final Description	DOB Action No Dispatch	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name 550 WEST 29TH STREET LLC	Contractor Name
31/2018	Mannattan	550	WEST 29 STREET	0	1 The Site Safety Manager reported that a worker was using a grinder when the blade caught his glove and caused a cut to his hand. An ambulance was called.	No Dispatch					Other Construction Related Incidents	550 WEST 29TH STREET LLC	
2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker cut his pinky finger while putting away his band-saw tool. The band-saw was unplugged. The worker went to a clinic. An ambulance was not called	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
2018	Manhattan	328	EAST 62 STREET	0	1 The Construction Superintendent reported that a worker was installing pour stops when he slipped into the side of rebar and injured his shoulder. The worker left the site in a cab.				Alt 1 - NB	121189846	Other Construction Related Incidents	YYY 62ND STREET LLC	JOY CONSTRUCTION CORP
2018	Manhattan	501	THIRD AVENUE	0	The Site Safety Manager reported that a painter was	No Dispatch					Other Construction Related Incidents	587-91 THIRD OWNER LLC	
.010			TIME WEIGE		carrying down supplies when he lost hs balance on the fourth step and fell, hurting his leg. An ambulance was called and the ambulance took the worker to a hospital.	The Bispaton					Siles Contained including	SO OT THING OTHER LEG	
018	Brooklyn	1	FLATBUSH	0	The Site Safety Manager reported that a worker was removing debris when a four inch pipe that was about three feet long fell on his foot. The worker went to a hospital.	No Dispatch					Other Construction Related Incidents		
2018	Bronx	869	EAST 147 STREET	0	The Site Safety Manager reported that a worker	No Dispatch					Other Construction Related Incidents	HP MLK PLAZA HOUSING DEVELOPME	
					complained about lower back pain while pulling a stud during carpentry work. The worker went to urgent care. An ambulance was not called.								
2018	Brooklyn	1	FLATBUSH AVENUE	0	1 The Site Safety Manager reported that a worker was doing taping work while on an 'A'-Frame ladder when he mis-stepped and fell two feet. The worker suffered a minor injury and an ambulance was called.	No Dispatch					Other Construction Related Incidents	ONE FLATBUSH AVENUE PROPERTY L	
2018	Brooklyn	37	BLUE SLIP	0	The Site Safety Manager reported that a worker got his thumb pinched between a window and a rack during a delivery. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT G LLC	
2018	Manhattan	10	RIVERSIDE BOULEVARD	0	The Site Safety Manager reported that a worker hurt his back while lifting a reel of wire into a box. An ambulance was called.	No Dispatch					Other Construction Related Incidents	RCB3 NOMINEE LLC	
/2018	Manhattan	24	2 AVENUE	0	1 The Site Safety Manager reported that a worker was putting away his tools at the end of the day when he opened a sliding glass door came off of its track and hit the worker. The incident took place on 2/5/2018, but was not reported until 2/6/2018. An ambulance was not called, but the worker said that he was going to see a doctor to be checked out. An EGB Violation and a DOB Violation were issued. A partial Stop Work Order on the use and installation of all backory sliding doors was issued. The General Contractor is to provide a Manufacturer's Specification on all door tracks and the reason for the door falling off its track.	ECB Violation	35299721R	020618BS03GD02			Material Fell	24 SECOND AVENUE OWNER LLC	
018	Manhattan	260	WEST 40 STREET	0	A DOB inspector reported that a worker was trying to leach for something on the platform of a baker scaffold when he moved the baker scaffold, causing it to strike the left shoulder of another worker. Both workers were on the floor and not using the scaffold. The injured worker was sent to a Med-Rite Clinic for a check up. The injured worker did not suffer a major injury. An ECB Violation was issued.		35285826Y		NB	121187394	Material Fell	PORT 40TH PARKING CORP	ZDG LLC
2018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that an electrician from Local 3 slipped in an isolated area by a Con-Edison box. The worker went to Staten Island Hospital on his own for a check up.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Manhattan	91	LEONARD STREET	0	The Site Safety Manager reported that a worker tripped, fell, and cut his hand. EMS was called. The worker was conscious and was taken to an area hospital.	No Dispatch			NEW BUILDING	121190166-01-NB	Worker Fell	353-357 BROADWAY LLC	TOLL GC LLC
018	Manhattan	91	LEONARD STREET	0	A worker tripped on a small piece of pipe in the mechanical room and cut his pinky finger. The worker went of a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	353-357 BROADWAY LLC	
2018	Manhattan	2395	FREDERICK DOUGLAS BOULEVARD	0	A DDB raspector reported that a worker was his in the head with a piece of timber that was dropped by another worker during a stripping operation. The worker who was hit by the piece of timber complained of a stiff neck and was sent to a hospital. An ECB Violation was issued, as well as a partial Stoy Work Order on all concrete work. A Means and Methods must be provided.	ECB Violation	35289390M				Other Construction Related Incidents	HP 2395 FDB HOUSING DEVELOPMEN	
2018	Manhattan	1283	YORK AVENUE	0	The Site Safety Manager reported that a worker was moving an 'A'-Frame dolly that was loaded with twenty sheets of 4 X 6 atmand plates when the dolly typed and hit her ankle. The injured worker went to an emergency room that was across the street from the site. An EGB Violation and a partial Stop Work Order were issued.		35299967R				Other Construction Related Incidents	THE NEW YORK AND PRESBYTERIAN	
2018	Brooklyn	911	ERSKINE STREET	0	1 The Sine Safety Manager reported that a worker was cutting the remainder of wood piles that were approximately four feet. While cutting one of the piles, the pile fell forward and hit him in the head. The worker went to a hospital by ambulance. This incident occurred no 2/6/2016, but was not reported until 2/6/2018. An ECB Violation was issued for a failure to notify the Department Of Buildings of the incident, as well as a partial Stop Work Order for the cutting of all wood piles. A Means and Methods for safe cutting operations with a tool box talk will be provided.	ECB Violation	35300547X,49.J	020818BS05HM01,02			Material Fell	FOUNTAIN SEAVIEW THREE HOUSING	



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/2018	Brooklyn	540	FULTON STREET		The Sie Safety Manager reported that during a drilling operation for the backs, a carpenter that was assisting the drill operator stepped onto an equipment insert and the clamp closed down on his left for. The worker was taken to a hospital by emergency personnel. Two ECB Violation, were issued, as well as a full Slop Work Order. The contractor has been directed to provide the manufacturer's specifications for the drilling equipment, as well as the required training for the personnel operation the equipment.		35309900Z 35309901K		NB	321185828	Mechanical Construction Equipment	540 FULTON ASSOCIATES	PAV-LAK CONTTRACTING INC
7/2018	Manhattan	460	PARK AVENUE SOUTH	0	The Site Safety Manager reported that a worker was opening a crate of window frames when a 5' X 5' tube pipe rolled out and onto his foot. The worker was seen walking around, but an ambulance was called.	No Dispatch					Other Construction Related Incidents	460 PARK AVENUE SOUTH ASSOCIAT	
/2018	Queens	27-17	42 ROAD	0	The Site Safety Manager reported that a worker lacerated his hand with a utility knife during a stripping operation when the utility knife slipped. The worker went to a hospital on his own.	No Dispatch					Other Construction Related Incidents	EASTERN STAR DEVELOPMENT LLC	
B/2018	Brooklyn	810	FULTON STREET	0	1 The Site Safety Manager reported that a worker was performing stipping work on the eleventh floor when pulled down a piece of plywood and the aluminum leg of the formwork hit the worker in the face and split his lip. An ambulance was called. An ECB Violation was issued for a fallure to provide safety measures. A DOB Violation was also issued. AT old EXT Talk will be issued before the start of stripping operations.		35300050K	020818BS02EP06			Material Fell	GREENPOINT-GOLDMAN CORP.	
/2018	Manhattan	388	GREENWICH STREET	0	The Site Safety reported that a worker hurt his foot while using a chipping gun. The worker took a cab to urgent	No Dispatch			ALTERATION TYPE 1	121190503-01-AL	Other Construction Related Incidents	CITIGROUP TECHNOLOGY, INC.	TISHMAN CONSTRUCTION CORP
8/2018	Queens	34-11	BEACH CHANNEL DRIVE	0	care.  The Site Safety Manager reported that a worker was dismandling a scaffold when the plank he was standing on broke and fell six feet. The worker went to a hospital by ambulance. An ECB Violation for a failure to safeguard all persons and property affected by construction operations was issued.	ECB Violation	35285811N		NB	421094283	Worker Fell	NOT ON FILE	Chateau GC LLC
/2018	Queens	160-08	JAMAICA AVENUE	0	The Site Safety Manger reported that a vehicle struck the flagman in the street. The Police Department responded to the incident. The worker was taken to Jamaica Hosoital.	No Dispatch					Other Construction Related Incidents	160 JAMAICA, LLC	
2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that an electrician was pulling his cart from the hoist when the handle on the cart became loose and the worker fell backwards to the floor, hurting his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
/2018	Brooklyn	500	GATES AVENUE	0	The Super reported that a mason was using a grinder for brick cutting when the grinder kicked back and the grinder's butt end (not the blade) hit the mason in the face. The mason suffered a bruise to his face and felt a little dizzy. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PCMH 500 GATES HOUSING DEVELOP	
2018	Brooklyn	340	EVERGREEN AVENUE	0	1 The Fire Department reported that a worker was hit in the head with a piece of rebar. Four ECB Violations and four DOB Violations were issued. A partial Stop Work Order was also issued. A Means and Methods and a Tool Box Talk must be provided.	ECB Violation	35300117X,118H,120R,121Z	020918BS04DH01,02,04,05			Material Fell	BUSHWICK REALTY HOLDINGS LLC	
2/2018	Bronx	2568	PARK AVENUE	0	The Site Safety Manager reported that a worker cut his knee while walking by rebar. The worker was taken to an area medical facility by a co-worker.	No Dispatch				220152484	Other Construction Related Incidents	2568 BRONX PARK LLC	STEVEN ALESSIO
12/2018	Brooklyn	135	EMERSON PLACE	0	The Site Safety Manager reported that during a stripping operation, a worker fell down from the sixth floor and landed on top of the sidewalk shed. The worker was found unconscious, but breathing. The worker was connected to the stripping from. The worker was taken to a hospital by ambulance. An ECB Violation and a full Stop Work Order were issued. Three additional ECB Violations/OATH Summonses and three partial Stop Work Orders were issued of the summon the stripping from the summon that		35300065N				Worker Fell	PRATT INSTITUTE	
12/2018	Manhattan	11	WEST 53 STREET	0	The Site Safety Manager reported that a worker was working in a man lift when he moved his body and twisted his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	THE MUSEUM OF MODERN ART	
2/2018	Manhattan	200	EAST 95 STREET	0	The Site Safety Manager reported that a worker pinched his finger while moving a steel beam on an "A"-Frame. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents		
2/2018	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker cut his left hand on metal studs. The worker was taken to an area hospital and received several stitches.	No Dispatch			ALT 1	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	EDWARD M GRUNWALD
13/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker entered the site from the outside of the mail area by the dirt parking area side, fell in ice that was mixed with dirt, and hurt his ankle. The worker went to urgent care.						Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	



											h=		
Incident Date 2/13/2018	Queens	Address Number 80-08	135 STREET		EOC Final Description  The General Contractor reported that two workers were	DOB Action ECB Violation	ECB Violation Numbers 35309854r	DOB Violation Numbers	Permit ALT 1	Permit No 420652378 AL	Incident Type Mechanical Construction Equipment	Owner's Name BRIARWOOD MP LLC	Contractor Name PAV-LAK CONTRACTING INC
					injured while grouting when a pump hose got clogged with grout and blew into the worker's faces. The worker tried to un-clog the pump while it was in use. The two workers were taken to a hosoital for treatment. An ECB								
					Violation and a partial Stop Work Order were issued.								
/13/2018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a worker was using the scaffold's stairs to bring rebase not a floor when a reba got caught on the stairs and pulled the same worker down. The worker was experiencing aches in his body and went to a clinic the next day. This incident took place on February 13, 2018. The building was a five story building with no permanent stairs. An ECB Violation and a full Stop Worker Order were issued for inadequate ingress-legress, an adequate supported scaffold, and theack of internal stairs.	9	3529630L				Worker Fell	DEPARTMENT OF EDUCATION	
15/2018	Brooklyn	1060	CLARKSON AVENUE	0	The Site Safety Manager reported that a worker cut his arm with a saw while cutting wood. The worker was taken to a hospital by ambulance.	No Dispatch			ALTERATION TYPE 2	302581347-01-EW-OT	Worker Fell	DEPARTMENT OF EDUCATION	ANSU CONSTRUCTION INC
2/15/2018	Manhattan	101	WEST 57 STREET	0	taxen to a nospiral by amousance.  I A DOB inspector reported that contractors were attempting to remove a tempered glass spanel when the panel shattered. A small piece of glass fell to the street level while the remainder of the shattered panel was on the terrace. A woman was injured and taken to a hospital by ambulance. The women's injury was minor and not life threatening. An aggravated Level 2 EGO Violation, a DOB Violation, and a partial Stop Work Order were issued for a failure to safeguard all persons and property during construction operations.	ECB Violation	35308906P	021518CERDY04			Material Fell	101 WEST 57TH STREET HOTEL INV	
/15/2018	Manhattan	42	WEST 33 STREET	0	The Site Safety Manager reported that a worker was climbing off of a scaffold when he slipped and fell approximately two feet, injuring his shoulder. An ambulance was called	No Dispatch					Worker Fell	38-46 WEST 33 STREET, LLC	
2/15/2018	Queens	30-35	COLLEGE POINT BOULEVARD	0	amousince was cause.  I A DOB inspector reported that a painter was on a scissor lift painting the area next to a roll down door sensor when he activated the door, which caused another worker to get hit by the door. The worker had the wind knocked out of him and was sent to a hospital. An ECB Violation and a partial Stop Work Order were issued for the failure to maintain safe operations. The General Contractor at the site is to provide a Means and Methods.	ECB Violation	35317705N				Other Construction Related Incidents	FEINSTEIN CP REALTY LLC	
/16/2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a concrete worker was carrying a Doka form that was about 2 X 9 feet and 100 pounds when he slipped and fell. The worker complained or back pain. A DOB inspector responded to the incident and reported that no enforcement action was necessary, as the injury cocurred as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	SMITELL SPONSOR LLC	
2/16/2018	Manhattan	233	WEST 125 STREET	0	The Site Safety Manager reported that a worker was lifting a piece of rebar when he claimed to have hurt his back. The worker walked up to an ambulance and the ambulance took him to a hospital.	No Dispatch			NEW BUILDING	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTRUCTION SERVICES L
2/16/2018	Manhattan	38	HOWARD STREET	0	2 A DOB inspector reported that an inspector from Cole NY was performing an inspection of the building for flaqade local law. While inspecting the building, the inspector stepped out onto the fire escape became distologed and fell to the ground, striking two pedestrians. One of the pedestrians suffered a life threatening injury, and the second pedestrian was in serious condition. The inspector fell sightly through an opening, but not all the way down. EMS was called. An ECB Violation, a ODB Violation, and an Immediate Emergency Declaration were issued.	ECB Violation	35308908Z	021618CERDY01			Material Fell	434 BROADWAY PROPERTY INVESTOR	CANY Architecture & Engineering, DPC.
2/16/2018	Queens	71-17	ROOSEVELT AVENUE	0	A DOB inspector reported that were four workers unloading bundles of rebar that were approximately forn five feet from a flathed ruck when one of the workers from the first of the first owners. It is not that the following the first owners are common to the first owners and the first owners are common to the first owners are for the first owners. The first owners suffered a booken right leg and was taken to a hospital. An EGB Violation and a partial Stop Work Order were issued for a failure to maintain the safe operations and to stop all material handling, including deleviers. The General Contractor is to provide a safe Means and Methods, including equipment and Tool Box talks.				NEW BUILDING	420653000	Material Fell	ROOSEVELT PARCILIC	BRAVO BUILDERS LLC
2/19/2018	Manhattan	200	EAST 21 STREET	0	The Site Safety Manager reported that a worker dislocated his left shoulder when he lifted a bag of concrete onto it. The worker was taken to Mount Sinai Hospital by ambulance.	No Dispatch			NEW BUILDING	121190479-01-NB	Other Construction Related Incidents	LONGER HILLS II LLC	BRAVO BUILDERS LLC



ncident Date	Borough	Address Number	er Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/19/2018	Brooklyn	805	WASHINGTON AVENUE	0	1 A DOB inspector reported that a worker was walking close to a Bobcat while an I-Beam was on the forks attached to the Bobcat when the I-Beam moved and the worker's hand got caught between the I-Beam and the Bobcat track. The worker suffered a fractured hand and was taken to an area hospital. The worker operating the Bobcat was not trained by the employer, which created Bobcat was not trained by the employer, which created This incident occurred on 2/18/2018, but the Sile Safety Manager was not informed of the incident until 2/20/2018. Four EGB Wildlations and a partial stop Work order were issued.		35317732Z, 35317733K AND 35317736K		NEW BUILDING	321478548	Mechanical Construction Equipment	805 WASHINGTON AVE LLC	HAPPY LIVING DEVELOPMENT
/19/2018	Brooklyn	211	SCHERMERHORN STREET	0	The Site Safety Manager reported that a worker rolled his ankle while moving material. The worker was taken to Brooklyn Hospital by EMS.	No Dispatch			FRANK HEALEY	321196200-01-NB	Other Construction Related Incidents	211 SCHERMERHORN DEVELOPMENT L	OESTREICHER CONSTRUCTION
2/20/2018	Manhattan	115	DELANCY STREET	0	The Site Safety Manager reported that a worker cut his finger while using a grinder. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
2/20/2018	Manhattan	425	PARK AVENUE	0	The Site Safety Manager reported that a worker fell from the fourth step of an "A"-Frame ladder. The worker complained of back pain. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
2/21/2018	Brooklyn	5718	2 AVENUE	0	A DOB inspector reported that a worker was pulling on one of the clips of a outrigger scaffold in order to install it properly. The worker pulled the clip hard, which caused the worker to sitled down the plant and twist his antike. The worker went to the emergency room across andike. The worker went to the emergency room across contingers were all built as per design. No enforcement was action necessary, as it was determined that the injury occurred as the result of a worker error.	No Action Necessary			ALTERATION-1	321192702	Worker Fell	NYU HOSPITALS CENTER	HUNTER ROBERTS CONSTRUCTION
2/21/2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager has reported that a worker was climbing down an 'A'-Frame ladder when he slipped and fell about four feet. An ambulance took the worker to a hospital. The worker suffered a possible fractured elbow.	No Dispatch					Worker Fell	SMITELL SPONSOR LLC	
2/21/2018	Queens	131-11	FOWLER AVENUE	0	The Site Safety Manager reported that a worker twisted his right wrist while bending rebars. A co-worker took him to a clinic.	No Dispatch					Other Construction Related Incidents	131-05 HOLDING LLC	
/21/2018	Queens	38-01	QUEENS BOULEVARD	0		ECB Violation	35285820P		NB	421387626	Worker Fell	CURBOUT QUEENS BLVD LLC	Sordoni Construction Comp
//22/2018	Staten Island	35 a	BAY STREET	0	The Site Safety Manager reported that a rebar installer slipped on a rebar floor and twisted his ankle. An ambulance was on site.	No Dispatch					Other Construction Related Incidents		
/22/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker was loading sheetrock onto an "A"-Frame when one of the boards slid and landed on his right foot. The worker was sent to urcent care.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
2/22/2018	Manhattan	122	LEXINGTON AVENUE	0	The Polico Department reported that two workers were making at elimitory to the role area of the structure when one of the workers let approximately eight to ten feet through an opening in the roof that was covered with a tarp. The worker fell to the third floor. The worker suffered injuries to his back and neck and was transported to Bellevue Hospital with head and neck injuries. A full Stop Work Order had been issued to the building on 4/2/2/2015 and a Vacate Order was issued on 12/2/2017. Two ECB Violations, and two DOB Violations were issued for the unlawful continuation of work while on the notice of a Stop Work Order and for a failure to safeguard.	ECB Violation	35308861K & 35308860Z	022218CERTQ01 & 022218CERTQ02			Worker Fell	122-24 LEXINGTON AVECP	
/22/2018	Brooklyn	19	KENT AVENUE	0	The Site Safety Manager reported that a worker walked into a pile of plywood and then felt discomfort in his upper torso and chest. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NEW BUILDING	320591944-01-NB	Other Construction Related Incidents	19 KENT ACQUISITION LLC	T.G. NICKEL & ASSOCIATES
/22/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker cut his finger while handling rebar. The worker was seen by the on-site medic and was sent to City M.D./urgent care.	No Dispatch					Other Construction Related Incidents	NYC HPD	
2/23/2018	Queens	83-09	36 AVENUE	0	1 A DOB inspector reported that workers at apartment number B42 were lowering a piece of plywood that was approximately 2 X 5 from the fourth floor fire escape to the ground using a heavy thick rope in front of the building. According to the Project Manager at the site and a bystander, the plywood slipped off of the rope and fell from the third floor level, string a young girl on the side of her head before landing on the ground. Marks from the fallen wood can still be seen on the ground where it landed. The injured young girl was transferred to New York Presbyterian Hospital of Queens with injuries to the side of her head. There Aggravated Level 2 EED Wichlotons were issued for a failure to safeguard, for work not confirms were sissued for a failure to safeguard, for work not confirms were sissued for a failure to safeguard, for work not confirms were sissed for the Stop Work Order were also issued.		35309174N, 36309325L & 35309326N	022318CERKC05, 022318CERKC04 & 022318CERKC06	ALTERATION TYPE 2	421548999-01-EW-OT	Material Fell	83-09 35TH REALTY LLC	MNR GROUP INC



ncident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	545	WEST 30 STREET	0	1 A DOB inspector reported that workers were using a full to unload window parels off of a truck. While the tull was being taken into the building, one of the panels sid off of the full and that a worker's anake. An ambulance took the worker to a hospital. An ECB Violation for a failure to maintain safe operations and a partial Stop Work Order were issued or all deliveries and material handling. The General Contractor is to provide a Means and Methods.		35317717K				Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
27/2018	Manhattan	685	FIRST AVENUE	0	The Site Safety Manage reported that a worker was working in a building when a couple of pieces of sheetrock fell over and onto his leg. An ambulance was called to the site.	No Dispatch					Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2/28/2018	Manhattan	1227	BROADWAY	0	A DOB inspector reported that a tower crane was engaged with loading a four foot piece of scaffolding engaged with loading a four foot piece of scaffolding many control of the piece of scaffolding the report of the piece of scaffolding the region of the piece of t		35225172L 35225171J & 35225172L		CN	CN 913/16	Mechanical Construction Equipment	YJL BROADWAY HOTEL LLC	BMNY CONTRACTING CORP
/28/2018	Manhattan	2	PARK PLACE	0	The Site Safety Manager reported that a worker got dust in his eye. The worker went to a hospital for treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
W1/2018	Brooklyn	391	HOOPER STREET	1	0 A DOB inspector reported that heavy gauge 2 X 10 celling joists were delivered and placed on top of the Concrete Mason, Unit CMU, exterior valls of the sixth floor when a worker enrowed a band that held the place of the concrete Mason of the sixth floor when a worker enrowed a band that held the ground of the worker of the scaffold to the ground. The joists landed on top of the worker as well. The worker was found dead on a revival. A DOB Violation and a full Stop Work Order were issued.	DOB Violation		030118BS01AS01			Other Construction Related Incidents	E&D MANAGEMENT GROUP LLC	
2/2018	Queens	28-02	JACKSON AVENUE	0	1 A DOB inspector reported that a panel of plywood that was about 8 X 4 fell from the parapet of a sidewalk shed and struck two pedestrians. One of the pedestrians suffered an injury in the shoulder area. The injured pedestrian was seen by the on-site medic, but denied further medical attention and left the scene. An Aggravated Level 2 ECB Vilolation was issued for a failure to safeguard public and property affected by construction operations. A second ECB Vilolation was also issued for a failure to maintain an inspection log for the sidewalk shed. A partial StDy Work Order was also issued. The sidewalk shed. A partial StDy Work Order was also issued. The sidewalk shed. Company was sent to the site for repair work.		35318105Y		NEW BUILDING	420652877	Scaffold/Shed/Fence/Shoring/Installation	LIC DEVELOPMENT OWNER, L.P.	TURNER CONSTRUCTION COMPA
2/2018	Manhattan	685	1 AVENUE	0	The Site Safety Manager reported that a worker was pushing a mini container when the gate on the bottom of a ramp swung and lacerated his right hand. The on-site medic put a band aid on the cut. An ambulance took the worker to a hospital.						Other Construction Related Incidents	685 FIRST REALTY COMPANY, LLC	
2/2018	Manhattan	260	WEST 40 STREET	0	The Site Safety Manager reported that a worker was using a lade and cut his finger. The worker was patched up on-site, but then went to City M.D. where he received two to three stitches.				NB - NEW BUILDING	121187394	Other Construction Related Incidents	PORT 40TH PARKING CORP	ZDG, LLC
3/2018	Manhattan	150	EAST 23 STREET	0	The Site Safety Manager reported that workers were carrying steel plates when one of the plates slipped and pinched one of the worker's left middle finger. The worker was transported to a hospital by ambulance.				NB	121981748	Other Construction Related Incidents	154 EAST 23 LLC	W & L GROUP CONSTRUCTION
3/2018	Manhattan	1912	1 AVENUE	0	The Site Safety Manager reported that a worker tripped and fell while carrying framing. EMS was called and the worker was transported to a hospital.	No Dispatch			NB	122879233	Worker Fell		PROCIDA CONSTRUCTION CORP
3/2018	Manhattan	396	BROADWAY	0	The Site Safety Manager reported that a worker dropped a piece of plywood on his foot. The worker left the site in an ambulance.				A1 - ALTERATION TYPE 1	120786417	Other Construction Related Incidents	BRIDGETON 396 BROADWAY FEE LLC	ANTHONY T. RINALDI
3/2018	Manhattan	425	WEST 18 STREET	0	The Site Safety Manager reported that a worker hurt his back while picking up a cement bag. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NB	122736762	Other Construction Related Incidents	NOT ON FILE	ARTIMUS CONSTRUCTION INC
5/2018	Brooklyn	10	HURON STREET	0	1 The Sie Safety Manager reported that there were two workers that were doing sheetrock work together when one of the worker lost his ging on a piece of sheetrock that landed on the other worker's finger, causing a cut. The second worker left the site and went to City M.D. in gasters on his finger. This drodlers could be seen to the site of the second worker of the second worker of the second worker of the second worker of the second to the Site Safety of the second to the	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	



ncident Date	Borough	Address Number		Fatalities Injurie	es EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
018	Queens	45-57	UNION STREET	0	1 A DOB inspector reported that a 16' X 8' size gate	ECB Violation	35317909P				Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
					swung out and hit a pedestrian that was walking by. The pedestrian was a student that was approximately seven years old. The student was evaluated by a nurse.								
118	Manhattan	2255	BROADWAY	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	2255 HOLDING LLC	
					lifting a 2 X 3 X 10 wooden beam in the elevator pit when he hit himself in the face with the wooden beam.								
					The worker went to urgent care and then went to a								
					hospital. This incident occurred as a result of a worker								
018	Bronx	2395	FREDERICK DOUGLASS BLVD	0	The Site Safety Manager reported that a pedestrian in a	FCR Violation	35300487N	030618BS10VP06			Other Construction Related Incidents		
		1			wheelchair fell over in a walkway due to a tripping								
					hazard around a Con-Ed sewer cap. The pedestrian went to a hospital by ambulance. A DOB inspector								
					responded to the incident, visited the site, and issued an								
					ECB Violation. The tripping hazard was corrected as of the time that the inspector was at the site.								
					and and the inspector was at the site.								
2018	Brooklyn	416	KENT AVENUE	0	1 The Site Safety Manager reported that a worker slipped,	No Dispatch				320622616	Other Construction Related Incidents	420 KENT AVENUE LLC	ZDG, LLC
					fell, and hurt his arm. The worker was taken to a hospital for a check up.								
2018	Manhattan	1681	3 AVENUE	0	1 The Site Safety Manager reported that an electrician	No Dispatch					Other Construction Related Incidents	95TH AND THIRD LLC	
					was running a wire when he tripped on a piece of plywood and skinned his right shin. The electrician went								
					to a City M.D. for assistance.								
2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a piece of plywood slid and hit a worker on the left knee while the	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
					worker was stocking plywood on the floor. The worker								
2018	Queens	28-07	JACKSON AVENUE	0	went to a clinic.  1 A DOB inspector reported that there were two	ECB Violation	35318121Y-FAIL TO SAFEGUARD	030818BS02KA01	NB	420656873	Material Fell	LIC SITE B-1 OWNER, L.L.C.	NEW LINE STRUCTURES & DEV
2010	quouns	20-07	U.O.OON AVENUE		electricians working on a scissor lift at the basement	200 Violation	GOOD TO THE TO GAI EGUARD	3300 1003021001	NO.	420030073	material i dii	DO SILE D'I OWNER, E.E.G.	ZINE STRUCTURES & DEV
					level when a temporary light fixture was accidentally bumped and dislodged, causing it to fall approximately								
					five feet and strike a worker that was passing by on the								
					head and back. The electricians were working without a controlled access zone below. The worker was found								
					alert, but complained of head pain and went to urgent								
					care. An ECB Violation for a failure to safeguard was issued, as well as a partial Stop Work Order for the								
					installation of electrical lighting work. A Means and								
					Methods must be provided.								
018	Staten Island	546	GULF AVENUE	0	The Site Safety Manager reported that a worker slid and	No Dienatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
2018	Staten Island	546	GULF AVENUE	0	hit his left knee as he was taking the stairs to his trailer.	No Dispatch					Worker Fell	STATEN ISLAND GLOBAL LOGISTIC	
					The worker was taken to a hospital for a check up.								
2018	Manhattan	1059	3 AVENUE	0		ECB Violation	35300269P	030918BS08MH01			Material Fell	63RD & 3RD NYC LLC	
					carrying a few formwork clamps that weight approximately 10-15 pounds and are about 18 feet long								
					in length up the third floor steps when one of the clamps								
					fell from his grip and hit the wrist of a mason that was working in the basement, possibly breaking the mason's								
					wrist. An ambulance was called. An ECB Violation and a								
					partial Stop Work Order were issued for the unsafe handling of materials. A DOB Violation was also issued.								
					A Means and Methods will be provided for the safe								
					handling of form work materials.								
2018	Manhattan	217	WEST 57 STREET	0	The Site Safety Manager reported that a worker as	ECB Violation	35286419N				Worker Fell	SMITELL SPONSOR LLC	
					carrying equipment when he slipped and fell. The worker hit the back of his head and blacked out. The worker	r							
					was sent to Mount Sinai Hospital. A DOB inspector								
					responded and visited the site and reported that the								
					worker slid on what look like an ice patch on the floor, even through there was ice melt spread throughout the								
					are. An ECB Violation was issued for a failure to maintain safe operations.								
2018	Manhattan	29	11 AVENUE	0	1 The Site Safety Manager reported that an iron worker	No Dispatch					Other Construction Related Incidents	NYS PARKS & RECREATION	
					was attempting to move a steel beam onto a dolly on his own when the beam slid and hit his left knee. 911 was								
					called and the worker was taken to a hospital.								
2018	Manhattan	704	7 AVENUE		The Site Safety Manager reports that a worker pinched	No Dienoteh					Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	
.010	mainaudli	701	AVENUE	0	his finger while cutting a Formica board with a circular	140 Dispatch					Outer Construction Related incidents	701 SEVENTH PROPERTY OWNER LLC	
					saw. The worker went to the emergency room on his								
2018	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that an ironworker	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
					hurt his right index finger while prying a cross brace.  The worker was transported to Bellevue Hospital by								
					ambulance.								
/2018	Manhattan	125	GREENWICH STREET	0	1 A DOB inspector reported that a worker was lifting up a	No Action Necessary					Material Fell	VS 125 LLC	
					four foot section of form work when the worker mishandled the form work, causing the form work to fall								
					on his knee. An ambulance was called, It was								
					determined that the incident happened as a result of a worker error and that no enforcement action was								
					necessary.								
			GREENWICH STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Worker Fell	VS 125 LLC	
/2018	Manhattan	125	GREENWICH STREET	0	Title One durity manager reported that a worker was								
/2018	Manhattan	125	GREENWICH STREET	0	handling a roll of felt paper when he slipped backwards and suffered a laceration to the left side of his forehead.								
2018	Manhattan	125	GREENWICH STREET	0	handling a roll of felt paper when he slipped backwards and suffered a laceration to the left side of his forehead. The worker did not want an ambulance to be called and went to a City M.D. instead.								



	Borough	Address Number		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/12/2018	Manhattan	255	EAST HOUSTON STREET	0	The Site Safety Manager reported that a worker's finger got caught between two beams while he was pushing	No Dispatch					Other Construction Related Incidents	255 EAST HOUSTON OWNER LLC	
					forwards beams on a truck. The worker was sent to								
3/2018	Queens	150-13	89 AVENUE	1	Bellevue Hospital.  0 A DOB inspector reported that a worker was riding on	DOB Violation		031318BS1201MC			Other Construction Related Incidents	88TH AVENUE OWNER LLC	
2010	quotio	155 15	OU AVENUE		the back of a fork lift during a placement of hundle	DOD VIOLATION		0010105012011110			Care Constitution (Care and Care)	SOTTIVE TO CONTENT ELECT	
					windows in the storing garage. The bundle was 10' X 5' X 6' and bounced up and down due to its size and								
					weight. The driver of the forklift heard a sound and then								
					saw that the worker who was riding on the back was on								
					the floor. The worker was found dead. There were no								
					witnesses to the incident, and the incident is currently under police investigation. The driver of the fork lift was								
					found to be not certified to operate a fork lift. The driver								
					was in a traumatized state and went to a hospital. A DOB Violation for a failure to safeguard and a Stop								
					Work Order were issued. ECB Violations are being								
					prepared to be served.								
2018	Brooklyn	3617	13 AVENUE	0	1 A DOB inspector reported that a worker lacerated his	ECB Violation	35318355R				Other Construction Related Incidents	37TH STREET HOLDINGS LLC	
					foot while driving a walk-behind saw to a container in order to park it. The worker was sent to a hospital. A an								
					ECB Violation was issued, as well as a partial Stop								
					Work Order on the use of the walk-behind saw. Manufacturer specifications must be provided.								
					manadatarer specimentorio mast be provided.								
2018	Manhattan	220	CENTRAL PARK SOUTH	0	The Site Safety Manager reported that an iron worker pinched his index finger while unloading a cart of steel.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
					pinched his index finger while unloading a cart of steel. The worker went to a clinic to receive stitches for his								
					finger.								
2018	Brooklyn	225	4 AVENUE	0	1 A DOB inspector reported that workers were in the	ECB Violation	35309294H	031518CERDM01	NB	310086554	Material Fell	225 4TH AVENUE PROPERTY OWNER	TRM Construction
					process of cleaning brick with an acid base solvent								
					when some of the solvent fell into the eye of a female pedestrian. The pedestrian had her eye rinsed out and								
					was treated on the site. The pedestrian did not go to the								
					hospital. An Aggravated Level 2 ECB Violation for the failure to safeguard all persons and property affected by								
					construction operations was issued, as well as a DOB								
					Violation and a partial Stop Work Order for facade work.								
					It was recommended that the BEST Squad perform a follow up inspection for compliance and safety								
					measures.								
018	Queens	21-30	44 DRIVE	0	1 The Site Safety Manager reported that a piece of	ECB Violation	35318143P	031918BS02KA04			Material Fell	44TH DRIVE OWNER LLC	
					plywood fell from the first floor to the cellar due to the wind. The plywood landed on the cellar floor where it								
					then fell onto a worker, hurting the worker's shoulder.								
					This incident occurred on March 16, 2018, but the								
					Department Of Buildings was not notified until March 19,								
					2018, because the Construction Superintendent claimed that he called the office on 3/16/2018 after 4:00 PM and								
					that no one answered the phone. An ECB Violation was								
					issued for a failure to safeguard for not securing materials during a weather advisory. A DOB Violation								
					and a partial Stop Work Order for all form work were								
					also issued. A Means and Methods for the securing of								
					materials during a weather advisory must be provided.								
2018	Manhattan	501	WEST 18 STREET	0	1 A DOB inspector reported that during excavation work, a	ECB Violation	35314141N		New Building	121191147	Excavation/Soil Work	18TH HIGHLINE ASSOCIATES, L.L.	Related Construction LLC
					worker was torching a hole in two steel "H" piles and								
					was laving side by side in order to sling and rig the pile								
					was laying side by side in order to sling and rig the pile								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the writer was okay as he suffered minor injuries to his								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between how piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution An ECB Violation was issued for a failure to safeguard. A partial Size Violation was issued to stop all								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A								
					was laying side by side in order to sling and rig the pile when the secretarior that was being used moved, which caused the worker's leg to become pinched between two piles. The Siles Safety Manager stated that the worker was okay, as he suffered minor juniors to his leg, but he was sent to a hospital as a precaution. An Aparial Stop Work Order was issued to stop all movement and properation of steep ijes. The contractor movement and preperation of steep lies. The contractor								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between how piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution has presented to see that the worker was okay, as he suffered minor injuries to his pile, but he was sent to a hospital as a precaution has partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Means and Methods for the safe								
					was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Sately Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.								
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two plies. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel plies. The contractor is to provide a Meema and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the	ECB Violation	ECB#3S318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two plies. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Slop Work Order was issued to stop all movement and preparation of steel piles. The contractor is to provide a Memera and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move	ECB Violation	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the sexcavor that was being used moved, which caused the worker's leg to become pinched between two piles. The Siles Safety Manager stated that the worker was okay, as he suffered minor liquides to his leg, but he was earn to a hospital as a precaution. An parial Stop Work Order was issued to stop all movement and reperation of steel piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powering failet jack to move	ECB Violation	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Mears and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement dwom a ramp when the powered pallet jack moved on its own and ran over the worker's left floot. The worker went to Rosewet Hospital. A DOB	ECB Violation	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Memars and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet pack moved on its own and ran over the worker's left ack moved on its own and ran over the worker's left lack moved on its own and ran over the worker's left in the property of the property		ECB#3SS18264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Sile Safety Manager stated that the worker was okay, as he suffered minor liquides to his leg, but he was sent to a hopsile as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Silog Work Order was issued to stop all partial Silog Work Order was issued to stop all partial Silog Work Order was issued to stop all more stated or the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack moved on its own and ran over the worker's left loot. The worker's left floor. The worker's left Roserver Hospital. A DOB Violation for a failure to maintain unsafe equipment. A DOB Violation and a partial Stoc Work Order for all work or the state of the safe was the safe of the safe or t		ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Memars and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet pack moved on its own and ran over the worker's left ack moved on its own and ran over the worker's left lack moved on its own and ran over the worker's left in the property of the property		ECB#3S318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
2018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Meman and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move to its own and ran over the worker's left lock, but the province of the province o		ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
2018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two plies. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Slog Work Order was issued to stop all movement and prepetation of steel plies. The contractor is to provide a Meera and Meholing for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move a float the safety of the saf		ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
2018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Meman and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move to its own and ran over the worker's left lock, but the province of the province o		ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS06MA01	NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
018	Manhattan	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preperation of steel piles. The contractor is to provide a Meman and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move to the second floor in some down over the worker's left lack moved or its own and ran over the worker's left lack moved or its own and ran over the worker's left lack moved or its own and ran over the worker's left lack moved or its own and ran unsafe equipment. A DGB Violation for a failure to maintain unsafe equipment. A DGB Violation for a failure to maintain unsafe equipment of Tower Boulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Means and Methods must be provided. The BEST Squal must be contacted for a re-		ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	Q31618BS05MA01	NB NB	121184592	Mechanical Construction Equipment	VNO 225 WEST 58TH STREET LLC	LEND LEASE CONSTRUCTION
2018	Manhattan  Brooklyn	220	CENTRAL PARK SOUTH	0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Sile Safety Manager stated that the worker was okay, as he suffered minor liquides to hile, but he was sent to a hospital as a precaution. An ECO Violation was issued for a failure to self-guard. An movement and properation of steep piles. The contractor is to provide a Means and Methods for the safe movement and properation of steep piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of centered down a ramp when the powered pallet inspector responded to the incident and issued an ECB Violation for a failue to maintain unsafe equipment. A DOB Violation and a partial Stoy Work Order for all work using equipment to transport loads as the second floor north of Tower Boulevard were also issued. The powered pallet jack was found to have no inspection not, an orientation and a Means and Methods must be provided. The EEST Squad must be contacted for a reimpection.	No Dispatch	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB NB	121184592 120622616	Mechanical Construction Equipment  Worker Fell	VNO 225 WEST 58TH STREET LLC  420 KENT AVENUE LLC	LEND LEASE CONSTRUCTION
				0	was laying side by slide in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two plies. The Site Safety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order was issued to stop all movement and preparation of steel plies. The contractor is to provide a Meera and Methods for the safe movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack moved on its own and ran over the worker's left foot. The worker went to Rosevet Hospital. A DOB inspector responded to the incident and issued an ECB Violation for a failute to maintain unsafe equipment. A DOB Violation and a partial Stop Work Order for all work using equipment to transport loads as the second floor north of Tower Boulevard were also issued. The powered pallet jack was found to have no rinspection.  1 The Site Safety Manager reported that at a twenty-two stopy new building under construction, a worker that was	No Dispatch	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS06MA01	NB NB				
				0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor liquides to his leg, but he was sent to a hospital as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Sigo Work Order was issued to stop all partial Sigo Work Order was sissued to stop all partial Sigo Work Order was issued to stop all movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move the worker's left floor. The worker's left floor. The worker's left floor. The worker's left floor on a failure to maintain unsafe equipment. A DOB Violation for a failure to maintain unsafe equipment of transport loads as the second floor north of Tower Soulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Menas and Methods must be provided. The BEST Squad must be contacted for a reinspection.	No Dispatch	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB NB				
				0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor laying state that the worker was okay, as he suffered minor lay layer to the piles of the suffered minor layer to stop all leg, but he was sent to a hopeful as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Sigo Work Order was issued to stop all partial Sigo Work Order was issued to stop all partial Sigo Work Order was issued to stop all movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move the worker's left floor. The worker's left floor. The worker's left floor on the Tower's pallet jack was found to have no inspection onth of Tower Soulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Menas and Methods must be provided. The BEST Squad must be contacted for a reinspection.	No Dispatch	ECB#3S318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB NB				
				0	was laying side by side in order to sling and rig the pile when the sexcavor that was being used moved, which caused the worker's leg to become pinched between two piles. The Siles Salety Manager stated that the worker was okay, as he suffered minor injuries to his leg, but he was sent to a hopeint as a precaution. An Aparial Stop Work Order was issued to stop all movement and reperation of steep piles. The contractor is to provide a Means and Methods for the safe movement of steel around the construction site.  1 This Site Safety Manager reported that a worker on the executed floor was using a powered palet jack to move heapy of foor was using a powered palet jack to move heapy of foor was using a powered palet jack to move heapy of foor was using a powered palet jack to move heapy of foor the surface of the provided that worker on the second floor in the contractor of the second floor to deviay a ring when the powered palet jack moved on its cown and ran over the worker's left foot. The worker went to Roosevelt Hospital. A DOB inspector responded to the incident and issued an ECB Violation for a failue to maintain unsafe equipment. A DOB Violation and a parial Stop Work Order for all work using equipment to transport loads as the second floor longs. An orientation and a Means and Methods must be provided. The BEST Squad must be contacted for a reinspection.	No Dispatch	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	Q31618BS05MA01	NB NB				
				0	was laying side by side in order to sling and rig the pile when the excavator that was being used moved, which caused the worker's leg to become pinched between two piles. The Site Safety Manager stated that the worker was okay, as he suffered minor laying state that the worker was okay, as he suffered minor lay layer to the piles of the suffered minor layer to stop all leg, but he was sent to a hopeful as a precaution. An ECB Violation was issued for a failure to safeguard. A partial Sigo Work Order was issued to stop all partial Sigo Work Order was issued to stop all partial Sigo Work Order was issued to stop all movement of steel around the construction site.  1 The Site Safety Manager reported that a worker on the second floor was using a powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move bags of cement down a ramp when the powered pallet jack to move the worker's left floor. The worker's left floor. The worker's left floor on the Tower's pallet jack was found to have no inspection onth of Tower Soulevard were also issued. The powered pallet jack was found to have no inspection logs. An orientation and a Menas and Methods must be provided. The BEST Squad must be contacted for a reinspection.	No Dispatch	ECB#35318264L FAILURE TO MAINTAIN UNSAFE EQUIPMENT	031618BS05MA01	NB NB				



ident Date	Borough	Address Number	er Street	Fatalities Injurie	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	1277	EAST 14 STREET	0	1 A competent person at the construction site reported that a worker slipped on a supported scalifold and fell approximately six feet, along with a few planks. The worker's foreman stated that the worker drove to see a doctor on his own. A DDB inspector responded and visited the site and reported that the supported scaffold did not conform to code specifications, as the scaffold did not conform to code specifications, as the scaffold was not fully placed, the planks were not tied down, and a guard rail system was missing from multiple locations. Two EDP violations and a parella Stop Work Order for a supported scaffold were issued.	ECB Violation	35285912M.35285913Y		NB	320597127	Worker Fell	1277 HOLDINGS LLC	Ray Builders Inc.
2018	Manhattan	40	CLERMONT AVE	0	1 The Site Safety Manager reported that a carpenter was working on an "A"-Frame ladder when he missed the fifth step of the ladder and fell. An ambulance came and took the worker to a hospital.	No Dispatch					Worker Fell		
2018	Manhattan	590	EAST 83 STREET	0	The Site Safety Manager reported that a worker tripped and jammed his finger. An ambulance took the worker to a hospital.	No Dispatch			NEW BUILDING	121190987-01-NB	Worker Fell	THE BREARLEY SCHOOL	E.W. HOWELL CO, LLC
/2018	Brooklyn	10	MONTIETH STREET	0	The Site Super reported that a worker attempted to jump over a fence and fell. The worker was taken to a hospital by ambulance.	No Dispatch			NEW BUILDING	320622750-01-NB	Worker Fell	BUSHWICK HOLDINGS I LLC	GALAXY DEVELOPERS LLC
/2018	Manhattan	108	EAST 89 STREET	0	The Site Safety Manage reported that a worker hurt his shoulder while installing a pipe scaffold. The worker went to a City M.D. to get checked.	No Dispatch			ALTERATION TYPE 1	122988623-01-AL	Worker Fell		E.W. HOWELL CO, LLC
20/2018	Queens	43-12	HUNTER STREET	0	1 A DOB inspector reported that contractors were in the process of litting a section of steel classisson in order to set at on a drill reg when a worker had his hand pinched between the caisson and a steel hook. The worker was alert and awake and was taken to a nearby hospital by a taat. The extent of the injury to the worker's hand was not known as of the time of inspection. An ECB Violation for a failure to safeguard and an ECB Violation for the beginn on log on site were issued, as well as a full Slop Work Order for the entire site. The contractor at the site was instructed to provide a Means and Methods for safe pile installation.		35314355z 35314356k		NB	420659530	Mechanical Construction Equipment	43-12 HUNTER LLC	Judy y Lee
2018	Bronx	2028	CRESTON AVENUE	0	The Site Safety Manager reported that at an eleven story new building under construction, a worker was handling concrete out of a mixer when cement splashed into the worker's right eye. The worker was alert and awake and was taken to Lincoln Hospital for treatment.	No Dispatch			NB	220392858	Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	MACQUESTEN CONS. MNGMT
2018	Manhattan	650	5 AVENUE	0	The Site Safety Manager reported that a worker was working with temporary electrical wiring on the second floor when a 48-ovel twie touched an I-Beam, which caused an ARC flash. The worker suffered an injury to his eyes and was taken to a hospital. A DOB inspector determined that there was no enforcement acton necessary.	No Action Necessary			Electrical	M00016968	Other Construction Related Incidents	650 FIFTH AVENUE COMPANY	
2018	Brooklyn	1835	STERLING PLACE	0	The Construction Superintendent reported that a worker slipped off of an "A"-Frame ladder while coming down from the ladder. The worker suffered a minor laceration to the head. The worker was found conscious and an ambulance was called.	No Dispatch					Worker Fell	NOT ON FILE	
3/2018	Manhattan	115	DELANCY STREET	0	1 The Site Safety Manager reported that a worker was cleaning around a Con Edision vault when he lifted an unmarked jeec of plywood that was covering the vault, tripped into a shaft, and fell approximately eight to nine was allert and awake and was taken to Bellevian Hospital. An ECB Violation for a failure to safequard was issued, as well as a DOB Violation and a partial Stoy Work Order for all exterior work at the ground floor at exposure three. Protections around the vaults at the ground level must be provided. An updated Means and Methods and Tool Box Talk must be provided.		ECB#35317775Z-FAIL TO SAFEGUARD	032318BSO3GD01	NB	121191646	Other Construction Related Incidents	NOT ON FILE	T.G. NICKEL & ASSOCIATES
8/2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that an electrician was climbing up the rebar cage to reach the electricial conduit when he slipped, fell two feet, and landed on his right ankle. The electrician was sent to a clinic.						Worker Fell	40-56 TENTH OWNER LLC	
/2018	Manhattan	1865	BROADWAY	0	The Site Safety Manager reported that a worker was cutting metal studs when he cut the top of his hand with a chop saw. The worker went to the emergency room with another worker. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	AVB 1865 BROADWAY, LLC	
/2018	Brooklyn	19	INDIA STREET	0	The Site Safety Manager reported that a worker was moving windows when he tripped, fell three steps, and hit the back of his neck on a cinderblock. The worker was alert and responsive and was taken to Bellevue Hospital.	No Dispatch			NEW BUILDING	310234207-01-NB	Worker Fell	145 WEST STREET LLC	NOBLE CONSTRUCTION GR LLC
/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	The Construction Superintendent reported that a worker was testing a refrigerant line when the line burst, causing discomfort to the worker's ears. A co-worker drove the injured worker to a hospital.	No Dispatch			Alt 1	320622894	Other Construction Related Incidents	ATLANTIC 2644, LLC	CAULDWELL WINGATE CO LLC



	Borough	Address Number		Fatalities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	250	SOUTH STREET	0	1 A DOB inspector reported that a worker was bringing a cardiol down when a gust of wind moved the pletform out of the building. The worker stuck his hand out to prevent the importa against the building, but hurt his shoulder and back in the process. The worker was taken to a hospital where he was in stable condition. It was determined that no enforcement action was necessary, as the suspended estaffold was found to be in compliance with approad drawings, the current notification and installation letter from the engineer was onsite, and all logs were in order.		N/A		NB	121185528	Scaffold/Shed/Fence/Shoring/Installation	NOT ON FILE	Lend Lease (US) Construct
26/2018	Manhattan	420	EAST 54 STREET	0	1 The Site Safety Manager reported that the building cowner's personal driver had his foot struck by a forkfilt. The injurid person was taken to a hospital. A DOB inspector reported that only one flag person was used when moving the forkfilt and that the injurid person walked into a controlled no access zone when he had his foot struck by the forkfilt. An ECB Violation was issued for a failure to safeguard. A DOB Violation and a partial Stop Work Order were also issued. A Means and Methods and Tool Box Talks will be provided by the General Contractor at the site for safe delivery operations and for the proper amount of flaggers.	ECB Violation	35317780N	032618BSo6GD01			Other Construction Related Incidents	RIVER TOWER OWNER, LLC	
7/2018	Manhattan	432	EAST 14 STREET	0	The Construction Superintendent reported that a worker was pushing a mini container when she slipped and hit her knee. The worker was taken to a hospital.	No Dispatch					Other Construction Related Incidents	EAST 14TH STREET OWNERS LLC	
28/2018	Manhattan	441	9 AVENUE	0	The Site Safety Manager reported that a worker got his hand jammed between two stripping panels. A foreman took the worker to a hospital.	No Dispatch					Other Construction Related Incidents	CBP 441 NINTH AVENUE OWNER, LL	
28/2018	Brooklyn	505	PACIFIC STREET	0	The Site Safety Manager reported that a worker slipped with a grinder and cut his face. An ambulance transported the worker to a hospital.	No Dispatch			NEW BUILDING	320909004-01-NB	Other Construction Related Incidents	PVII HSC ATLANTIC LLC	TRITON CONSTRUCTION CO.,
30/2018	Manhattan	265	WEST 114 STREET	0		ECB Violation	35286045H		Alt 1	121189668	Material Fell	TRINITY WEST HARLEM PHASE TWO	Mega Contracting Gp LLC
2018	Queens	22-06	31 STREET	0	1 A competent person at the site reported that a worker that was coming into the site slipped on snow and injured his knee. The worker went to see his doctor for a check up. There was a snowstorm in progress as of the time of the incident.	No Dispatch					Other Construction Related Incidents	DITMARS 31ST STREET ASSOCIATES	
2018	Staten Island	2655	RICHMOND AVENUE	0	1 A DOB inspector reported that there were workers that were moving a wooden ramp that was about 4 X 8 r X. 201. When the ramp was in a vertical position, one 2 X 4 fell onto the hand of one of the workers. The worker went to urgent care. An ECB Violation and a partial Stop Work Order (PSWO) were issued for all use of ramps. A Means and Methods and the design drawing must be provided.		35327352X				Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
/2018	Bronx	2681	MARION AVENUE	0	1 A DOB inspector reported that a flagger was signaling for deliveries for traffic on the street when a cab driver inted to maneuver around a comer and ran over the flaggers foot. The flagger went to a hospital with a coworker in an ambulance. The inspector determined that there was no enforcement action necessary, as the flagger was certified and a delivery Means and Methods was at the site.	No Action Necessary					Other Construction Related Incidents	PCMH MARION AVENUE HOUSING DEV	
/2018	Bronx	2760	BRIGGS AVENUE	0	1 The Site Safety Manager reported that a worker slipped on plywood that had snow on it. The worker claimed to have hunt his wist while tyrigo to brace himself after slipping. The worker went to a doctor on his own. This incident occurred in the morning, but the worker waited until the alternoon to report the incident and go to a doctor. A DOB inspector visited the site and reported that there were no witnesses to the worker slipping and that there were no witnesses to the worker slipping and the area that the worker was working. A cause of the slip could not be determined. Because of this, no enforcement action was deemed necessary.						Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker slipped on a wet surface and fell on his hand. The worker went to a City M.D.						Worker Fell	NYC HPD	
3/2018	Brooklyn	422	FULTON STREET	0	The Site Safety Manager reported that a security guard tripped and fell. The security guard was taken to a hospital as a precaution.	No Dispatch			ALT 1	320908899	Other Construction Related Incidents	NOT ON FILE	TRANSPARENT CONSTRUCTION



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
4/4/2018	Brooklyn	5815	7 AVENUE		performed because a construction fence fell at the site. A DOB inspector responded and viside the site and reported that the job site fence at exposure one had collapsed not the public sidewalk. There were two injuries reported; a mother and a daughter. The mother and daughter were both taken to an area hospital. All fencing and debris at the site has been removed and made safe against the wind. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and full Stop Work Crider were also issued. This incident was reported under Incident Number 25737. Incident Number 25737 was deleted by accident, and Incident Number 25473 was created in its place.		35323275N	040418CERCM02	Alteration 1	320516152	Other Construction Related Incidents	SIU PING	GUO Z HUANGNIEWLAND CONSTRUCTION
4/4/2018	Manhattan	500	WEST 33 STREET	0	The Safety Director reported that a worker slipped and his her tailabone while getting of I of a scissor lift. An ambulance was called and transported the worker to a hospital. A Dol sinspector visited the site and issued an ECB Violation and a partial Stop Work Order on all use of scissor lifts. The General Contractor is to provide training.		35327428N				Other Construction Related Incidents	NOT ON FILE	
4/5/2018	Manhattan	4	WEST 37 STREET	0	The Site Safety Manager reported that a plumber was found dead on the fourth floor of a framed out empty room. There were no tools and no ladder found on the scene. A DOB inspector responded to the incident and visited the site, and reported that the worker suffered a possible heart attack and was revived with a faint pulse. No enforcement action was necessary.						Other Construction Related Incidents	4 WEST 37TH STREET LLC	
4/6/2018	Manhattan	125	GREENWICH STREET	0	The Site Safety Manager reported that a worker hit himself in the face while stripping forms. The worker was driven to a City M.D.	No Dispatch			NEW BUILDING	121183799-01-NB	Other Construction Related Incidents	VS 125 LLC	PLAZA CONSTRUCTION LLC
4/9/2018	Brocklyn	231	AINSLIE STREET	o	IA DOB inspector reported that, according to a worker that was at the sich, the owner of the construction company at the site was on a pipe scalloid inspecting brick work that was done when he look in shalance and tried to grab a bike rack was not here her look in shalance and tried to grab a bike rack was not here rack of the scalloid. The bike rack was not properly secured and gave way, causing the owner to fall eight feet from the pipe scalfold that was on top of the sidewalk shed deck. The owner was transported to an area hospital with serious injuries. There was some debris found on the sidewalk shed deck, and the pipe scalfold was not fully planked, did no have any railing, and did not have all feline. The SCE Violations, two DOB Violations, and a full Stop Work Order (FSWO) were issued for the failure to safeguard all persons and properly, for the supported scalfold on top of the shed not being maintained as per code, for work without permit being performed, and for brick exterior work first exceeded the area that does not require a permit.	t	35323245M & 3532324@y	040918CERDF03 & 040918CERDF04			Worker Fell	ST OONO DE TEGGIANO C	
4/9/2018	Brooklyn	420	KENT AVENUE	0	1 The Site Safety Manager reported that a steamfitter cut his finger while putting coupling on a pipe. 911 was called and the worker was taken to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	420 KENT AVENUE LLC	
4/9/2018	Manhattan	11	WEST 53 STREET	0	The Construction Superintendent reported that a worker was on a sisses filt and was typing to gain access into a plenum. The worker's hand was on the handrail of the scissor lift and his hand got pinned between the handrail and the handrail got or of the plenum. The worker's hand was cut and the worker went to a hospital for a checkup.				ALTERATION-1	121190193	Other Construction Related Incidents	THE MUSEUM OF MODERN ART	TURNER CONSTRUCTION CO
4/9/2018	Manhettan	15	WEST 26 STREET	0	IA DOB inspector reported that a worker was using a hele saw that jammed. The Construction Superintenden unplugged the tool and straightened it out. When the hole saw was plugged back in, the saw was ung around and pushed the Construction Superintendent down, causing him to fall approximately lever feet. The Construction Superintendent subserious condition. The Construction Superintendent is now stable, but suffered a brain injury. An ECB Violation, and Dat Violation, and Dat Violation, and Dat Violation, and Superintendent is now stable, but suffered a brain injury. An ECB construction operations, as the Construction operations, and the Construction operations of the Construction ope	DOB Violation	35323475H	040918CERND01	ALTERATION TYPE 2	123203069-01-EW-OT	Worker Fell	ST SAVA CATHEDRAL	G.P.J. O'DONOGHUE CONTRAC
4/9/2018	Manhattan	25	PARK ROW	0	The Site Safety Manager reported that a hoist installer got the tip of his finger crushed while working on the hoist when the gate came down. The worker was taken to the emergency room.	No Dispatch					Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	FOC Final Description	DOB Action	FCR Violation Numbers	DOR Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
Incident Date 4/9/2018	Borough Manhattan	Address Number 420	Street EAST 54 STREET	Fatalities Injuries	EOC Final Description  1 A DOB inspector reported that there were three workers working on the thirty seventh floor doing interior demolition work and removing debris. There was an approximate 277 x 277 opening in the floor that was not properly covered, as a door from the demolition work was used to cover the hole and the hole was not properly marked or secured. One of the workers picked up the door, unaware of the hole underneast it, and fell through the opening to the thirty sixth floor. The worker was sent to a hospital for a checkup. Follow up information regarding the injured worker is not currently available. Two EOE Wolstons were issued for the diafure to maintain safety measures and for inadequate to maintain safety measures and fer inadequate Themose was also and the safe to provide underneast and Methods for the safe operation of the job, including the protection of empty shafts and floor openings.		ECB Violation Numbers 35317792K, 35317793M	DOB Violation Numbers	Permit ALTERATION 2	Permit No 122939357	Incident Type Worker Fell	Owner's Name RIVER TOWER OWNER, LLC	Contractor Name VECTOR BUILDING CORP
4/9/2018	Queens	123-30	ROOSEVELT AVENUE	0	The Site Safety Manager reported that a worker tripped on a curb and twisted his ankle while carrying a panel.	No Dispatch					Other Construction Related Incidents	NYC PARKS	
4/9/2018	Queens	147-40	ARCHER AVENUE	0	An ambulance was called.  1 The Site Safety Manager reported that a worker stepped on a tie-wire that was used for rebar work and the tie-wire punctured his boot and foot. The worker went to see a doctor on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
4/10/2018	Manhattan	150	5 AVENUE	0	The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taken to a hospital by an ambulance.	No Dispatch			ALTERATION TYPE 1	122700292-01-AL	Worker Fell	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
4/11/2018	Queens	45-57	UNION STREET	0	to a ricepitate by an anitoplance.  The Site Safety Manager reported that a worker was on a six foot ladder when he missed the second rung of the ladder while coming down from it and fell backwards and hit his head. The worker went to a hospital with his shop steward.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
4/11/2018	Queens	147-40	ARCHER AVENUE	0	1 The Site Safety Manager reported that a worker was stripping form work when a dust particle got between his safety glasses and irritated his eye. The worker went to a nearby City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
4/12/2018	Bronx	600	BERGEN AVENUE	0		ECB Violation	35314470y		NB	220151868	Mechanical Construction Equipment	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST.DEVELP.
4/12/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was walking on the second floor when he stepped on a nail. The worker went to get a tetanus shot.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
4/12/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manger reported that a worker twisted his knee while climbing down from a machine. The worker was driven to the emergency room.	No Dispatch			NEW BUILDING	520135675-01-NB	Worker Fell	MACY'S RETAIL HOLDINGS, INC.	AURORA CONTRACTORS INC
4/13/2018	Bronx	2044	WESTCHESTER AVENUE	0	1 The Project Manager at the site reported that a masonry worker was laying cinderblocks when he fell off a supported scaleful that was approximately three feet in height. The worker landed on his back and appeared to be in stable condition, but release to talk to aryone until an ambulance arrived. The worker was taken to Jacobi Medical Center. A DOB inspector responded and visited Medical Center. A DOB inspector responded and visited in the control of	No Action Necessary	NA .		NB	220152572	Worker Fell	HP WESTCHESTER MEWS HOUSING DE	Procids Construction Corp
4/13/2018	Manhattan	20	BROAD STREET	0	The Site Safety Manager reported that a worker was pushing a mini-container through a wall opening when he pinched his pinky finger. The worker left the site to see a doctor for treatment.	No Dispatch					Other Construction Related Incidents	NY STOCK EXCHANGE BLDG. CO.	
4/13/2018	Manhattan	701	7 AVENUE	0		No Dispatch			ALTERATION TYPE 1	121324343-01-AL	Other Construction Related Incidents	701 SEVENTH PROPERTY OWNER LLC	CNY CONSTRUCTION LLC
4/14/2018	Brooklyn	50	COURT STREET	0	3 DOB's Emergency Response Team was informed that a sidewalk shed was in the process of being dismantled when a partial collapse occurred at the corner of Court Street and Jonalemon Street. Approximately twenty limitar feet of the sidewalk shed collapsed. Two pedestrians and one worker suffered non-tile threatening injuries and were sent to Lutheran Hospital. The remaining unaffected parts of the sidewalk shed were removed. The Department Of Transportation replaced the cross work light at the site. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard all persons and property affected by construction operations. A DOB Violation was sasses	ECB Violation	35323276P	041418CERCM01	Alt 3 - SH	321426774	Scaffold/Shed/Fence/Shoring/Installation	50 COURT STREET ASSOCIATES	NEW FORCE CONSTRUCTION CO
4/17/2018	Manhattan	130	EAST 82 STREET	0	The Site Safety Manager reported that a worker accidentally ran a screw into his hand while screwing screws during duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	134 EAST 82 LLC	
4/17/2018	Brooklyn	856	WASHINGTON AVENUE	0	drilling a core hole in a deck slab when the drill kicked back and the base of the drill hit him on the side of his face. The worker was alert. The worker went to a	No Dispatch					Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
					hospital by ambulance.		Page 15 of 39						



ncident Date	la	Address Number	la	Forefittee Industry	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	Brooklyn	63	FLUSHING AVENUE	Patalities injuries	The Site Safety Manager reported that a worker slipped while going down the stairs. There were no witnesses to		ECB Violation numbers	DOB Violation Numbers	Permit	Permit No	Other Construction Related Incidents	NYC DSBS	Contractor Name
					the worker slipping, and the stairs were free of debris. An ambulance was called. The worker was okay, but walked to the ambulance when the ambulance arrived at the site and went to a hospital.	:							
	Brooklyn	1900	PARK PLACE	0	1 The Site Safety Manager reported that a worker strained his lower back while picking up a cement block. An ambulance was called.						Other Construction Related Incidents	HABITAT FOR HUMANITY LATENT TH	
4/18/2018	Brooklyn	25	EAST 19 STREET	0	1 The Site Safety Manager reported that a worker was passing an I-Beam down from a sidewalk shed when he lost his footing and fell about sixteen feet to the ground. The worker was wearing a harness that as not attached to anything. The worker was found awake and speaking and was taken to a hospital. An ECB Violation was issued for a failure to safeguard persons and property.	ECB Violation	35323790Н		Alt	340452520	Worker Fell	EBE HOLDING LLC	CS Bridge Corp
					issued for a failure to safeguard persons and property.								
4/18/2018	Manhattan	220	CENTRAL PARK SOUTH	0	The Site Safety Manager reported that a worker cut his finger when another worker closed a door on his hand by accident. A co-worker took the injured worker to a hospital.	No Dispatch					Other Construction Related Incidents	VNO 225 WEST 58TH STREET LLC	
4/18/2018	Queens	71-17	ROOSEVELT AVENUE	0	The Site Safety Manager reported that a worker sprained his back while carrying steel form. The worker went to a hospital by ambulance for observation.	No Dispatch					Other Construction Related Incidents	ROOSEVELT PARC LLC	
4/18/2018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker hurt his shoulder when he picked up a bundle of threaded rods. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
4/19/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker was conducting a survey and was wearing proper footwear when he stepped onto a nail that punctured his foot. The worker went to urgent care for a tetanus shot.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
4/19/2018	Manhattan	70	VESTRY STREET	0	The Site Safety Manager reported that a worker was installing 3' X 6' stone at the base of a building when his knee gave out, causing the worker to fall onto his knee. An ambulance was called.	No Dispatch					Other Construction Related Incidents	BRIDGE LAND VESTRY LLC	
4/19/2018	Manhattan	112	WEST 25 STREET	0	The Site Safety Manager reported that a subcontractor was carrying a door from a truck when the door fell and leaned on the subcontractor's right knee. The worker did not suffer a visible injury, but was in pain. An ambulance transported the worker to a hospital for a check up.				NEW BUILDING	121187214	Material Fell	LAM GEN 25 LLC	FLINTLOCK CONSTR SVCS INC
4/19/2018	Brooklyn	422	FULTON STREET	0	The Site Safety Manager reported that a worker was performing demolition work on the roof of a building when he felt pain in his back while lifting a barrel. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
4/19/2018	Bronx	545	EAST 166 STREET	1	0 The New York City Police Department reported that a worker was hit by a hoist. A worker was on the eight floor securing a piece of wingwall when he stepped up onto a bucket to look over the gate while trying to securing plywood. The hoist was on the floor above the worker and the hoist came down at the same time that the worker was learning over the gate. The worker was struck in the head and succumbed to his injuries. An Aggravated Level 2 ECB Violation was issued for the unsafe or improper use of hoist equipment.	ECB Violation	38259262J	042018E2607B01			Mechanical Construction Equipment	545 E. 166TH STREET HDFC	
4/20/2018	Manhattan	45	PARK PLACE	0	The Site Safety Manager reported that a carpenter foreman was securing a formwork panel for the shear wall and was repositioning his retractable device with both hooks in one anchor point when the insert gave way, causing the foreman to fall about ten feet backwards. The foreman was taken to a hospital.	ECB Violation	35326676H		NEW BUILDING	121185635	Worker Fell	PARK PLACE PARTNERS DEVELOPMEN	GILBANE RESIDENTIAL CONST
4/20/2018	Manhattan	560	WEST 33 STREET	0	The Site Safety Manager reported that a worker was climbing up a baker's scaffold when he lost his grip on the second rung of the ladder and fell about two feet.  I would be seen the seen that the incident occurred due to a worker's error.				NB	1211192618	Worker Fell	ERY NORTH TOWER RHC TENANT LLC	Roger & Sons Conctrete Inc
4/23/2018	Manhattan	400	WEST 61 STREET	0	1 The Site Salety Manager reported that at a thrity eight story new building under construction, a plumber was placing a pipe into hangers when the plumber fell off of a ladder. There were no witnesses to the height of the fall, and the plumber claimed to have fallen approximately between five and seven feet. The plumber was found alert, awake, and complaining of pain in his hip. The plumber was taken to St. Luke's Hospital by ambulance. A DOB imspector responded and visited the site and determined that there was no enforcement action necessary, as the fall occurred as the result of a worker's error.	No Action Necessary			121193181	NB	Worker Fell	RCB1 NOMINEE LLC	TISHMAN CONSTRUCTION CORP
4/23/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker on the first floor bumped his knee on a reshore tripod. The worker went to a City M.D.						Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
4/24/2018	Brooklyn	540	FULTON STREET	0	The Site Safety Manager reported that an iron worker pinched his finger while unloading steel rebar from a	No Dispatch					Other Construction Related Incidents	540 FULTON ASSOCIATES	



cident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
26/2018	Manhattan	461	WEST 34 STREET	0	The Site Safety Manager reported that a worker was on the twenty eighth floor of a twenty nier story new building and was cutting sheetock and metal stud for electrical work when he suffered a cut to his hand. A reciprocal balea jammed and the worker's hand got caught. The worker was found awake and alert and was taken to a nearby hospital.			Jos Tollion Militers	NB	121237009	Other Construction Related Incidents	34-10 DEVELOPMENT, LLC	ATRIA BUILDERS LLC
6/2018	Manhattan	225	BOWERY	0	It was reported that there were workers that were moving materials on the roof. When the workers moved a metal piece together, one of the workers right hand got caught in the pinch point. The worker suffered a scrape to his right hand. An ambulance was called to the site. The worker received stathces at Mount Sinai	No Dispatch				121862751	Worker Fell	VNAA BOWERY LLC	AEH-VSLV, LLC
5/2018	Manhattan	22	NORTH LOOP ROAD	0	Hospital.  1 The Site Safety Manager reported that a worker hit his left hand with a hammer. The worker went to urgent care	No Dispatch					Other Construction Related Incidents		
/2018	Manhattan	2	PARK PLACE	0	The Site Safety Manager reported that at a fifty seven story building that was under construction, a worker was cutting metal with a grinder when he cut his left shin. The worker was conscious and alert and walked to New York Presbyterian Hospital.					121290085	Other Construction Related Incidents	NOT ON FILE	AHEARN-HOLTZMAN, INC
/2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was coming down the stairs on a scaffold when he slid down the stair riser. The worker went to a City M.D.	No Dispatch					Worker Fell	95TH AND THIRD LLC	
6/2018	Brooklyn	1	CLINTON STREET	0	The Site Safety Manager reported that during concrete operations, a laborer was removing concrete key when his finger got scratched between rebar. The worker was working alone and scratched this finger while reaching into formwork. The worker want to a City M.D. and returned to work in two days.	No Dispatch			NB	321197478	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
/2018	Queens	147-40	ARCHER AVENUE	0	The Site Safety Manager reported that a worker struck his left thumb with a hammer while hammering a nail. The worker took himself to a City M.D.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
V2018	Brooklyn	109	2 AVENUE	0	The Construction Superintendent reported that a worker was shaking out steel at the street level when he pinched his finger between a two by four and a steel beam. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	THE SALVATION ARMY	
2018	Manhattan	1069	3 AVENUE	0	1 The Site Safety Manager reported that a pedestrian went over a ramp in front of the site, slipped/tripped on damaged mesh, and fell. The pedestrian suffered an injury to her left ellow and was taken to a hospital. A notation of the site of the	ECB Violation	35318046N				Other Construction Related Incidents	63RD & 3RD NYC LLC	
2018	Manhattan	130	WILLIAM STREET	0	The Site Salety Manager reported that a worker was attempting to help a carperter when he accidentally walked into the swing radius of a harmer and pot hit in walked into the swing radius of a harmer and pot hit in New York Presbyterian Hospital and was in stable condition. A DOB inspector responded and visited the site and determined that no enforcement action was necessary, as the incident occurred as a result of a worker's error.	No Action Necessary			NB	121192903	Other Construction Related Incidents		GILBANE RESIDENTIAL CONST
0/2018	Manhattan	425	PARK AVENUE	0	1 A DOB inspector reported that masons were finishing concrete pouring pads on the sixteenth floor when a worker that was working with the masons removed the mode that was working with the masons removed the mode of the sixteenth floor. The finishing that the suffered a cut to his ear and complained of head and nock pain. The worker was taken to Cornell University hospital for observation. Two CEB Violations were issued for there being no design drawings for floor openings present and for the failure to maintain safety operations. Two partial Stop Work Orders, (PSWO) were issued on all work within the feet of all floor coverings or all floors and for the floor coverings being not properly secured. Two DOB Violations were also issued. A Mearia and Methods for the installation of floor coverings must be provided.	ECB Violation	35326639N / 37P	043018BS06GD01/02			Worker Fell	T-C 425 PARK AVENUE, LLC	
/2018	Manhattan	540	WEST 53 STREET	0	The Site Safety Manager reported that a worker suffered     a cut finger. An ambulance was called	No Dispatch			NEW BUILDING	121191968-01-NB	Other Construction Related Incidents	CLINTON HOUSING DEVELOPMENT	MEGA CONTRACTING GP LLC
/2018	Manhattan	390	MADISON AVENUE	0	a cut finger. An ambulance was called.  The Site Safety Manager reported that a worker on the first floor stepped up on a few concrete masonry unit blocks when he fell approximately three feet off of the blocks and landed on a metal plate. EMS was called and transported the worker to a hospital.	No Dispatch					Worker Fell	COMPTROLLER OF NY STATE	
2018	Manhattan	222	EAST 41 STREET	0	The Site Safety Manager reported that a worker was installing metal trim when a cut piece fell down and lacerated his wrist. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
5/2/2018	Brooklyn	1277	EAST 14 STREET	0		No Dispatch	250 Yokkidi Kumbub	DOD VIOLATON NAMESCO		T CHILLE NO	Other Construction Related Incidents	1277 HOLDINGS LLC	Contactor Name
5/2/2018	Brooklyn	63	FLUSHING AVENUE	0	The Site Safety Manager reported that a worker was walking back from a coffee truck when he tripped, felt, and hit his head. The worker was found conscious and alert. An ambulance was called. A DOB inspector responded to the incident and visited the site and found no evidence of debris or tripping hazards, as well as no violating conditions. No enforcement action was necessary.	No Action Necessary			NB	321190563	Other Construction Related Incidents	NYC DSBS	GILBANE BUILDING COMPANY
5/2/2018	Manhattan	10	VANDERBILT AVENUE	0	1 The Site Safety Manager reported that a latherer was coming down from a rebar cage when he missed sist assistep, lell backwards, and hurt his ankle. The worker went to a hospital by ambulance. It was reported that the worker suffered a broken safe, A DOB inspector responded and visited the site and reported that the worker misreped during a rebar operation, and that the operation was proceeding according to the site plan. No enforcement action was deemed necessary.	1					Worker Fell	ONE VANDERBILT OWNER LLC	
5/2/2018	Manhattan	320	EAST 43 STREET	0	The Site Safety Manager reported that a worker was cleaning near the dumpster in the basement C-Level area when he hit his lower lego na dumpster. The worker was cut, but the bleeding was stopped. The worker does not know how he hurt himself. An ambulance was called.	No Dispatch					Other Construction Related Incidents	FORD FOUNDATION	
5/3/2018	Brooklyn	10	HURON STREET	0	The Site Safety Manager reported that a worker cut the skin of his finger on a table saw. The worker went to a hosoital with a co-worker.	No Dispatch					Other Construction Related Incidents	10 HURON FS CONDO LLC	
5/4/2018	Staten Island	546	GULF AVENUE	0		No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
5/4/2018	Queens	36-18	MAIN STREET	0	The Site Safety Manager reported that a worker was coming down off of a ladder when he lost his balance and grabbed onto a metal stud, causing a cut to two of his fingers. The worker went to urgent care.	No Dispatch					Worker Fell	134-22 35TH AVE., LLC	
5/4/2018	Manhattan	40	10 AVENUE	0	The Site Safety Manager reported that a worker sliped on rebar and hurt his wrist. The worker went to a City     M D.	No Dispatch					Other Construction Related Incidents	40-56 TENTH OWNER LLC	
5/4/2018	Manhattan	308	WEST 133 STREET	0	1 The Site Safety Manager reported that a worker was causiling a window when he fell from a baker scalled and burt six flow of the fell from a baker scalled and burt six flow. The fell from the scalled and the scalled scalled the scalled scalled A DOB inspector responded and visited the site and reported that the worker was not tied off when he fell. Two ECB Violations were issued for a failure to safeguard and for a failure to provide a four hour user training card. A partial Stop Work Order was issued on baker scaffolds until a Means and Methods is provided.	ECB Violation	35323933X, 35323934H		NB	122620333	Worker Feil	308 WEST 133RD STREET LLC	Happy Living Development
5/4/2018	Brooklyn	810	FULTON STREET	0	2 The Site Safety Manager reported that two workers were trying to install a pipe on top of a baker scafflold when both of the workers learned towards the same side of the same size of the same		35323694H,35323695J		NB	320597083	Worker Feil	GREENPOINT-GOLDMAN CORP.	Bradway Construction
5/4/2018	Brooklyn	63	FLUSHING AVENUE	0	1 The Site Safety Manager reported that a worker was unloading a pallet of glass that was approximately 2' X 8 when the pallet of glass the down or not him and pind when the pallet of glass the down or not him and pind him against the wall of the furch. The worker went to a hospital by ambulance. A DOB inspector responded and visited the site and issued an Aggravated Level 2 ECB Violation for a failure to safeguard, as there was not for the previous delivery operations that happened at the site. A partial Slop Wirk Crofer was issued on all deliveries. A Means and Methods for safe delivery operations and Tool Box Talks must be provided.		35318496K	050418BS02JJ01			Material Fell	NYC DSBS	
5/4/2018	Brooklyn	138	WILLOUGHBY STREET	0	The Site Safety Manager reported that a worker slipped on rebar and cut his right thumb. The worker walked to the ER.	No Dispatch					Other Construction Related Incidents	NYC HPD	
5/7/2018	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a welder was performing Support Of Excavation (SOE) work when he picked up a steel plate that was 12 X 12 and 38 thick when he injured his back. A co-worker took the worker to a City MLD, where a physician recommended inspector responded to the incident and visited the site and reported that there were no unsafe conditions found and that all of the workers at the site had ten hour OSHA cards. No enforcement action was deemed necessary.				FO	220151868	Worker Fell	COMUNILIFE LA CENTRAL HOUSING	Mountco Constrcution & development
							Page 18 of 39						



ncident Date	Borough	Address Numb		Fatalities Injuries		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
018	Brooklyn	2085	ROCKAWAY PARKWAY	0	1 The Construction Superintendent reported that a worker	No Dispatch			ALTERATION TYPE 3	340451308-01-EQ-SH	Worker Fell	NYC HOUSING AUTHORITY	SKYWORX CONTRACTING INC
					from the sidewalk shed company fell four feet while descencing from a baker scaffold. An ambulance took								
					the worker to a hospital.								
	Brooklyn	814	BEDFORD AVENUE	0	The New York City Emergency Management     Department and the New York City Fire Department	ECB Violation	35327578Z				Worker Fell	814 PARK LLC	
					reported that a worker was stripping concrete form work								
					for the first floor deck when the worker fell approximately								
					fifteen feet into the cellar and landed on capped rebar.								
					The worker was taken to a hospital and was accompanied by another worker. The injured worker did								
					not suffer any life-threatening injuries. An ECB Violation								
					for the failure to maintain safe operations was issued. A								
					full Stop Work Order (FSWO) was also issued. Additional safety violations will be issued.								
18	Queens	24-02	49 AVENUE	0	The Site Safety Manager reported that a worker at the fourth floor level was struck by duct work that was	ECB Violation	35326893Y	050718BS02DH01	ALT1	421518566	Worker Fell	LIC 73 OWNER, LLC	UNITY CONSTRUCTION GROU
					approximately ten feet high while on a ladder that was								
					approximately eight feet high. The duct work had came								
					loose, swung down, and struck the worker, which caused him to fall off of the ladder. The worker suffered								
					a broken leg and was taken to a nearby hospital. A DOB								
					inspector responded and visited the site and issued an								
					ECB Violation for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also								
					issued.								
040	Manhattan	250	BRADHURST AVENUE		4 The Cite Celeb Manager seconded that a	No Discostole					Other Construction Related Incidents	MSBGC-NYC SUPPORT CORPORATION	
018	mannatan	250	DRAUHURST AVENUE	0	1 The Site Safety Manager reported that a worker cut his finger on a table saw while cutting zinc clips for a façade						Other Construction Related incidents	MODOC-NYC SUPPORT CORPORATION	
					connection. The worker went to a hospital by ambulance to receive stitches on his finger.								
018	Brooklyn	535	4 AVENUE		The Site Safety Manager reported that a hoist mechanic	No Dispatch					Other Construction Related Incidents	XYZ PROPERTIES INC	
.010	DiouxiyII	535	4 AVENUE	0	lacerated his finger while cutting a piece of plastic away	NO DISPAICH					Outer Construction Related incidents	ATZ PROPERTIES INC	
					from a hoist. A co-worker took him to a hospital.								
018	Brooklyn	11	HOYT STREET	0	The Site Safety Manager reported that a worker was working on a rebar wall when he was struck in the neck	ECB Violation	35331175X				Other Construction Related Incidents	11 HOYT PROPERTY OWNER, L.P.	
					by dislodged shoring. A DOB inspector responded and								
					visited the site and reported that reshores were installed								
					contrary to the approved plan. An ECB Violation and a								
					were issued.								
018	Manhattan	115	DELANCEY STREET	0	The Site Safety Manager reported that at a twenty six story new building under construction, a worker was	No Dispatch			NB	121191646	Other Construction Related Incidents		T.G. NICKEL & ASSOCIATES
					coming back on site when he stepped on loose concrete								
					masonry and turned his ankle. The worker was found								
					alert and awake. The on-site medic issued ice for on-								
					site treatment and the worker went to a nearby urgent care center to receive further treatment.								
					care contains reserve rainer accument.								
2018	Manhattan	118	FULTON STREET	0	The Site Safety Manager reported that a worker jammed his finger while drilling into concrete. The worker walked	No Dispatch			NEW BUILDING	121333440-01-NB	Other Construction Related Incidents	CP V TS FULTON OWNER, LLC	RNC INDUSTRIES LLC
					to the emergency room.								
2018	Manhattan	560	WEST 33 STREET	0	was walking down stairs when he hurt his ankle on	No Dispatch					Other Construction Related Incidents	ERY NORTH TOWER RHC TENANT LLC	
					permanent stairs. An ambulance was called.								
/2018	Queens	54-17	101 STREET	0	2 New York City Emergency Management reported that	ECB Violation	35313352Z 35313353K				Other Construction Related Incidents	HANAC CORONA HOUSING DEV. FUND	
					two workers that were working on wires on the bulkhead when they experienced electric shocks. The workers								
					were able to make it down from the bulkhead and were								
					transported to a hospital. A DOB inspector responded to								
					the incident and visited the site and issued two ECB								
					Violations for the equipment ground not being provided and for the exposed wires at the bulkhead area not								
					being properly terminated, secure, and protected around								
					the HVAC air handler unit. A partial Stop Work Order (PSWO) was also issued for electrical work.								
					C 2 Of this also losses for electrical work.								
2018	Manhattan	100	EAST10 STREET		The Site Safety Coordinator reported that a worker was	No Astion Massa			ND	121193476	Other Construction Related Incidents		CCNY CONSTRUCTION INC
2018	warnatan	80	EASTIU STREET	0	moving pallets of concrete block around when some of	INU ACTION Necessary			INB	12/1934/6	Outer Construction Related incidents		CONT CONSTRUCTION INC
					the concrete block fell off and struck the worker's right								
					leg. An ambulance was called and the worker went to a hospital for treatment. A DOB inspector responded and								
					visited the site and reported that the worker pulled the								
					stationary part of the pallet jack while pulling the								
					concrete block onto himself. It was determined that this incident occurred as the result of a worker's error, and								
					that no enforcement action was necessary.								
/2018	Manhattan	7	WEST 57 STREET	0		No Dispatch					Other Construction Related Incidents	7 WEST 57TH STREET REALTY COMP	
					discomfort in his shoulder during stripping operations.  The worker took a cab to a clinic on his own.								
2018	Manhattan	515	WEST 36 STREET	0		ECB Violation	35331118J				Other Construction Related Incidents	FIRST ST MARKS LLC	
					pushing a cart when he tripped on planks that were								
2010					covering a hole. The worker suffered a cut to his right								
2010													
2010					hand and went to a hospital. A DOB inspector responded to the incident and visited the site and issued								
.010					responded to the incident and visited the site and issued an ECB Violation for the improper covering of holes.								



ident Date	Borough	Address Numbe		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
)/2018	Manhattan	424	EAST 34 STREET	0	The Site Safety Manager reported that a tapper tried to move an "A"-Frame with masonite on it out of his way by himself when he tipped the "A"-Frame and was hit in the right shin by both the "A"-Frame and the masonite. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NYU HOSPITALS CENTER	
2018	Brooklyn	8	NEVINS STREET	0	The Site Safety Manager repoted that a worker was stripping form work on the eighteenth floor when a post fell floward and in him in the back. The worker experienced back pain and an ambulance was called. A DOB inspector responded and visited the site and reported that another worker had leaned a stripping post against a wall instead of stacking the post and the post slid from an upright position and hit the injured worker. An ECB Volation was sized for a failure to institute/foliov safety measures for stripping operations. A DOB Violation was also issued.	ECB Violation	35326856P	0510188\$02,101			Material Fell	NEVINS STREET OWNER LLC	
2018	Bronx	1410	STORY AVENUE	0	A DOB inspector reported that a worker was sitting on top of a beam setting piests on the second floor of a new building. He was setting piests and he all pest anded a joist when the signal man signalled to the crane operator to hoist up with set clicksers (no load) on the hook. While hoisting up, one of the chokers or negot me to piest and up jetcked it up. The worker who had landed the joist timed to get out of the way from the joist, but lost his balance and fell two stories to the ground. The worker was host bed off, other workers at the site reported that the injured worker was bleeding from the mouth and was experiencing severe pain in his legs, but was conscious. The Hotel Kaethen Gypearfor (H. Mo.) at his site stated that he was standing next to the crane operator's cab as of the time of the incident and was given the okay to hoist up via radio. The lift director's logs were filled out on where the site of the host post with the higher downker. Two CCB Violations for a failure to safeguard were issued to the General Contractor and the crane operator. A full Stop Work Code (FSWC) was issued or there being no Construction Superintendent on site as of the time of insperition, and the site of the state of the contractor and the crane operator. A full Stop Work Code (FSWC) was issued or there being no Construction Superintendent on site as of the time of insperintendent on site as of the time of construction Superintendent on site as of the time of construction Superintendent on site as of the time of construction Superintendent on site as of the time of construction Superintendent on		35327286R 35327285P	051018BS09VP01,02			Worker Fell	BR-2012 REALTY LLC	
018	Staten Island	2655	RICHMOND AVENUE	0	The Site Safety Manager reported that a worker cut his right thumb while installing duct work. The worker went to urgent care. An ambulance was not called.	No Dispatch					Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	
018	Manhattan	553	WEST 30 STREET	0	The Site Safety Manager reported that a worker was using a grinder and suffered a cut to his right leg when the grinder kicked back. The worker was taken to a hospital by an ambulance.	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
018	Manhattan	425	PARK AVENUE	0	The Site Safety Manager reported that a worker cut his finger while using a band saw and suffered a minor gash to his finger. An ambulance was called.	No Dispatch					Other Construction Related Incidents	T-C 425 PARK AVENUE, LLC	
2018	Manhattan	357	EAST 57 STREET	0	A DOB inspector reported that façade work was underway at exposure floor on the sixteenth floor when a section of brick weneer disologed and fell onto the sixteenth sixty was set of the sixty with the sixty of th	ECB Violation	35245643J	051118CERJM01	ALTERATION TYPE 2	123179951-01-EW-OT	Material Fell	357 EAST 57 STREET CONDOMINIUM	EDRAS GROUP CORP
018	Manhattan	305	WEST END AVENUE	0	The Construction Superintendent reported that an electrician was working on the emergency lighting of the seventh floor permanent stairs when he was hit in the head from a tape measure that fell from above. The electrician was taken to a hospital. A DOB inspector responded and visited the site and sissued an ECB Violation for the failure to maintain safe operations and a partial Stop Work Order (PSWO) for all work next to openings. The General Contractor is to provide a Means and Methods and a Toolbox Talk.	ECB Violation	35331190Y				Material Fell	305 WEST END PROPERTY, LLC	
018	Brooklyn	76	NORTH 6 TH STREET	0	The Construction Superintendent reported that a worker was cleaning a paint gun when his finger was injured by the pressure from the nozzle. The worker went home to see his doctor due to pain in his finger.	No Dispatch					Other Construction Related Incidents		
018	Manhattan	42	WEST 33 STREET	0	The Site Safety Manager reported that a worker twisted his knee on Saturday, May 12, 2018. This incident took place on May 12, 2018, but was reported on Monday, May 14, 2018. The worker walked himself to a hospital.	No Dispatch			NEW BUILDING	121186849-01-NB	Other Construction Related Incidents	38-46 WEST 33 STREET, LLC	CAULDWELL WINGATE CO LLC



cident Date	Borough	Address Number	Street	Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
12/2018	Manhattan	500	WEST 25 STREET	0	1 The Site Safety Manager reported that workers were removing material from the goale level at the leading edg when two pieces of caisson pilings that were approximately two feet long were cut in half. The pieces of caisson pilings fell approximately fifteen feet and struck a worker that was in the excuration pit in the leg. The worker went to a hospital. The status of the worker injuries is unknown. A DOB inspector responded and visited the site and issued four ECB Violations for the abscence of the boards at the guardralis, the prescence of inadequate vertical reating, the prescence of an inadequate quarted that was not constructed to code, and the prescence of inadequate housekeeping. A Violations were also issued. The contractor is to provide a Means and Methods and a Toolbox Talk for the safe continuation of work.	ECB Violation	35331326W26Y/27X/26H	051218BS04PK01/02/03/04			Other Construction Related Incidents	500 W25TH OWNER LLC	
4/2018	Brooklyn	211	72 STREET	0	The New York City Fire Department reported that a worker was walking on a scaffold on the second level when he tripped and hurt his knee. The worker was taken to an area hospital.	No Dispatch			A2 - ALTERATION TYPE 2	302579662	Worker Fell	DEPARTMENT OF EDUCATION	KG CONSTRUCTION SERVICES
14/2018	Brooklyn	7	WHIPPLE STREET	0	The Construction Superintendent reported that workers were installing Q-decking on the second floor when a worker fell from the second floor on the first floor deck. The worker was found conscious and was transported to Bellevue Hospital. Additional information regarding the injuries was not available. The Construction Superintendent was not on site as of the time that the incident occurred. An DOB inspector responded and visited the site and issued an ECB Violation to the General Contractor for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) was also issued.		35308771R	051418CNEDG01	Alt 1 / NB	321285275	Worker Fell	WHIPPLE PROPERTIES LLC	SUNSHINE CONSTRUSA INC
14/2018	Manhattan	150	FIFTH AVENUE	0	A DOB inspector reported that there were workers moving steel beams with an electric hoist through a sharthway for an alteration on a twelve story building. The sharthway for an alteration on a twelve story building. The dots the stacked. One of the workers was edigasting the stacked. One of the workers was edigasting the stack when he was struck by two onder workers that were putting steel in place. The struck worker got his right hand crusted between two beams and was taken to Beth Israel Hospital for treatment. An ECB Violation for a failure to safeguard was issued. A partial Stop Work Order (PSWO) was issued on all work in shrhway hoisting materials. A Means and Methods and a Toolbox Talk must be provided.		35331139H-FAIL TO SAFEGUARD.		ALT1	122700292	Other Construction Related Incidents	150 5TH AVENUE OFFICE LLC	METROPOLITAN BUILDING SER
5/2018	Manhattan	701	7 AVENUE	0	The Site Safety Manager reported that a worker was on the roof setback setting roof pavers when he stepped in a hole with the roof pavers that he was working on and hit his right shin. The worker was conscious and alert and walked to a City M.D. to be checked out.	No Dispatch			ALT1	121324343	Worker Fell	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
/2018	Manhattan	627	GREENWICH STREET	0	The Site Safety Manager reported that a plumber slipped off of the fourth step of a ladder that he was working on and suffered a sprained ankle. An ambulance was called.	No Dispatch					Worker Fell	627 GREENWICH OWNER LLC	
5/2018	Manhattan	500	WEST 23 STREET	0		ECB Violation	35326800X				Other Construction Related Incidents	NOT ON FILE	
5/2018	Manhattan	20	BROAD STREET	0	The Site Safety Manager reported that a worker tripped on debris and fell on his back. An ambulance was called, A DOB imspector responded and visited the site and reported that no enforcement action was necessary, as the incident occurred as the result of a worker sector. The worker was okay and was reported to have returned to work the following day.						Worker Fell	NY STOCK EXCHANGE BLDG. CO.	
(2018	Manhattan	100	EAST 104 STREET	0	2 The New York City Police Department reported that debris was falling from the building. A DOB inspector responded and visited the site and reported that at the fifteenth floor setback, sections of localition and plywood became separated due to high winds and fell to the street level along Park Avenue, striking two individuals. One of the individuals that was struck was taken to a local hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard. A DOB Violation and a full Stop Work Order (FSWO) were also issued.		35309489H	051518CNEGS02	NEW BUILDING	121192887-01-NB	Material Fell	TERRACE ON THE PARK LLC	GLENWOOD CONSTRUCTION



	Manhattan	Address Number	WALL STREET		setting up needle beams when a portion of screw jack- ell onto the worker when he bent down. The struck worker complained or lonck pain and left the site to visit his own doctor. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to maintain safe operations and a partial Stop Work Order (PSWO) on the use of all needle beams. A Mears and Methods and a Toolbox Talk must be provided. An additional ECB Violation will be assued for the inadiation of a pipe scaffold that was done contrary to the design plans.	ECB Violation	ECB Violation Numbers 35327019M	DOB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name MIP ONE WALL STREET ACQUISITIO	Contractor Name
5/15/2018	Brooklyn	626	SHEEPSHEAD BAY ROAD	0	The Project Manager reported that a painter was on a ladder on the third floor when he misused the ladder and slipped off. The worker fell approximately six fee and hurt his shoulder. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NEPTUNE SOUTH COMMERCIAL LLC	
5/15/2018	Brooklyn	416	KENT AVENUE	0	2 A DOB inspector reported that approximately 50°-0" interar feet of sidewalk shed dock and parapet deck enclosure had blown off of a sidewalk shed and onto the street, injuring two pedestrians. The two pedestrians were taken to a hospital. Their condition was unknown as of the time that they were taken to a hospital. The company that erected the sidewalk shed responded and visited the site to enrove the debris from the steet. An Aggravated Level 2 ECS Violation was issued for a Violation was so as the sidewalk shed responsed and Violation was so to sieued. A partial Step Work Order (PSWO) was issued on all crane and exterior operations, except for work to make safe the installation of a sidewalk shed.		35322610R	051518CERSM05	NEW BUILDING	320622616-01-NB	Material Fell	420 KENT AVENUE LLC	ZDG, LLC
5/15/2018	Bronx	1017	HOME STREET	0	1 The Construction Superintendent reported that a worker was plumbing up a metal stud wall when the stud wall left, hit a generator, and then bounced off the generator and landed on the worker's leg. An ambulance was called. A DOB inspector responded to the incident and visited the site and reported that safety measures were not in place for a bearing wall installation. An ECB Violation and a DOB Violation were issued, as well as a partial Stop Work Order (PSWV) on all bearing wall installations. A Means and Methods and safety measures for bearing wall installations must be provided		35327290J	051518BS03VP01			Material Fell	DREAMYARD 1017 HOME STREET HOU	
5/16/2018	Manhattan	44	UNION SQUARE EAST	0	A competent person at the site reported that a worker was removing a vertical shoring post when his finger got caught between the safety pin and the plate. The worker suffered a swollen finger and went to a hospital on his	t					Other Construction Related Incidents	READING TAMMANY OWNER LLC	
5/16/2018	Manhattan	76	11 AVENUE	0	own.  I The Site Salety Manager reported that a foreman was hanging an eight inch steel pipe when he lost control of he pipe. The foreman was then knocked off of a ladder by the pipe. An ambulance was called. A DOB inspector responed and wisted the site and reported that the anchor from which the pipe was to be hung from failed. An ECB Violation was issued for a failure to maintain safe operations.		35331136N				Other Construction Related Incidents	76 ELEVENTH AVENUE PROPERTY OW	
5/16/2018	Queens	45-07	COURT SQUARE	0	The Site Safety Coordinator reported that a worker was using a four inch grinder when the grinder kicked back and cut the worker's left arm. The handle and grinder guard were in place. The worker was conscious and awake and went to Mount Sinai Hospital for treatment.	No Dispatch			NB	420902410	Mechanical Construction Equipment	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
5/17/2018	Queens	2100	49 AVENUE	0	The Construction Superintendent reported that an electrician was re-adjusting a ladder when he fell approximately five feet off of the ladder. The worker complainted of back pain and was taken to Elmhurst Hospital. The worker was alert and awake.	No Dispatch			ALT1	420656686	Worker Fell	2100 49TH AVENUE OWNER, LLC	ARCHSTONE BUILDERS LLC
5/17/2018	Queens	101	PENNSYLVANIA AVE	0	The Construction Superintendent reported that while working on a seven story new building, a project manager picked up a sheet metal that cut his finger. The project manager went to urgent care.				NB	320622894	Other Construction Related Incidents		CAULDWELL WINGATE CO LLC
5/17/2018		112	EAST 11 STREET	0	1 The Site Safety Manager reported that a worker was coming down a gang ladder when he slipped on the third step of the ladder and fell there feet. The worker complained of back pain. An ambulance was called. A DOB inspector responded and visited the site and found no unsafe conditions present as of the time of inspection. No enforcement action was necessary.						Worker Fell	UD-DEV ASSOCIATES LLC	
5/17/2018	Brooklyn	138	WILLOUGHBY STREET	0	2 A DOB inspector reported that a signalman had landed a banded load on the top dock with a tower crane. The rigging was released after the load was landed, and the load shifted and started another worker that was carrying pieces of rebar. The worker tripped, fell, and hurt his antile. The worker was taken to a hospital for X- rays. The signalman suffered a cut to his finger from the banding after releasing the rigging and went to a City MD. for tradement. There were no witnesses to the worker failing. No enforcement action was necessary, as it was determined that the signalman suffered a cut due to a worker error.				CN	773/17	Worker Fell	NYC HPD	Trident General Contracting, GC lend lease



Marie														1.
	cident Date				Fatalities Injurie	s EOC Final Description		ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
	7/2018	Bronx	1903	WEST FARMS ROAD	٩	performing insulation work behind a stud wall when she	No Dispatch					Material Fell	SAMARITAN-COMPASS V HOUSING DE	
Marchane						pushed a stack of sheetrock that was leaning against a								
March   Marc						wall, which caused the boards to fall forward and hit her								
Part						in the leg. An ambulance was called.								
Part	2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	1 The Site Safety Manager reported that a worker cut his	No Dispatch					Other Construction Related Incidents	ATLANTIC 2644, LLC	
Part						finger on a piece of sheet metal. The worker went to								
Part														
	2018	Brooklyn	422	FULTON STREET	0	1 A DOB inspector reported that a crane was making a	No Action Necessary			CN	80/17	Mechanical Construction Equipment	NOT ON FILE	FJM- Ferro Inc
						street to the roof. The beam was rigged up and the								
						signal man gave the crane operator the signal to come								
						up with the load. The crane had litted the load								
March   Marc						an iron worker attemped to steady the load to keep the I								
Part						Beam from swaying. When the iron worker did this, he								
Part						stationary beam on the flatbed truck. When he did this.								
						the worker created a pinch point, and the moving load								
Property						struck the worker's leg and caused a cut. The worker								
Part						The DOB inspector found no violating conditions during								
Second   S						his inspection, as all of the workers at the site had the								
Part														
						had logs, and the signal man had his card. No								
						enforcement action was necessary.								
	2018	Brooklyn	578	COZINE AVENUE	0	1 A DOB inspector repored that a worker was performing	ECB Violation	35322901R 35322902Z	051818CERRJ03 051818CERRJ04	Abatement		Worker Fell	NYBC REALTY LLC	GSC Services Corp
						asbestos abatement work on the roof when he fell								
						was taken to Brookdale Hospital. The abatement work								
Part						was being performed as per the posted notice. Two								
Market   M						Aggravated Level 2 ECB Violations for a failure to safeguard were issued to the abatement company and								
						building owner. A partial Stop Work Order (PSWO) was								
Part						issued for all work at the roof level. The contractor at the	•							
Accordance   Acc						removal of material from the roof level.								
Market   M														
Market   M														
Manufacture	2018	Brooklyn	6	METROTECH	0	1 A New York City Police Officer reported that a plumber	No Action Necessary			PLUMBING	321562288	Mechanical Construction Equipment	NEW YORK UNIVERSITY	VITO M. GIACHETTI
Part						was working on a pipe on the fifth floor when the pipe								
Prince of the						ambulance was called. A DOB inspector responded to								
Marients   Washington   Washi						the incident and visited the site and determined that								
						there was no enforcement action necessary, as the job								
Marie						approved technical plans.								
Service Control and Control an														
In the first of the search of	2018	Manhattan	130	WILLIAM STREET	0	1 The Site Safety Manager reported that a ten feet long	ECB Violation	35331400N				Other Construction Related Incidents	130 WILLIAM STREET ASSOCIATES	
Part						piece of rebar that was standing vertically and was to be	'							
In the control of the						ground, hitting him in the side of his hard hat. The								
Market   Description and a production and a post of production of the Side Step Option 2 Annual Programme						worker went to a City M.D. A DOB inspector responded								
Design						failure to maintain safe operations, as well as a partial								
						Stop Work Order (PSWO) for all concrete operations.								
District    District						The General Contractor at the site is to provide a Means and Methods and a Tool Box Talk	•							
Section   Sect														
Section   Sect	2018	Bronx	2865	CRESTON AVENUE	0	The Site Safety Manager reported that a worker was	ECB Violation	35327296K, 35327297M, 98, 99X,353184OOR, 01Z				Worker Fell	10 MINERVA PLACE HOUSING DEVEL	
In Proposed, A Cold Register responsed and Authorise Model and Proposed Authorise Model Authorise M						putting up forms on a column when he fell about six to								
size and found that is a south fall as a local fall as						seven feet and injured his foot. The worker was sent to a hospital, A DOB inspector responded and visited the								
In continue to the Section of the						site and found that a hook that was holding form up was								
Comperison was issued, as well as a partial Stopy Work.  Other PANK AVENUE  1 The Sile Siderly Manager reported that as worker fell from No Diagnoch the boy of a formation of the institution of the specified of the institution of the inst						damaged, which may have possibly caused the worker								
Order (PSVV) for all concrete work. Additional ECP (Visible) and a vertical ECP (Visible) and the vertical ECP (Visible) in the recibility.  1 The Side Study Messager reported shall a vertical to the first force. The vertical vertical reported that the vertical verti														
related to the accident.    PARK AVENUE   0   The Site Selvey Manager reported that a worker fell from the late those. The hospited by ambidiance.   PARK AVENUE   0   TREMONT RENAISSANCE HOUSING DE   JOY CONSTRUCTION CORP						Order (PSWO) for all concrete work, Additional ECB								
18 Brox 4215 PARK AVENUE 0 1 The Sale Salety Manager reported that a worker fell from he boy of a horist thirt was stopped on the first floor. The worker attempted to a horist thirt was stopped on the first floor. The worker attempted to a horist thirt was stopped on the first floor. The worker attempted to a horist thirt was stopped on the first floor. The worker attempted to a horist warrange of the first floor. The worker attempted to a horist warrange of the first floor. The worker attempted to a horist warrange of the first floor. The first worker attempted to a stopped to a stopped to a first floor. The first worker attempted to a horist warrange and bumps place stopped to a first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to a horist warrange and bumps place the first floor. The first worker attempted to the first floor. The first worker attempted to a horist manuscript and the first floor. The first worker warrange warrange and bumps place the first floor. The first worker warrange warrange and bumps place the first floor. The first worker warrange w						Violations were also issued for infractions that were not								
Best of a host task was stopped on the first floor. The worker surfered minor in jumps and was transported to a longish by ambitation.						TOURS TO THE HIGHER.								
Best of a host task was stopped on the first floor. The worker surfered minor in jumps and was transported to a longish by ambitation.	2018	Bronx	4215	PARK AVENUE	0	1 The Site Safety Manager reported that a worker fell from	No Dispatch			NEW BLIII DING	220157700-01-NP	Worker Fell	TREMONT RENAISSANCE HOUSING DE	JOY CONSTRUCTION CORP
Nonpillar by ambulance   Nonpillar by ambula			4213	. THURST COL	, and a	the top of a hoist that was stopped on the first floor. The				TETT DOILDING	22010770001740			CONCINCOTION CONF
WEST 87 STREET  O 2 The New York City Police Department reported that two workers were in the process of installing a supported useful of when they slipped and fell from three frames of pipe scatellot. The voices suffered scarges and bumps to the hands and legs and were taken to St. Like's and visited the size and issued row Agrovated Level 2 ECB Violations. The first Violation was issued for the premoval or affection of the supported scaffold by the General Contractor before the inspector's arrival, which is the memory of experiment material, or workforce that is nettled to an incident. The second the Department OF buildings of the incident, as the incident was reported by the NYPD.  Of the Oueens  O 1 The Site Safety Manager reported that a worker was curling a metal stud when he out his hand. An						worker suffered minor injuries and was transported to a								
workers were in the process of installing a supported scaffold when the syspept and refl from three frames of pipe scaffold. The workers suffered scrapes and tumps to the hir hands and legs and were taken to SL Luk's Hospital. A DOB inspector responded to the incident and visited the site and issued both and signal and were taken and source the site and issued both and signal and were the site and issued both and signal and were the site and issued both and signal and were the site and issued both and signal and	2018	Manhattan	247	WEST 87 STREET	0	The New York City Police Department reported that two	ECB Violation	35324011Y - 35324012X		N/A		Worker Fell	KSB BROADWAY ASSOCIATES	Jerrick Associates Inc
iscaffold when they slipped and fell from three frames of pipes catifold. The workers suffeed scrapped and bumps to their hands and legs and were taken to St. Luke's Hospital. A DOB inspector responded to the incident and visited the sate and issued two Agravated Level 2 ECB Violations. The first violation was issued for the removal or alteration of the supported scartfold by the General Contractor before the inspector's arrival, which is the removal or department, structural material, or evidence that is related to a in incident. The second violation was issued for a failure to prompty routily the Department of Desafford with the prompty routily and the prompty routily and the prompty routily and the prompty routile and the prompty r	- 10		247		, i	workers were in the process of installing a supported	_ 55 1.0.0001	3111 0002-1012/		1471			Shorten	III
bother hands and legs and were taken to St. Luke's Hospital. A DOB inspector responded to the incident and visited the site and issued two Aggravated Level 2 ECB Violations. The first violation was issued for the removal or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department of Evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department of Evidence that is related to an incident, as the incident was reported by the NYFD.  30 Queens 30 0.2 39 AVENUE 0 1 The Site Safety Manager reported that a worker was coming a metal study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another events a study when he cut his band. An another event a study when he cut his band. An another event a study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band. An another event as study when he cut his band and another event as study when he cut his band and another event as study when he cut his band and another ev						scaffold when they slipped and fell from three frames of								
Hospital. A DOB inspector responded to the incident and visited the site and issued two Agrayarded Level 2 ECB Violation. The lint violation was issued for the lenroval or alteration of the supported Scaled by the lenroval or alteration of the supported Scaled by the lenroval or alteration of the supported Scaled by the lenroval of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department of Buildings of the incident, as the incident was reported by the NYPD.  18 Queens 30-02 39 AVENUE 0 1 The Stafety Manager reported that a worker was cutting a metal stud when he cut his hand. An						to their hands and legs and were taken to St. Luke's								
ECB Violations. The first violation was issued for the fremoval or alteration of the supported scaffold by the General Contractor before the inspector's arrival, which is the removal of agricultural naterial, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department Of Buildings of the incident, as the incident was reported by the NYPD.  Office Construction Related Incidents and the cut his hand. An analystope was called an expected of the cut his hand. An analystope was called an expected of the cut his hand. An analystope was called and the cut his hand and the cut his hand. An analystope was called and the cut his hand and the cut his hand. An analystope was called and the cut his hand and the cut his hand. An analystope was called the cut his h						Hospital. A DOB inspector responded to the incident								
removal or alteration of the supported scaffold by the General Contractor Destroe the inspector's arrival, which is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly nority the Department Of Buildings of the incident, as the incident was reported by the NYPD.  018 Queens 39-02 39-AVENUE 0 1 The Stafety Manager reported that a worker was curing a mail at will when he cut his hand. An						and visited the site and issued two Aggravated Level 2								
General Contractor before the inspector's arrival, which is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department Of Buildings of the incident, as the incident was reported by the NYPD.  On a 1 The Site Safety Manager reported that a worker was cutting a metal stud when he cut his hand. An anythere was called						removal or alteration of the supported scaffold by the								
is the removal of equipment, structural material, or evidence that is related to an incident. The second violation was issued for a failure to promptly notify the Department Of Bulldings of the incident was reported by the NYPD.  018 Queens 30-02 39 AVENUE 0 1 The Site Safety Manager reported that a worker was custing a metal stud when he cut his hand. An						General Contractor before the inspector's arrival, which								
violation was issued for a failure to promptly notify the Department Of Buildings of the incident, as the incident was reported by the NYPD.  Offer Construction Related incidents  Other Construction Related incidents						is the removal of equipment, structural material, or								
Department Of Buildings of the incident, as the incident was reported by the NYPD.  Other Construction Related Incidents						violation was issued for a failure to promptly notify the								
Queens 30-02 39 AVENUE 0 1 The Site Safety Manager reported that a worker was cutting a metal stud when he cut his hand. An ambitance was called						Department Of Buildings of the incident, as the incident								
cutting a metal stud when he cut this hand. An ambulance was called an ambulance was called						was reported by the NYPD.								
outing a metal stud when he out his hand. An ambiliance was called an instance was called														
outing a metal stud when he out his hand. An ambiliance was called an instance was called														
ambulance was called	018	Queens	30-02	39 AVENUE	0	1 The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	30-02 ASSOCIATES LLC	
						ambulance was called.		Page 23 of 39						



cident Date	Borough	Address Numbe	r Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
23/2018	Staten Island	149	PROVIDENCE STREET	0	1 The New York City Office Of Emergency Management reported that a worker fell from the structure, EMS transported the worker to a hospital. A DOB inspector responded to the incident and visited the site we ECS Violations for the failure to safeguard and for the failure to notify the Department Of Buildings of the incident. A full Stop Work Order (FSWO) was also issued.		35322804M/05Y	052318CERRJO1/02	ALT 1	520323212	Worker Fell	PERRI, ALFONSO	A. FONTANA & SONS LLC
V2018	Manhattan	76	11 AVENUE	0	1 The Site Safety Managor reported that a worker was building the walk-out for a lower cane and was standing, on the crane's ise-back beam when he slipped off of the beam and fell. The worker was wearing fall process	1					Worker Fell	76 ELEVENTH AVENUE PROPERTY OW	SBF Construction
3/2018	Marhattan	26	1 AVENUE	0	1 A New York City Police Officer reported that a worker fell approximately five stories or fifty feet from an unguaried section of pies scaffiold. The worker was in critical condition and was taken to Bellevue Hospital. A DOB inspector responded to the incident and veiting the state and reported that it could not be determined what and reported that it could not be determined what inspector interviewed claimed to have not seen or know about the incident. Four ECB Violations were issued for the failure to safeguard, for the presence of a superdesscaffold that was not built according to code and was missing guardrails, missing to boards, and was not full decked, for the absence of plans, drawings, and logs or site, and for the failure to provide a four hour supported scaffold user card upon request. A partial Stop Work Order (PSWO) was also issued.	,	35324057J, 35324059L, 35324059N, 35324080K		Alt	140761995	Worker Fell	DROBENKO NICHOLAS	Lime-Light Construction Co
4/2018	Brooklyn	2837	WEST 8 STREET	0	1 The Project Manager at the site reported that during the installation of concrete panel around a builchead, a panel cracked, refl, and caused an innor cut to a worker hands. The worker went to a clinic and then came back to the site on the following day. A DG inspector responded to the incident and visited the site and set in the site of	5					Material Fell	AISD CORP.	
2018	Brooklyn	41	BLUE SLIP	0	The Site Safety Manager reported that the driver of a concrete truck was washing out his truck when he hopped off of a ladder and turned his ankle. EMS was called and the worker was sent to a nearby hospital.	No Dispatch					Other Construction Related Incidents	BOP GREENPOINT F LLC	
4/2018	Brooklyn	420	EAST 21 STREET	0	1 The New York City Fire Department requested that an inspection please be performed due to a retaining wall collages. A DOB Inspector responded and visited the site and reported that the building owner was performing work on the retaining wall that was separating 420 and 412 East 21 Street when a section of the retaining wall hat was separating 420 and 412 East 21 Street when a section of the retaining wall hat was progroundarily twenty feet wide collapsed into the was proposed to the street of the street and compromised the stability of 412 East 211 Street's garage and driveway. During search operations, an FDNY freelighter suffered a minor injury and was transported to a local hospital. Two Aggravated Level 2 ECB Violations and two DOB Violations were issued at 220 East 21 Street for a failure to safeguard and for work being performed without a permit. A full Sop Work Order (FSWO) and a pariall Vactae Order were also issued at 420 East 21 Street. A DOB Violation and a full Vacate Order were issued the garage of 412 East 21 Street. (412 Garage East 21 Street).		35322725R, 35423726Z	052418CNESC04, 05, 052418CNE01SC			Other Construction Related Incidents	HOSSAIN, GOLAM	
1/2018	Brooklyn	84	CARLTON AVENUE	0	A competent person at the site reported that a worker was installing roof protection when the worker tripped or a piece of plywood and fell. The worker was sent to a hosoital for a check up.						Other Construction Related Incidents	NYC HOUSING AUTHORITY	
2018	Manhattan	233	WEST 125 STREET	0	The Site Safety Manager reported that a worker slipped while coming down from a ladder. The worker was taker to a hospital by EMS.	1			NEW BUILDING	121187447-01-NB	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
5/2018	Manhattan	24	2 AVENUE	0	The Site Safety Manager reported that a worker cut his arm with a sheetrock knife while cutting sheetrock. The worker went to a nearby urgent care facility to receive medical attention.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/25/2018	Queens	28-07	JACKSON AVENUE	0	A DOB inspector reported that there was a six man team for the meaning support columns when one of the columns when one of the columns was released the fore one of the workers had a hold of the column. The column struck this worker to the ground. The worker was wearing his Personal Protection Equipment (PPE) and was found alert and responsive. The worker did not suffer a serious injury, but was taken to a hospital by ambidunce as a precaution. Documentation was provided to show that the worker attended a pre-job meeting and that the worker was up to date with daily pre-tash harzard safety meetings that are designed to avoid such incidents. The inspector determined that no enforcement action was necessary and that the incident occurred as the result of a worker.	No Action Necessary			ALT I NB	420656873	Material Feii	LIC SITE B-1 OWNER, LL.C.	NEW LINE STRUCTURES & DEV
5/26/2018	Manhattan	217	WEST 57 STREET	1	O A DOB Professional Engineer (PE) reported that at a sixty-seven story new building that was under construction, a security guard was walking from the frost to the rear on the first floor of the building when an approximate 1 eV 8 £ 2,300 pound glass curtain wall panel with a supporting steel "A"-Frame toppled and prinned the security guard undermeth it. Several workers		35322614Y	052618CERSM01	ALT 1 NB	121328205	Material Fell	SMITELL SPONSOR LLC	LEND LEASE (US) CONSTRUCT
					litted the "A"-Frame and removed the pinned security guard. The security guard was taken to Mount Sinai Hospital, where he was later pronounced dead. A DOB inspector that was also at the side reported that the glass panel fell because it was accidentally hit by another worker that was trying to it in picce of HYAC metal duct that was in close proximity. A contributing factor to the glass panel fall was that the vertical side of the "A"- Frame that was supporting the panel was factor to the glass panel fall was that the vertical side of the "A"- Frame that was supporting the panel was factor to the Jacks panel so "A"-Frames were found to have been stored in an unsafe position. The on duty Site Safety Manager stated that he performed a daily safety inspection at the site at the start of the work day that morning. However, the did not fill out his safety big. A full Stop Work Order (FSWO) was issued, as well as an Aggravated Level 2 ECB Violation for a failure to safeguard. A DOB Violation was also issued.								
5/26/2018	Brooklyn	101	PENNSYLVANIA AVENUE	0	2 The New Yok City Fire Department requested that a structural stability inspection please be performed because a construction fence had partially collapsed. A DOB inspector responded to the incident and visited the site and reported that there was approximately 100 feet of construction fence that was made of water-filled jerney barriers and a four foot chain link fence that had fallen over onto a pedestrian waltway and injured two pedestrians. The two pedestrians were not transported by ENIS in receive off-site medical assistance. The YMO ECEV Moistons were issued or a failure to safeguard and for a defective job site fence. Two DOB Violations were seased.		35323583P, 35323584R	052518CERFC02 , 03	ALT 1NB	320622894	Material Fell	SPRINGER, JEAN E	CAULDWELL WINGATE CO LLC
5/29/2018	Bronx	220	EAST 178 STREET	0	1 The Site Safety Coordinator reported that while working on a twelve story New Building that was at the Support of Exceeding COSC stage, a hose from the fire hydern of Exceeding COSC stage, a hose from the fire hydern temperature of the Safety Sa	ECB Violation	35332113P 36332114R		New Building	220546620	Excavation/Soil Work	GRAND APTS HOUSING DEVELOPMENT	M. Melnick & Company Inc
5/29/2018	Manhattan	15	BRIDGE PARK DRIVE	0	The Site Safety Manager reported that a worker was unloading an air handler when he lacerated his middle finger on a sharp edge of the air handler. The worker went to a local clinic.	No Dispatch					Other Construction Related Incidents		
5/29/2018	Manhattan	151	MAIDEN LANE	0	went to a local crinic.  1 The Siles Saley Manager reported that workers were moving a refingiration unt when it toppled over onto one of the workers. The injured worker was taken to a hospital. A DOB inspector responded to the incident and visited the site and issued an ECE Violation for the incident workers and issued an ECE Violation for the siles of the Committee of the Com		35336652H				Other Construction Related Incidents	151 MAIDEN LLC	



Incident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/29/2018	Queens	45-57	UNION STREET	o o	The Site Safety Manager reported that a worker was on baker scaffold at the second floor when the worker fell from the scaffold. The worker was found conscious, but complainted of pain in his shoulder and leg. The worker walked to a nearby hospital. A ODG inspector responded to the incident and visited the site and issue one ECB Violation for a scaffold platform that was not fully planked and for the presence of planks that were not tied down. A partial Stop Work Order (PSWO) for	ECB Violation	35323972Z - 35323973K	DOS VIOLATION RUITIDENS	NB	402898959	Worker Fell	DEPARTMENT OF EDUCATION	Leon D. Dematteis Construction
/29/2018	Queens	45-57	UNION STREET	0	the use of a supported scaffold was also issued.  1 The Site Safety Manager reported that an electrician	No Dispatch					Worker Fell	DEPARTMENT OF EDUCATION	
					tripped while walking and suffered an injury to his rlbs.  The worker went to urgent care.								
/30/2018	Brooklyn	2550	3 AVENUE	0	The Site Safety Coordinator reported that a worker's for came into contact with a piece of pipe that was in a pile of garbage that was to be picked up. The worker suffered a foot laceration and was sent to a hospital.	t No Dispatch					Other Construction Related Incidents		
/31/2018	Brooklyn	107	COLUMBIA HEIGHTS	0	1 The Site Safety Coordinator reported that four workers were carrying heavy mechanical equipment down the stairs when equipment fell on one of the workers. The worker was sent to a hospital for a check up. A DOB inspector responded to the incident and visited the site and issued an ICBV loitation for the failure to maintain safe operations and a partial Stop Work Order (PSWO) on the handling of heavy material. The General Contractor is to provide a fileans and Methods.		35326663N				Other Construction Related Incidents	CLIPPER 107 CH LLC	
/31/2018	Manhattan	360	EAST 89 STREET	0	1 A DOB inspector reported that a worker was sorting and moving glass window panels when one of the panels shifted and hit the worker in the leg. The worker was taken to a hospital by ambulance for evaluation. An EV (Violation and a partial Elop Work Order (PSWO) was issued for the failure to maintain safety measures, at the worker was injured due to improper material handling. The General Contractor is to provide a Means and Methods for safe material handling in order to prevent future incidents.	3	35318415.J		NEW BUILDING	121186242	Material Fell	1711 LLC	RYDER CONSTRUCTION INC
31/2018	Queens	51-35	REEDER STREET	0	The Construction Superintendent reported that a worker strained his back while lifting a crate onto a dolly. An ambulance was called and the worker was transported to a hospital.	No Dispatch			NEW BUILDING	420812446-01-NB	Worker Fell	85-15 QUEENS BLVD. REALTY, LLC	STRUCTURAL LAND MANAGEMEN
5/31/2018	Queens	546	GULF AVENUE	0	The Site Safety Manager reported that a worker cut his finger while using a box cutter. The worker went to a	No Dispatch					Other Construction Related Incidents		
/1/2018	Manhattan	701	7 AVENUE	0	I The Site Safety Manager reported that two workers wer loading glass panels that were approximately 5 X 3 ont a cart when the glass came into contact with a metal part of the cart, which caused the glass to break into pieces. One of the workers suffered a minor laceration to his left hand. The injured worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	20 TSQ GROUNDCO LLC	
5/1/2018	Manhattan	49	CHAMBERS STREET	0	1 The Site Safety Manager reported that a worker was trying to move a doily that was carrying a machine motor for an extent relevator up the ramp of the loading dock when he lost his balance and the machine motor tipped over, causing the worker to fall face down. The worker suffered cuts and bruises to the face and was taken to hospital for treatment. A DOB inspector responded to the incident and visited the site and issued an ECB Violation and a partial Slop Work Order (PSWO) to stop all deliveries and material handling. The General Contractor at the site is to provide a Means and Methods for safe operation.		35335925Y		ALTERATION 1	121186821	Material Fell	49-51 CHAMBERS LLC	NY DEVELOPERS & MANAGEMEN
/1/2018	Brooklyn	18	SPENCER STREET	0	The Site Safety Manager reported that a worker was working on a twelve story new building and suffered a cut to his arm while carrying 2 X 4's and sharp edge metal track material. The worker went to a nearby doctor treatment and received a few stitches.						Other Construction Related Incidents	LL 18 SPENCER HOLDINGS LLC	
/4/2018	Manhattan	10	VANDERBUILT AVE	0	The Site Safety Manager reported that an iron worker was climbing down the stairs when he slipped and fell about three feet. The worker complained of a sprained back. An ambulance was called.	No Dispatch					Worker Fell		
/4/2018	Manhattan	108	LEONARD STREET	0	1 The Site Salety Manager reported that a steamlitter wat working on a scissor lift and was installing spirilider system anchors between pipes that were installed by other plumbers. One of the anchors falled and a pipe for and landed on one of the steamlitter's hands, taking a tip of his hand off. A DOB inspector responded to the incident and visated the site and issued a DOB Violation and a partial Stop Work Order (PSWO) on all overhead installations. The General Contractor is to provide a Means and Methods and a Tool Box Talk.	1	35327073N				Material Fell	CIVIC CENTER COMMUNITY GROUP B	



cident Date		Address Number		Fatalities Injurie	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
1/2018	Manhattan	233	WEST 125 STREET	0	1 The Site Safety Manager reported that a worker was stripping concrete form work on the first floor when he slipped and fell approximately four feet from the platform. The worker was found conscious and without a		35327077K, 78M, 79Y		NEW BUILDING	121187447	Worker Fell	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
					visible injury, but was taken to a hospital for a check up. A DOB inspector responded to the incident and visited the site and reported that the worker was not using any type of fall arrest system, that the working are								
					illuminated with lights, and that there was water on the floor that created a slipping hazard. Three ECB Violations and a full Stop Work Order (FSWO) were issued. The General Contractor at the site is to provide a Means and Methods for the safe operation of the job.								
018	Brooklyn	4813	9 AVENUE	0	The Construction Superintendent reported that a worker was unloading a metal track when the track slid and cut his thumb. The worker went to urgent care for treatment						Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
018	Manhattan	241	WEST 62 STREET	0	The Project Manager at the site reported that a worker was carrying a 2 X 4 when he accidentally dropped the 2 X 4 onto the foot of another worker. The injured worker was sent to a hospital for a check up and returned to the site afterwards.	No Dispatch					Other Construction Related Incidents	NYC HOUSING AUTHORITY	
018	Manhattan	500	WEST 33 STREET	0	The Site Safety Manager reported that an electrician was moving his equipment when he hurt his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
018	Brooklyn	1	CLINTON STREET	0	The Site Safety Manager reported that a worker twisted his left ankle while installing rebar. The worker went to a clinic and then returned to the site.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
2018	Manhattan	1059	3 AVENUE	0	The Site Safety Manager reported that during the construction of a thirty story new building, a worker walked into the corner of a steel Heam and hunt his right floot. The worker continued to work, but the Site Safety Manager roticed that he was not doing well and the story of the steel of the steel of the story of	No Dispatch					Other Construction Related Incidents	63RD & 3RD NYC LLC	
018	Manhattan	110	UNIVERSITY PLACE	0	The Site Safety Manager reported that a plumber was installing a pipe when a piece of debris fell into his eyes. The plumber went to a doctor.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
018	Manhattan	455	5 AVENUE	0	1 A Project Manager at the site reported that during the installation of floor opening protection, a worker lost control of a plank that hit him in the nose. The worker walked to a clinic.	No Dispatch					Other Construction Related Incidents	NEW YORK PUBLIC LIBRARY	
2018	Staten Island	35 a	BAY STREET	0	The Site Safety Manager reported that a worker hurt his arm while removing formwork. The injured worker walked to urgent care.	No Dispatch			NEW BUILDING	520138379-01-NB	Other Construction Related Incidents		HOLLISTER CONSTRUCTION SE
018	Manhattan	209	EAST 19 STREET	0		No Dispatch			NB	121958480	Other Construction Related Incidents	VISUAL ARTS HOLDING CORP	GRAMERCY SQUARE LLC
2018	Manhattan	15	EAST 30 STREET	0	The Site Safety Manager reported that a worker fell down from the first floor supporting deck to the ground and suffered a very bad head injury. The worker was found conscious and was taken to a hospital by ambulance. The worker was reported to be in stable condition. A DOB inspector responded to the incident and visited the site and reported that the worker was yeaking along the re-shores and may have possibly fainted or tirpged and hit his head on one of the reshores. No enforcement action was deemed necessary, as the inspector off in ort observe any hazardous conditions during the time of inspection.	No Action Necessary					Worker Fell	MADISON 30 31 OWNER LLC	
2018	Manhattan	122	EAST 23 STREET	0	1 A DOB inspector reported that an electrical worker at the cellar level was on a twelve foot ladder installing electrical work, on the celling when he fell approximately six to seven feet. The worker was not wearing a harness and was taken to a nearly hospital. An ECB Violation would be considered to the property of the provided.		3532074P		NB	121190157	Worker Fell	NOT ON FILE	CM AND ASSOCIATES CONSTRU
2018	Manhattan	111	LEROY STREET	0	The Site Safety Coordinator reported that a worker injured his middle finger while using a pallet-jack. The	No Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
2018	Brooklyn	4813	9 AVENUE	0	worker was sent to urgent care.  1 The Construction Superintendent reported that a worker was carrying a few metal studs when he came into contact with a pipe scaffold tieback and twisted his knee. The worker was taken to urgent care.	No Dispatch					Other Construction Related Incidents	MAIMONIDES MEDICAL CENTER	
2018	Brooklyn	123	LINDEN BOULEVARD	0	The Site Safety Manager reported that a worker hurt his arm while moving formwork. The worker was transported to a hospital by another worker.	No Dispatch			NEW BUILDING	321228603-01-NB	Other Construction Related Incidents	NEW YORK CONGREGATIONAL CENTER	BUSHBURG BUILDERS LLC



Incident Date	Bassauch	Address Number	Ctreat	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Desmit	Permit No	Incident Type	Owner's Name	Contractor Name
6/8/2018	Borough Manhattan	Address Number 60	STREET GREENE STREET		I A DOB inspector peorted that a worker on the first floor was leaving the bathroom when he walked toward a temporary aluminum stat system that he thought was in place and secured. The stainvey collapsed and the suffered possible injuries to the neck and head and was able to stand on his own power. The worker received treatment in the emergency como of a nearby hospital, and eventually returned to the site to pick up his tools. ECB Violations were issued for a failure to safeguard, for there being no plans on site for ongoing construction work, and for three being no plans on site for ongoing construction work, and for three being no plans and was available for a temporary staircase. A full Stop Work Order (FSWO) was also issued.	ECB Violation	ECB Violation Numbers 35314346r 35314347z	COO Y KINGBURI NUMBURS	Permit AL	Permit No 123172217	Incident type Worker Fall	Owner's Name  NOT ON FILE	Contractor Name SHAWIMIUT WOODWORKING & SUP
6/8/2018	Manhattan	767	5 AVENUE	0	1 The Site Safety Manager reported that a worker was doing waterproofing work in a tree pit on the plaza area. When the worker was walking away, he walked into a metal object that was on the wall. The worker went to a clinic for a check up on his own and will be reporting back to work.	No Dispatch			ALTERATION 1	122970721	Other Construction Related Incidents		TURNER CONSTRUCTION COMPA
6/9/2018	Brooklyn	242	EAST 46 STREET	0	2 A DOB inspector reported that two workers were working on the eave and gutters of the roof while on pump jacks when the workers led approximately twenty feet. One of the workers sustained rinjuries to his wrist, while the other worker sustained a head rinjury and was in critical condition. Both workers were transported to Kinga County Hospital by ambulance. An ECB Violation, a DOB Violation, and a full Stop Work Order (FSWO) were issued for work being performed without a permit.	ECB Violation	35322879R	060918CERMR05			Worker Fell	PRINCE, LINCOLN	
6/9/2018	Manhattan	200	EAST 59 STREET	0	2 A DOB inspector reported that there were two electricians that were working in the utility room on the fourteenth floor with their foreman onsite. The workers were working on a panel board when they de-emergized hard of the board of their between the working or a panel board when they de-emergized hard of the board of the most of the standard of the board of the most of the standard both workers were electrocuted and suffered burns, and both workers were electrocuted and suffered burns, and both workers were taken to a hospital. Two Aggravated Level 2 ECB Violations were issued: one to the General Contractor, and one to the Electrical Subcontractor, for a failure to maintain safety measures. A partial Stop Work Order (FSWO) was also issued. Two other ECB Violations were issued for infractions not related to the incident.		35335966K, 35335967M		NEW BUILDING	121192912	Other Construction Related Incidents	MIPA 59/THIRD OWNER LLC	GILBANE RESIDENTIAL CONST
6/11/2018	Manhattan	45	BROAD STREET	0	1 A DGB inspector reported that a worker was holding an that was to be used to set the auger on a dtill gig when another worker his life figure with a hammer. The struck worker was taken to a nearthy hospital and was later released with a bruised finger. An ECB Violation was issued for a failure to safeguard. A partial Stop Work Order (PSWO) was issued or all use of the auger. The General Contractor is to provide a Means and Methods for the safe installation of an auger.		35332161J		NB	121190772	Excavation/Soil Work	MADISON 45 BROAD DEVELOPMENT L	pizzarotti LLC
6/11/2018	Manhattan	138	EAST 38 STREET	0	The Site Safety Manager reported that an iron worker was cutting a tie wire with a utility knife when the knife slipped out of his hand and cut his forearm. The worker was transported to a hospital by ambulance for treatment.	No Dispatch			NB	121186028	Other Construction Related Incidents	TATHAM HOUSE,	TISHMAN CONSTRUCTION CORP
6/11/2018	Brooklyn	41	BLUE SLIP	0	I A DOB inspector reported that a worker was in the process of climbing down an ejish foot ladder when he missed a thread at three feet high and fell to the floor. The worker complained of shoulder pain and was taken to a hospital for evaluation. The inspector found no defects to the ladder or the area where the work was being performed. No enforcement action was deemed necessary.	No Action Necessary			Ait 1	320597449-01-NB	Worker Fell	BOP GREENPOINT F LLC	T.G. NICKEL & ASSOCIATES
6/11/2018	Bronx	988	EAST 180 STREET	0	The Site Safety Manager reported that a worker was cutting water proofing with a sheetrock knife when he accidentally cut his thumb. The worker was taken to urgent care for treatment.	No Dispatch			NB	220152233	Other Construction Related Incidents	988 EAST 180 STREET HOUSING DE	MONADNOCK CONSTRUCTION IN
6/12/2018	Manhattan	300	LAFAYETTE STREET	0			35335881L				Other Construction Related Incidents	LVC 298, LLC	



ncident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
12/2018	Queens	28-30	JACKSON AVENUE		1 A DOB inspector reported that an electrician was working on a PVC junction box in the floor with glue. The box had live electrical wires, and the wires got touched as the electrician tried to push them down into the box, which created a spark that set the glue on fire. The electrician suffered a second degree burn and was taken to a hospital, where he was reported to be in stable condition. An Aggiravated Level 2 EGB Violation was issued for the failure to maintain safety measures while working on live electrical wires. A partial Stop Work Order (PSW O) was also issued to stop all electrical work.	ECB Violation			NEW BUILDING	420652886	Other Construction Related Incidents	LIC DEVELOPMENT OWNER, L.P.	HUDSON MERIDIAN CONSTRUCT
3/2018	Manhattan	15	EAST 57 STREET	0	The Site Safety Manager reported that a worker was using a grinder to cut steel when he lost control of the grinder, which caused a small laceration to his foreman. The worker went to a local hospital.	No Dispatch					Other Construction Related Incidents	15 EAST 57TH ST.ASSOC.	
3/2018	Manhattan	701	7 AVENUE	0	The Site Safety Manager reported that a carpenter was cutting sheetrock with a utility knife when he accidentally cut his forearm. The worker's foreman took him to a City M.D. for treatment. The worker is expected to return to work.				ALTERATION 1	121324343	Other Construction Related Incidents	20 TSQ GROUNDCO LLC	CNY CONSTRUCTION LLC
13/2018	Queens	42-20	27 STREET	0	1 The Site Safety Manager reported that a worker was illiting up the per farmes of a supported scaffold with a pulley when the worker burned his hands on the rope and dropped the pipe farmes of a wide by the supported scaffold. The worker was taken to a nearby hospital by a forenar for treatment. A DOB inspector responded to the incident and visited the site and reported that the details of how the incident accord were not known. Two ECB of how the incident accord were not known. Two ECB supported scaffold installation in a safe manner and for the failure to provide a supported scaffold erector card. A partial Stop Work Order (PSWO) for the installation of supported scaffolds was also issued.		35324229R - 35324230Y		SF	Q00040613-I1-SF	Material Fell	CRESCENT & 27 LLC	Classic Consulting Group
13/2018	Staten Island	2589	RICHMOND AVENUE	0	The Site Safety Manager reported that a water pipe was damaged by a worker on the second floor, which cause a flood on the first floor. One of the store workers the address slipped and fell. An ambulance was called. A DOB inspector responded to the incident and visited the site and determined that there was no enforcement action necessary, as the work that was being performed was approved under a DOB issued permit.	No Action Necessary			SPRINKLER	540138929	Other Construction Related Incidents	MACY'S RETAIL HOLDINGS, INC.	PATRICK BOWE
4/2018	Manhattan	532	WEST 33 STREET	0	The Site Safety Manager reported that a roof worker complained of pain in the left side of his chest while lifting waterproofing materials. The worker was alert and awake and was taken to Bellevue Hospital by ambulance for treatment.	No Dispatch			NB	121191183	Other Construction Related Incidents	NOT ON FILE	TISHMAN CONSTRUCTION CORP
14/2018	Brooklyn	210	CLASSON AVENUE	0	1 A DOB inspector reported that during a stripping operation that was taking place between the elevator shaft and north stairwell on the fifth floor, an "ULMA" formwork beam that was approximately sixteen feet long struck a worker in the head while the worker was transported to a hospital, where it was reported that he had suffered a concussion. The worker was latentagority of a concussion the worker was elementated to a concussion of the worker was alert and stable in the hospital. An ECB Violation was issued for a failure to maintain safe operations. A partial Stop Work Order (FSWO) was also issued on all concrete work. The General Contractor is to provide a Means and Methods for safe operations.		35336020Y				Other Construction Related Incidents	PRATT INSTITUTE	
4/2018	Brooklyn	1	CLINTON STREET	0	The Site Safety Manager reported that a worker was walking down from the second floor when he missed his step and fell down. The worker hurt his knee and went to a City M.D.						Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
4/2018	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a worker was carrying a piece of lumber that was 4 X 10 X 7" when the worker slipped, which caused the lumber to fall onto another worker's hand. The injured worker went to a City						Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	
4/2018	Bronx	600	BERGEN AVENUE	0	The Site Safety Manager reported that a worker hit his foot while unloading a beam. The worker's foreman took him to a first med.	No Dispatch			NEW BUILDING	220151868-01-NB	Other Construction Related Incidents	COMUNILIFE LA CENTRAL HOUSING	MOUNTCO CONST. & DEV.CORP
14/2018	Bronx	1812	VYSE AVENUE	Ö	1 A DOB inspector reported that a worker was taking the delivery of a Concrete Masonry Juni (CMU) block that was being delivered by a lull when his finger got caught between pallets and one of his fingertips separated. The worker's foreman took him to a hospital for treatment. An ECB Violation was issued for the failure to maintain safety measures. A partial Stop Work Order (PSWO) was also and an all material handling, including deliveries. A second partial Stop Work Order (PSWO) was also issued for the use of scaffloids in which the horizontal size of the safety of the property o		35318423J		NEW BUILDING	220152851	Other Construction Related incidents	VIA VYSE PARTNERSHIP HOUSING D	HLS BUILDERS CORP



ncident Date	Borough	Address Number		Fatalities Injuries			ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/18/2018	Brooklyn	15	WASHINGTON AVENUE	0	1 The Site Safety Manager reported that during the final pressure testing inspection of a standpipe, the regulator let the air out of the standpipe, which caused another worker to hit a wall. He worker complained of a back ache and an ambulance was called. A DOB inspector responded to the incident and visited the site, and reported that no enforcement action was deemed necessary, as the incident outcomed as the result of a worker error.	No Action Necessary					Other Construction Related Incidents	NYC DSBS	
18/2018	Manhattan	110	UNIVERSITY PLACE	0	The Site Safety Manager reported that an electrician was using a sheet rock knife to try to cut a conduit when he sliced his left index finger. The worker was escorted to the emergency room at Beth Israel Hospital with another co-worker to receive treatment.	No Dispatch					Other Construction Related Incidents	NOT ON FILE	
3/19/2018	Brooklyn	276	KENT AVENUE	0	1 A DOB inspector reported that a worker was forming a third floor deck when a retractable largyard device for a safety harmess was let not noise playwood. The deck was safety harmess was let not noise playwood. The deck was not been also also also also and the lose playwood, to also also also also also also also als		35327169H		NEW BUILDING.	320916407	Material Fell	DOMINO A LLC	280 KENT CONSTRUCTION LLC
3/19/2018	Brooklyn	306	NORTH HENRY STREET	0	1 A DOB inspector reported that a contractor had overloaded joist girders that expanded rightly eight feet with eight bundles of corrugated steel decking that were twenty feet. The decking was placed in a concentrated area on the joist girders. However, the joist girders were twenty feet. The decking was placed in a concentrated and an expectation of the place of the place girders. However, the joist girders were installed with one 34" but that eventually sheared off and collepsed. This collapse caused the worker to fall forty feet to the ground. EMS was called and the worker was found alter and responsive when EMS arrived. The worker suffered a broken shoulder and possible back riguries and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for a failure to safeguard, as well as a full Stop Work Order (FSWO).	ECB Violation	35336227L		EW-OT	340499080	Worker Fell	300 NORTH HENRY LLC	R, KING WINDOW CORP
19/2018	Manhattan	1681	3 AVENUE	0	The Site Safety Manager reported that a worker was removing a kitchen cabinet when he was hit in the head by the cabinet when it became loose. The worker suffered a cut to his face. The worker went to a City M.D. to receive treatment and will return to work.	No Dispatch			NEW BUILDING	121191913	Material Fell	95TH AND THIRD LLC	GILBANE RESIDENTIAL CONST
19/2018	Queens	36-18	MAIN STREET	0	The Site Safety Manager reported that an elevator company worker was putting down counter weights when his finger got pinched between the weights. The worker went to a City M.D.	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
/19/2018	Queens	37-09	COLLEGE POINT BOULEVARD	0	1 A DOB inspector reported that a worker was installing guardrails on the perimeter of the job site when he was asked to help install O-decking at the second floor. When the worker went to get a torch to help tim this dock, the worker stepped on a loces sheet of decking and the second floor and the second floor. When the worker went to get a torch to help tim this worker was not set to the second floor and the second floor second		ECB#35327475X		NB	420653607	Worker Fell	NOT ON FILE	TOP 8 CONSTRUCTION CORP
S/20/2018	Manhattan	328	EAST 62 STREET	0	I A DOS inspector reported that there were workers that were getting ready to cut out and remove a raker section that was connected to the Support OF Excavation (SOS) waller and protrouling through the foundation walls. The Construction Superintendent at the site stated that the Section needed to be removed for the completion of a waterproofing installation. During the process of preparing jackhammers to chip out the concrete around the raker pit, a worker slipped and fell approximately four fell that the raker pit, landing on his back. The landing that the state of the		35332281V-35332282X		NB	121189846	Worker Fell	YYY 62ND STREET LLC	Joy Construction corp



Incident Det	Deservet	Address No.	Pterest	Fatalities 1	EOC Final Description	DOD Assis	ECR Violation Numbers	DOR Violation Numbers	Desmit	Dormit No.	Insident Time	Owner's Name	Contractor Name
Incident Date 6/20/2018	Borough Manhattan	Address Number	Street LAFAYETTE STREET		EOC Final Description  J A ODB inspector reported that there were electricians moving spools down a flight of stairs when they lost control of one of the spools, which it one of the workers in the leg. The worker was taken to a hospital by ambulance. An EOB Violation was issued for a failure to maintain safe operations. A partial Stop Work Order (PSWO) was also issued for a heavy material handling. A Means and Methods must be provided.		ECB Violation Numbers 35331146R	DOB Violation Numbers	Permit	Permit No	Incident Type Other Construction Related Incidents	Owner's Name LVC 298, LLC	Contractor Name
6/20/2018	Marhattan	25	SUTTON PLACE SOUTH	0	I A DOB inspector reported that a worker was attempting to lower a chipping gun from a root to a setback to another worker when he accidentally dropped the control of the setback to another worker when he accidentally dropped the chipping gun for the report of the rep		35322737Y 35333276Y	062018CNESC01 062018CNEGS01	ALTERATION TYPE 2	122907426-01-EW-OT	Other Construction Related Incidents	CANNON POINT NORTH INC	DNA CONTRACTING LLC
6/20/2018	Manhattan	1558	3 AVENUE	0	The Site Safety Manager reported that a garbage truck was passing by when it hit a barrier that hit a worker. The worker complained of back pain and walked to urgent care.	No Dispatch					Other Construction Related Incidents	180 EAST 88TH STREET REALTY LL	
6/20/2018	Manhattan	1227	BROADWAY	0		No Dispatch					Other Construction Related Incidents	YJL BROADWAY HOTEL LLC	
6/21/2018	Brooklyn	583	LORIMER STREET	0	1 A DOB inspector reported that a worker injured his finger while using a drill during steel erection/modification work because the drill was used contrary to the manufacturer's specifications. The injured worker was sent to a hospital, where he received stitches. This incident occurred on June 21, 2018, but was not reported until June 22, 2018. Four ECB Violations were issued. These violations include a violation for a failure to maintain safe operations, a violation for a failure to maintain safe operations for the use of a drill contrary to the manufacturer's specifications, and a violation for the failure to notify the Department Of Buildings of the incident in a timely manner.	ECB Violation	35331149M, 1450L,1451N, 1452P				Other Construction Related Incidents	583 LORIMER LLC	
5/21/2018	Brooklyn	77	CLARKSON AVENUE	0	1 A DOB inspector reported that a worker was working on a platform deck when he fell approximately six feet to the lower level. The worker was found conscious and alert and was taken to a nearby hospital. An Aggravated Level 2 ECB Violation was issued for the failure to safeguard. A DOB Violation was sussued. A partial Stop Wink Port (FSWD) was issued for all of the work being conducted at the fifth floor.	ECB Violation	(35309269X	062118CNERWS01	Alt - 1NB	321197771	Worker Fell	CLARKSON BU LLC	DAWNY CONSTRUCTION LTD
6/21/2018	Manhattan	441	9 AVENUE	0	The Site Safety Manager reported that an iron worker was working racide an elevator shalt on a man basket was working racide an elevator shalt on a man basket worker's arm. An ambulance transported the worker to a hospital for treatment. A DOB inspector responded to a hospital for treatment. A DOB inspector responded to the incident and visited the site and reported that design drawings for working platforms were provided, a certification for the usage of a scaffold was provided, and lighting was being but in place during the time of inspection. However, an EOS Virolation was issued for inspection, However, an EOS Virolation was sasued for the presence of a suspended scaffold on the site. A parial Slop Work Order (PSWO) was issued for all work in an elevator shaft. A Means and Methods for all safe operations in a shaft must be provided.		35331147Z	062118BS04SA01			Material Fell	CBP 441 NINTH AVENUE OWNER, LL	
6/21/2018	Manhattan	45	BROAD STREET	0	I A DOB inspector reported that contractors were transporting material with an excavator when the knuckled of the machine struck the Concrete Masonry Unit (CMU) wall of the adjacent property (55 Broad Street, Manhatan), which is a Cosi restaurant. The impact dislodged a small section of concrete block that struck a customer that was eating lunch inside of the large track and the struck and the	ECB Violation	35332283h		FO	121190772	Material Fell	MADISON 45 BROAD DEVELOPMENT L	Pizzarotti LLC



ident Date	Borough	Address Numb		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Manhattan	15	EAST 30 STREET	0	The Site Safety Manager reported that a worker dropped a coupling on his foot during a rebar installation. The worker suffered a swelled foot and went to urgent care	No Dispatch					Material Fell	MADISON 30 31 OWNER LLC	
2018	Manhattan	315	EAST 46 STREET	0	with a co-worker.  1 The Site Safety Manager reported that a worker bent down to plug in an extension cord and hit his head on a	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
					stored piece of rebar. The worker went to urgent care.								
2018	Manhattan	100	CHURCH STREET	0	I A DOB inspector reported that at a nineteen story building that was having alteration work performed on it, there were workers installing and welding sewer pipes on the eight floor utility shaft using a "Lewel Clamp" that keeps the pipes in position. The "Jewel Clamp" slipped dout of the hands of one of the workers and fell through the shaft. The clamp bounced on the third floor and landed in the cellar, where it his another worker on his hand. The injured worker suffered cuts and bruises on his arm, but do not suffer a browner bore. The "liqued worker suffered cuts and bruises on his arm, but do not suffer a browner bore. The "liqued worker suffered cuts and bruises on the same, but do not suffer a browner bore." The "liqued worker suffered cuts and bruises on the same but and the suffered cuts and bruises on the suffered cuts and bruises on the suffered cuts and bruises and bruises on the suffered cuts and bruises on the suffered cuts and bruises a	ECB Violation	35327483X, 84H, 85J, 86L				Material Fell	100 CHURCH FEE OWNER LLC	RAS CONST. CONTRACT. INC
018	Queens	5	COURT SQUARE	0	The Site Safety Coordinator reported that a construction worker tripped and sustained a minor knee injury. EMS was called and the worker was transported to a local hospital.	No Dispatch			NB - NEW BUILDING	420902410	Worker Fell	JACKSON 2524 LLC	ZHONG WANG CONSTRUCTION S
2018	Manhattan	505	WEST 43 STREET	0		ECB Violation	35300598M		NEW BUILDING	121187456	Worker Fell	NOT ON FILE	NEW LINE STRUCTURES & DEV
2018	Manhattan	149	EAST 125 STREET	0	2 A DOB inspector reported that a Jekko crane machine on the fourth floor was in the process of placing a curtain wall panel on the third floor when the machine fell from the fourth floor of the other than the fell from the full from the fourth floor. One worker fell from the third floor to the street and suffered a crisical injury, and a second worker that was on the third floor was struck by crane components and suffered a non-file threatening back flug. Both injured workers were taken to a hospital. The inspector reported that the injured workers were not special to the structure of the control of the structure of the struct				NEW BUILDING	121192388	Mechanical Construction Equipment	NOT ON FILE	ZDG, LLC
2018	Brooklyn	420	ALBEE SQUARE	0	The Site Safety Manager reported that the Construction Superistendent was moving material on a pallet jack by himself when he hit a divert. The Construction Superistendent tried to stop the piece of material that was being moved from falling, but the material fell on his ankle. An ambulance was called.						Other Construction Related Incidents	JEMB ALBEE SQUARE LLC	
2018	Brooklyn	1	CLINTON STREET	0	The Site Safety Manager reported that a worker was picking up a garbage bag when he backed into stacked rebars and suffered a scratch to his right calf. The worker walked to a City M.D.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
2018	Bronx	2028	CRESTON AVENUE	0	The Site Safety Manager reported that a worker pulled his back while using a pallet jack. The worker complained of a back ache. An ambulance was called.	No Dispatch					Other Construction Related Incidents	HP 2030 CRESTON HOUSING DEVELO	



	Borough	Address Number		Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
6/2018	Brooklyn	1	CLINTON STREET	0	1 The Site Safety Manager reported that a worker was	No Dispatch			NEW BUILDING	321197478-01-NB	Other Construction Related Incidents	CADMAN ASSOCIATES LLC	T.G. NICKEL & ASSOCIATES
					fueling a generator when fuel was spilled on his arm. The worker walked to a City M.D. as a precaution.								
2018	Manhattan	1	BEEKMAN STREET	0	The Site Safety Manager reported that the diamond	ECB Violation	35342751Z	062618BS01KR01			Other Construction Related Incidents	ONE BEEKMAN OWNER, LLC	
					plate in a hoist car was not secured and that the diamond plate foll over and hit he ankle of a worker that was in the hoist. An ambulance was called. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for the failure to institute safety measures for the diamond plate in the host. A DOB Violation was also issued. As of the time of inspection, the diamond plate was made secure.								
/2018	Manhattan	1	WEST END AVENUE	0	1 A DOB rispector reported that workers were in the process of diamenting a fourteen foot high sidewalk shed when one of the workers fell back between the junitor beams. The worker was experiencing minor back pain and was taken to a local hospital by ambulance. An ECB Violation was issued to the sidewalk shed company for the failure to safeguard all persons and property.		35324259H		Shed	M00023179	Worker Fell	NOT ON FILE	Colgate Enterprises Corp
2018	Manhattan	400	WEST 61 STREET	0	1 The Site Safety Manager reported that a worker was carrying material down a flight of stairs when he missed the last step. The worker suffered a shoulder injury and was taken to a hospital by ambulance.	No Dispatch					Worker Fell	RCB1 NOMINEE LLC	
2018	Manhattan	61	9 AVENUE	0	The Site Safety Manager reported that a worker was	No Dispatch					Other Construction Related Incidents	G.D.C.L. HOLDINGS LLC	
					doing sheet metal work with a screw gun when he accidentally drilled a screw into his right hand. The worker was transported to a hospital by ambulance.								
9/2018	Brooklyn	63	FLUSHING AVENUE	0		No Dispatch					Other Construction Related Incidents	NYC DSBS	
					going on a break when he opened a box and the lid of the box fell on his hand, causing a laceration to his middle finger. The worker went to a hospital for a check up.								
9/2018	Brooklyn	856	WASHINGTON AVENUE	0	The Site Safety Manager reported that a section of sidewalk caved due to a rain storm that occurred on	ECB Violation	35335899J	062918BS08PK01			Other Construction Related Incidents	856 WASHINGTON OWNER LLC	
					June 28, 2018. A pedestrian stepped into the caved in section of sidewalk and hut her anilek, knee, and shoulder. An ambulance was called and the pedestrian was taken to a hospital by ambulance. A DOB inspector responded to the incident and visited the site and reported that there were cracks along the section of sidewalk that cewed in during the rain storm, which may be a section of the secti	i.							
2018	Manhattan	111	LEROY STREET	0	The Site Safety Manager reported that a window installer was taking suction cups off of a window when he pulled his back. An ambulance was called.	No Dispatch					Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	
29/2018	Queens	33-02	30 AVENUE	0	A DOB inspector reported that a worker was using a concrete trowel machine when he came upon a floor opening. The worker was using he machine close to the exterior wall when he hit the wall, which caused the machine to kilo back towards the opening. Both the worker and the machine fell approximately theelve feet into the basement. The New York City Fire Department removed the worker and EMS took the injured worker to a hospital. You EGD Worker been essued, including a hospital worker and EMS took the injured worker to a hospital. You EGD Worker been essued, including a safeguard and a second violation for the failure to post a project information panel. Two ODB Violations and a full Stop Work Order (FSWO) were also issued.		35334832K & 35334833M	062918CERRJ01 & 062618CERRJ02	ALTERATION TYPE 1	420474347-01-AL	Worker Fell	ANDREW G GEORGIOU TRUST FUND B	CENTRAL BUILDERS DEVELOPM
2018	Bronx	1520	STORY AVENUE	O I	A DOB inspector reported that a worker was on top of a concrete mixer and was attempting to remove a piece of concrete. The worker was pushing the piece of concrete. The worker was pushing the piece of concrete with its right floor when he go hit is bot caught in the shredder of the concrete mixer. One of the worker's toes was severed. The General Contractor at the site contacted NYC Fire Department EMT personnel, who transported the worker to Jacoby Hospital. An Aggravated Level 2 ECB Wolation was issued to the General Contractor for a failure to safeguard. A partial Stop Work Order (PSWO) on all concrete and cement operations was also issued. The contractors at the site must provide a Means and Methods for concrete and cement operations.		35332291h		NB	220151895	Other Construction Related Incidents	HP STORY AVENUE HOUSING DEV. F	L &M Builders Group
2018	Bronx	1880	BOSTON ROAD	0 1	The Site Safety Manager reported that a roofer hit the edge of the coping while doing roof work and cut his	No Dispatch					Other Construction Related Incidents	1880 BOSTON ROAD LLC	



cident Date	Borough	Address Number	Street	Fatalities Injuries	s EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2/2018	Bronx	764	EAST 152 STREET	0 1	A DOB inspector reported that at the fifth floor, a worker was moving a hose when he became entangled in the hose and fell approximately five feet from a pipe scaffold to the deck on the fill floor. The worker was taken to a hospital for treatment. Two Aggravated Level 2 ECB Violations were issued, one violation for a failure to safeguard, and a second violation for the failure to notify the Department Of Buildings of the incident. Two DOB Violations and a full Slipp Work Order (FSWO) were also issued.	ECB Violation	35322847P & 35322848R	070218CERJM02 & 070218CERJM01	NEW BUILDING	220562905-01-NB	Worker Fell	764 EAST 152ND STREET LLC	UA BUILDERS CORP
/2018	Brocklyn	350	HENRY STREET	0 1	A DOB respector reported that a worker was cleaning around a shaftway when he little a piece of plywood away from the shaftway and fell approximately fifteen feet through an opening. The plywood was not secure and the opening was not marked. The worker suffered possible fractured arm and fractured vertebrae. A partial Stop Work Order (PSWO) was issued on demolition work around shaftways.		3834814M=FAL TO SAFEGUARD. HOLES NOT SECURE, WORKER CLEANING UP THE SITE FELL THRU TO THE FLOOR		ALT1	320625294	Worker Fell	FPG CH 350 HENRY, LLC	ICS BUILDERS, INC
/2018	Manhattan	301	PARK AVENUE	0 1	The Site Safety Manager reported that a worker cut the middle finger of his right hand while pushing a mini container. The worker was taken to a clinic to get stitches.	No Dispatch			ALT-11	122978625	Other Construction Related Incidents	THOR 30 PARK AVENUE LLC	TISHMAN CONSTRUCTION CORP
2/2018	Manhattan	49	CHAMBERS STREET	0 1	The Site Safety Manager reported that a HVAC worker cut his right arm during a duct installation. A DOB inspector happened to be at the site as of the time of the incident and reported that the injury occurred as the result of a worker's error. The worker walked to a hospital. No enforcement action was necessary.						Other Construction Related Incidents	49-51 CHAMBERS LLC	
/2018	Manhattan	815	5 AVENUE	0 1	The Site Safety Manager reported that there were workers that overloaded an "A"-Frame cart, which caused a few 2 X 4 X 4" stones to slide off the cart. One of the stones fell onto a worker's foot. An ambulance was called.	No Dispatch					Other Construction Related Incidents	EIGHT HUNDRED AND FIFTEEN FIFT	
3/2018	Brooklyn	1	CLINTON STREET	0 1	The Site Safety Manager reported that a worker lost his footing and hurt his leg while pushing garbage in a thirty yard dumpster. An ambulance was called.	No Dispatch					Other Construction Related Incidents	CADMAN ASSOCIATES LLC	
/2018	Manhattan	1	WALL STREET	0 1	The Site Safety Manager reported that a worker came to the end of his shift when he complained that he strained his testicles while pushing a mini-dumpster. An ambulance was called.	No Dispatch					Other Construction Related Incidents	MIP ONE WALL STREET ACQUISITIO	
3/2018	Manhattan	150	5 AVENUE	0 1	A DOB inspector reported that a plumber was running a new line above an existing boliev when he came into contact with a live electrical wire. The plumber's partner pulled him off the wire. Both the worker and his partner were shaken up and were taken to a hospital by ambularie for a check up. An ECS Violation was issued for the presence of unapproved unselfe wiring in the under the presence of unapproved unself wiring in the terminated wires were also found in the basement bolier room. A partial Stop Work Order was issued on work on a confined space by the cellar boiler. A DOB Violation was also issued.	ı	35343112R	070318EE105EFF01			Other Construction Related Incidents	150 STH AVENUE OFFICE LLC	
/2018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker had pulled off some plywood during a stripping operation when he was hit in the eye by a nail. The worker went to a City M.D. A DOB inspector responded to the incident and visited the site and reported that the worker was not wearing his safety goggles/PEF (Personal Protection Equipment). An EOB Violation was issued for a failure to maintain safe operations.		35343006L				Other Construction Related incidents	PARK ROW 23 OWNERS LLC	
5/2018	Manhattan	392	ASSER LEVY PLACE	0 1	The New York City Police Department reported that he file on site worker called 911 and reported that he file from supported scaffold and sustained injuries. A DOB inspector responded to the incident and visited the site and reported that the worker was found laying on the ground root level. The worker told the NYPD, the FDNY, and the responding paramedics that he fell from the second level of the installed pipe scaffold. The worker suffered a broken right arm and was arifitted by the FDNY and transported to Bellew Hospital by ambulance. The DOB inspector also reported that the contractor was the site was soing fleaded pointing work that did not require a permit, and that the contractor was supported Scaffold permits. There ECB violations were issued: one violation for the presence of a scaffold than was not enclosed, one Aggravated Level 2 violation for the absence of a complete guard rail system. A partial Stop Work Order (PSWO) was also issued on the use of supported scaffolds.		35324944M, 35324345Y,35324346X				Worker Fell	PARKS AND RECREATION (GENERAL)	BQE industries inc
5/2018	Manhattan	701	7 AVENUE	0 1	The Site Safety Manager reported that an electrician cut his arm on a metal stud. The electrician went to urgent care.	No Dispatch					Other Construction Related Incidents		



cident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker twisted his ankle while coming down the stairs. The worker went to a City M.D. This incident occurred on July 5, 2018, but the Site Safety Manager was not notified of the incident until July 6, 2018.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
2018	Manhattan	25	PARK ROW	0 1	The Site Safety Manager reported that a worker on the sixth floor was standing on stilts to install track when he walked into a pipe hanger and fell off of the stilts and to the ground. The worker complained of left arm pain. EMS was called and the worker was taken to a nearby hospital.	No Dispatch			NB	121190610	Other Construction Related Incidents	PARK ROW 23 OWNERS LLC	URBAN ATELIER GROUP LLC
2018	Manhattan	425	PARK AVENUE	0 1	A DDB inspector reported that a worker stepped on a piece of ulreactured plywood on the second floor and fell perportionately themp; who feet to the first floor. The worker was taken to a hospital, and its reported to have suffered a dislocated hip. Four ECB Violations were issued: one violation for the presence of floor openings that were not securely covered and marked, a second violation for the presence of very poor housekeeping throughout the building, for the absence of perimter protecting at various places and vertical netting, and for a failure to safeguard persons and property. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35342980M,81Y,82X,83H		NEW BUILDING	121333921	Worker Fell	T-C 42S PARK AVENUE, LLC	TISHMAN CONSTRUCTION CORP
2018	Manhattan	215	PEARL STREET	0 1	A DOB inspector reported that a worker was using a baker scattold on the twenty fifth floor to perform tapping work. The scattold was not propely rected, the wheels of the scattold were not properly placed, and there were housekeeping issues present in the work area. As a result, the worker fell approximately six feet off of the staten to a hospital for a checkup. An ECB Violation was issued for the presence of poor housekeeping under the scaffold. A partal Slop Work Chref (PSW) was used for all work on baker scaffolds. The General Contractor is to provide a Means and Methods for safe operation.		35331468J		121017559	NEW BUILDING	Worker Fell	LAM PEARL STREET HOTEL LLC	ANTHONY T. RINALDI LLC
/2018	Manhattan	1227	BROADWAY	0 1	A DOB inspector reported that a worker was installing rebar inside of column cages on the sixteenth floor. The worker was installing an eighteen foot long, approximately one hundred pound piece of rebar all by himself. When he listed the rebar about three feet, he lost control of the rebar and was thrown to the floor. The worker suffered a dislocated shoulder and was taken to a hospital. Three EGB Violations were issued, including a violation for the failure to maintain safety measures and a violation for the failure to maintain safety measures and a violation for the failure to maintain safety measures and a violation for the failure to provide a DGB-approved design drawing for climbing form work. A partial Stop Work Order (PSWO) was also issued.		35345150R, 51Z, 52K		NEW BUILDING	121191986	Material Fell	YJL BROADWAY HOTEL LLC	FLINTLOCK CONSTR SERV LLC
2018	Bronx	603	JACKSON AVENUE	0 1	The Site Safety Manager reported that a worker fell form a baker scaffold. The worker was experiencing back pain and was taken to a hospital.	No Dispatch			NEW BUILDING	220151840-01-NB	Worker Fell	HP JACKSON AVENUE HOUSING DEVE	GALAXY GENERAL CONTRACTIN
018	Manhattan	111	LEROY STREET	0 1	The Site Safety Manager reported that an electrical worker was on the roof and using a band saw when he cut his middle finger one inch deep. The worker was alert and conscious and was taken to a nearby hospital for treatment.	No Dispatch			NB	122622992	Other Construction Related Incidents	PMG LEROY STREET DEVELOPMENT L	PMG CONSTRUCTION GROUP LL
2018	Manhattan	315	EAST 46 STREET	0 1	A DOB inspector reported that a signal man was giving signals to a crane operator that was operating a mobile crane that had a load on its hook. While giving crane that had a load on its hook. While giving endemn the crane's main host cable and the sheeve of a load block. The signal man suffered as severed left pinky finger and was taken to Bellevue Hospital. The inspector reported that the crane operator was in possession of a sisteen hour rigging card and had all required certifications, paper work, and olgo on site. The other members of the work crew were also in possession of sisteen hour rigging cards. No enforcement action was deemed necessary, as it was determined that the incident occurred as the result of a worker error.				CN	392/18	Mechanical Construction Equipment	GOVERNMENT OF THE UNITED ARAB	Urban foundation engineering IIc
2018	Queens	36-18	MAIN STREET	0 1	The Site Safety Manager reported that a roofer got some waterproofing material in his eyes while he was spraying. The roofer walked to an urgent care center.	No Dispatch					Other Construction Related Incidents	134-22 35TH AVE., LLC	
/2018	Brooklyn	1520	FULTON STREET	0 1	The Site Safety Manager reported that a plumber that was working in the basement slipped on water that was on the floor and hurt his knee. The worker went with another worker by car to see a doctor.	No Dispatch					Other Construction Related Incidents	HELLO FULTON LLC	
/2018	Brooklyn	170	BUFFALO AVENUE	0 1	The Site Safety Manager reported that a worker fell from an "A"-Frame ladder and hurt his ankle. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	BUFFALO AVE. REALTY ASSOCIATES	
0/2018	Manhattan	19	EAST 70 STREET	0 1	The Site Safety Manager reported that a worker was carrying a pail of sweeping compound on his shoulder when he lost control of the pail and the pail fell on his right leg. The worker was sent to a hospital.	No Dispatch					Other Construction Related Incidents	NY 70TH STREET LLC, A NY LLC,	



ident Date	Borough	Address Number		Fatalities Injurie		DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
2018	Manhattan	218	EAST 16 STREET	0 1	The Site Safety Manager reported that a worker was cutting off a tie-wire from an extension cord when he cut his hand with a cutting knife. The worker had his protective gloves on, but the knife went through the top	No Dispatch					Other Construction Related Incidents	SOCIETY OF FRIENDS	
					of the glove, between the thumb and index finger. An ambulance was called.								
018	Manhattan	524	RIVERSIDE DRIVE	1 0	A DOB inspector reported that a piece of the suspended scaffold system became dislodged at the roof level, fell twelve stories, and struck a worlder in the head. The worker was taken to the nearest hospital in critical condition, but later succumbed to his injuries. A DOB Violation was issued for a failure to safeguard and a full Stop Work Order (FSWO) were issued.	DOB Violation		071218CER01KC	ALTERATION TYPE 2	122912027-01-EW-OT	Scaffold/Shed/Fence/Shoring/Installation	INTERNATIONAL HOUSE	PRATT CONSTRUCTION & REST
018	Brooklyn	138	WILLOUGHBY STREET	0 1	A DOB increases accorded that there were wedgens union	ECB Violeties	35322622Y	071318CERSM01	NEW BUILDING	321197085-01-NB	Other Construction Related Incidents	NYC HPD	LEND LEASE (US) CONSTRUCT
2018	Brooklyn	138	WILLOUGHBY SI KEET	0 1	A DOB inspector reported that there were workers using chairfalls to move on the ground the collar of a crane in order to position it into a better working position as part of a crane; jumping operation. While the collar and was being moved, one of the worker's legs was pinned between the collar and a piece of the building. The worker was taken to Methodist Hospital by ambulance. The crane was not being used as of the time of the incident. The inspector reported that incident was caused by the use of inadequate means and methods in rigging by the Master Rigger. An ECB Violation was issued for a failure to safeguard. A DOB Violation was also issued.		\$53226224	0/1318CERSMU1	NEW BUILDING	32119/085-01-NB	Other Construction Related Incidents	NYCHED	LEND LEASE (US) CONSTRUCT
018	Manhattan	20	WEST 40 STREET	0 1	The New York City Fire Department requested that an	ECB Violation	35326871N				Other Construction Related Incidents	NOT ON FILE	
					inspection please be performed because a construction worker suffered a head rijury after coming into contact with a grinder. The worker was in stable condition and suffered a broken nose. The worker was transported to a hospital by EMS and received butterfly stitches on his forehead. The worker was released from the hospital after treatment. A DOB inspector responsed to the incident and visited the site and reported that the grinder was used contrasty to the manufactuer's specifications. An ECB Violation was issued for the failure to maintain safe operations. A partial Stop Work Order (PSWO) was issued on the use of all grinders. A Means and Methods and a Tool Box Talk must be provided.								
2018	Queens	24-16	QUEENS PLAZA SOUTH	0 1	The Site Safety Manager reported that a worker on the	No Dispatch					Other Construction Related Incidents	24-16 QUEENS PLAZA PROPERTY OW	
.010	question	24.10	dozeno i Bibliocom		top of a deck at the twenty third floor was cut on his arm by a circular saw. The worker was taken to a hospital by ambulance.	Tio Disputori					Carlo Constitution Notated Molecula	24 to doctrion beautiful con-	
2018	Manhattan	9	ORCHARD STREET	0 1	The Site Safety Manager reported that a worker hurt his back while placing a chipping gun on the floor. An ambulance was called.	No Dispatch					Other Construction Related Incidents	NINE ORCHARD PARTNERS, LLC	
2018	Manhattan	50	AMSTERDAM AVENUE	0 1	The Project Manager at the eite reported that a female worker tripped on a temporary electrical conduit that was laying on the roof of the building. The worker suffered bruised knee and a lowelle write and was taken to a hospital by ambulance. A DOB imspector responded to the incident and visited the site and issued two ECB Vollations: one vollation for the presence of an unsupported aluminum pipe, and a second violation for there being no equipment ground provided for the disconnect of 200 amps that ran between the basement and the roofflorp sub-panel. Two DOB Violations were also issued.	ECB Violation	35343201Z, 35343202K.	71818EE107RID01, 71818EE107RID02			Worker Fell	NYC HOUSING AUTHORITY	
2018	Manhattan	36	GROVE STREET	i o	A DOB inspector reported that a worker was performing an electrical installation on an energized circuit in the bathroom. The worker suffered an 120 voil electrical shock. The worker suffered an 120 voil electrical shock. The worker was taken to Leon CHIII Health Plex, where he was pronounced deed. The inspector reported that the worker failed to de-energize the circuit before performing the electrical installation. Three ECB Violations were issued: one violation for the presence of unapproved and unsafe wiring that had not been terminated, unsupported boxes, unsecured splice boxes, the failure to provide a GFCI, and the failure to provide a GFCI and the failure to provide a GFCI and relation for the failure to post an electrical permit, and one violation for the use of an electrical room as storage.	ECB Violation	35315697N, 35315698P & 35343200R	71618EE102RID01, 71618EE102RID02 & 71618EE102RID03			Other Construction Related Incidents	LUKE, TIMOTHY	
/2018	Brooklyn	25	COLUMBIA HEIGHTS	0 1	The Site Safety Manager reported that an electrician cut his arm while walking by a sharp object. The worker was						Other Construction Related Incidents	25-30 COLUMBIA HEIGHTS BROOKLY	
10040	Madaga	105	ODEENWOULDTDEET		driven to a hospital.							NO 405 1 1 0	
2018	Manhattan	125	GREENWICH STREET	0 1	The Site Safety Manager reported that a worker was performing a window installation when he flipped over a piece of tube steel and got his index finger caught between the tube steel and the floor. The tip of the						Other Construction Related Incidents	VS 125 LLC	
/2018	Queens	28-07	JACKSON AVENUE		worker's index finger was crushed. The worker went to a hospital by taxi.  The Site Safety Manager reported that a truck driver cut						Other Construction Related Incidents	LIC SITE B-1 OWNER, L.L.C.	



7/18/2018	Borough Brooklyn	Address Number 422	Street FULTON STREET	Fatalities Injuries 0 1	The Site Safety Manager reported that a worker slipped and fell lints a 7 x 3 x 2 deep hed using a rebar inspection in the cellar. The worker suffered a leg injury and an ambulance was called. A DOB inspector responded to the incident and visited the site and confirmed the Site Safety Manager's report. The inspector determined that the incident occurred as the result of a human error and that no enforcement action was necessary.	No Action Necessary	ECB Violation Numbers	DOB Violation Numbers	Permit P	ermit No	Incident Type  Other Construction Related Incidents	Owner's Name  NOT ON FILE	Contractor Name
7/18/2018	Manhattan	214	WEST 29 STREET	0 1	A competent person at the site reported that a worker slipped off an "A"-Frame ladder. The worker went to a hospital for a check up.						Other Construction Related Incidents	WALSAM TWENTY-NINE CO	
7/18/2018	Manhattan	24	2 AVENUE	0 1	The Site Safety Manger reported that a worker stepped on a nail. The worker walked to medic care for a check up.	No Dispatch					Other Construction Related Incidents	24 SECOND AVENUE OWNER LLC	
7/18/2018	Queens	147-40	ARCHER AVENUE	0 1	The Site Safety Manager reported that a worker was walking down a flight of stairs when he lost his balance on the bottom step and hurt his right foot. The worker went to urgent care on his own.	No Dispatch					Other Construction Related Incidents	HP JAMSTA HOUSING DEV. FUND CO	
7/19/2018	Brooklyn	420	UNION STREET	0 1	electrician that was working on a School Construction Authority (SCA) project cut his right thumb. The electrician went to an out patient clinic.	No Dispatch					Other Construction Related Incidents	DEPARTMENT OF EDUCATION	
7/19/2018	Manhattan	140	ESSEX STREET	0 1	The Construction Superintendent reported that during a drilling operation, a section of a drill bit fell and hit a worker in the back. The worker was awake and conscious and was able to walk, but paramedics put the worker on a stretecher and took him to a hospital. The worker on a stretecher and took him to a hospital to check on the worker. The Construction Superintendent reported that the worker had suffered minor bruises, with no broken bones, and was released from the hospital. A DOB inspector responded to the incident and visited the site and reported that the Construction Superintendents' license had apprend. An ECB Violation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.		353362632		FO 1:	21187642	Material Fell	SITE 8 DSA HOUSING DEVELOPMENT	Essex Site 8 Builders LLC
7/19/2018	Manhattan	625	WEST 125 STREET	0 1	The Site Safety Manager reported that a worker was installing a light fixture when he tripped over the light fixture and hurt his knee. The worker went to a hospital by ambulance.	No Dispatch					Other Construction Related Incidents	THE TRUSTEES OF COLUMBIA UNIVE	
7/20/2018	Manhattan	30	EAST 31 STREET	0 1	The Site Safety Manager reported that a pedestrian was entering her building when she was hit in the head by a piece of debris hat tell from a construction site. The pedestrian did not suffer any visible injuries, but an ambulance was called. A DOB inspector responded to the incident and visited the site and and issued an ECB Violation for a failure to safeguard. A partial Stop Work Order (FSWO) on all concrete work operations was also issued. A Means and Methods for safe operations must be provided.		35342859K				Other Construction Related Incidents	31ST STREET ZEF LLC	
7/21/2018	Brooklyn	3514	SURF AVENUE	0 1	A DOB respector reported that a worker was stripping opposed with the workers coming from behind him. The worker that was performing the stripping did not notify the other workers that he opened a hole, and the worker that was performing the stripping operation fell two stories through the hole. The worker was found conscious and was taken to an area hospital. The inspector observed that the protocol for a pre-lask meeting for stripping operation was not followed up. and that there were house keeping issues present at the top floor that were recorded by the Site Safety Manager. Three ECB Violations were issued: one violation for the failure to maintain or institute safety measures for construction operations, one violation for the failure to maintain or institute safety measures for the failure to provide a Professional Engineering letter of design drawing for protection at large slab openings. Three DOB Violations were also issued. A partial Stop Work Order (FWSWO) was issued on concrete and stripping operations. A Means and Methods for the safe continuation of work must be provided.		35342860H/61J/62/	072118BS13EP01/02/03			Worker Fell	RED APPLE SURF REALTY III LLC	
7/23/2018	Manhattan	545	WEST 30 STREET	0 1	The Site Safety Manager reported that a worker was in the hoist with equipment when he got his foot caught under the equipment. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	15 HUDSON YARDS CONDOMINIUM	
7/23/2018	Manhattan	401	WEST 31 STREET	0 1	A DOB inspector reported that there was work being performed under the street level for the removal of existing Anthrat racks and the installation of new steel for the relocation of an existing sub-station. An iron worker was installing sate design when he tell approximately ten feet through a gap and suffered a firactured arm. The worker was tound in stable condition and with his harmess, on, as the harness had to be cut of the first three workers was town to a hospital. An ECB Violation was issued for a failure to safegueard. A DOB Violation was also issued for all used work being performed for the relocation of a sub-station.	ECB Violation	35245391J	072318CNEDB01	A2 - ALTERATION TYPE 2 1:	23091705	Worker Fell	BOP WEST 31ST STREET LLC	JOHN CIVETTA & SONS INC



cident Date	Borough	Address Number	Street	Fatalities Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
/2018	Manhattan	217	WEST 57 STREET	0 1	The Site Safety Manager reported that there were workers that were backing up a trailer on the job site with flaggers when a bicyclist went around the flagger, slipped on wet pavement, and hurt his arm. The pavement was wet because of rain. The bicyclist did not hit the trailer. An ambulance was called.	No Dispatch		Joseph Managara	, sum	, cum ne	Other Construction Related Incidents	SMITELL SPONSOR LLC	
3/2018	Manhattan	152	EAST 87 STREET	0 1	A worker fell back and scrapped his arm against a trash chute. The worker went to a hospital for treatment. The worker received two stitches and returned to work.	No Dispatch					Other Construction Related Incidents	ALLAN GARAGE,	
/2018	Manhattan	150	EAST 38 STREET	0 5	A DOB inspector reported that contractors were performing interior demoition work on the fourth floor when the wood and plaster celling collapsed and injured five workers. Two of the workers were in serious condition and were taken to Bellevue Hospital. No structural damage was observed. An Aggravated Level 2 ECB Vilolation was issued for a failure to safeguard. A full Stop Work Order (FSWO) was also issued.	ECB Violation	35343417H		Alt 1	123254263	Other Construction Related Incidents	SUN, ANGELA	zzz carpentry Inc
/2018	Manhatian	19	EAST 70 STREET	0 1	A DOB inspector reported that during the hosting of pipe scaffold trames from the fifth floor down to the pipe scaffold trames from the fifth floor down to the interior of a stairs shaft, one of the frames got toose and tit the Construction Superintendent in the head on the issoond floor, knocking him unconscious. The worker was taken to Presbyterian Hospatal in stable condition. Two ECB Violations were issued: one violation for a failure to safeguard all persons affected by construction operations, and one violation for work being performed that did not conform to approved plane. A partial Stop Mark and Conform to approved plane. A partial Stop Stopport of the property of the		35324422Z - 35324423K		Alt 1	121944227	Material Fell	NY 70TH STREET LLC, A NY LLC.	Sweeney & Conroy Inc
/2018	Manhattan	315	EAST 46 STREET	0 1	The Site Safety Manager reported that a worker performing form work when he got his finger pinched during an installation and suffered a cut to his finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	GOVERNMENT OF THE UNITED ARAB	
5/2018	Queens	43-12	HUNTER STREET	0 1	The Site Safety Manager reported that a worker in the basement cut his right eye while moving rebar. The worker went to a City M.D. with a co-worker.	No Dispatch					Other Construction Related Incidents	43-12 HUNTER LLC	
2018	Staten Island	546	GULF AVENUE	0 1		No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
2018	Staten Island	546	GULF AVENUE	0 1	a nospital on his own.  The Site Safety Manager reported that a steel worker was using a chain when the chain slipped out of his hand and pinched his left finger. The worker went to urgent care.	No Dispatch					Other Construction Related Incidents	STATEN ISLAND GLOBAL LOGISTIC	
5/2018	Manhattan	250	SOUTH STREET	0 1	The Site Satety Manager reported that are iron worker was on a man lift and working on a small piece of seel was on a man lift and working on a small piece of seel of the clip and fell approximately 30' inside the job site. A DOB inspector responded to the incident and visite in the site and reported that the worker suffered a minor injury to his shoulder from the steel clip when the clip left. The worker did not report the injury, and left the set without letting anyone know. An ambulance was not called. The worker later reported that he went to see a called. The worker later reported that he went to see a institute safely measures. A DOB Wolation and a partial Stop Work Order (PSWO) were also issued.	ECB Violation	35331357R	072618BS03JJ01			Material Fell	NOT ON FILE	
/2018	Manhattan	215	PEARL STREET	0 1	The Site Salety Manager reported that a worker was standing on a ladder that was behind a closed door when another worker opened the door and knocked the worker off of the ladder. The worker hit his head, and a mahulance was called. A DOB inspector responded to the incident and visited the site and issued an ECB Violation for a failure to institute safely measures. A DOB Violation was also issued. A partial Stop Work Order (PSWO) was issued on all door closure installations. A Means and Methods and a safe Controlled Access Zone area for ladder work during an installation must be provided.	ECB Violation	35342769R	072618BS01KR02			Worker Fell	LAM PEARL STREET HOTEL LLC	
7/2018	Manhattan	438	WEST 54 STREET	0 1	A DOB inspector reported that a worker was on a truck and receiving planks while dismantling a sidewalk shed when he lost his footing and fell off off the truck and onto a pedestrian. The pedestrian received aid from the onate Sidewalk Shed company, Til Borough Scaffoldring. The pedestrian requested medical treatment. The FDNY responded to the request and visited the site, and examined both the worker that fell from the truck and the pedestrian. The worker was determined to be okey and returned to work, while the pedestrian as taken to a hospital. Two ECB Violations were issued: one violation for a failure to safeguard pedestrian and property, and one violation for a failure to provide a sidewalk shed as required. A full Stop Work Order (FSWO) was also issued.		35324486H - 35324487J		NB	122822605	Worker Fell	15024 EMMUT PROPERTIES LLC	Best Point Mgmt Corp
0/2018	Bronx	1812	VYSE AVENUE	0 1	The Site Safety Manager reported that a worker was moving pipes when his right middle finger got caught between pipes. The worker went to the emergency room with his supervisor. An ambulance was not called.						Other Construction Related Incidents	VIA VYSE PARTNERSHIP HOUSING D	



Incident Date	Borough	Address Number	Street	Fatalities	Injuries	EOC Final Description	DOB Action	ECB Violation Numbers	DOB Violation Numbers	Permit	Permit No	Incident Type	Owner's Name	Contractor Name
7/30/2018	Bronx	4511	3 AVENUE	0		The Site Safety Manager reported that a plumber was tightening a sprinkler pipe when he hit a stud and cut his finger. The worker walked to urgent care across the street from the job site.	No Dispatch					Other Construction Related Incidents	STB HOUSING DEVELOPMENT FUND C	
7/30/2018	Manhattan	110	UNIVERSITY PLACE	0		The Site Safety Manager reported that a worker was on a ladder when he mis-stepped, fell off of the ladder, and pulled his back at. The worker went to urgent care.						Worker Fell	NOT ON FILE	
7/30/2018	Manhattan	122	EAST 23 STREET	0		The Site Safety Manager reported that a cleaning person was cleaning the apartments when she went down to the cellar, where there was construction work being performed. The cleaning person stepped walked off of the elevator and hit her foot on a man-tift that was left in the basement. The man-fit was in the basement because it was being used in construction work that was being performed. The cleaning person went to urgent care on her own.						Other Construction Related Incidents	NOT ON FILE	
7/30/2018	Manhattan	233	WEST 125 STREET	0		SThe Site Safety Manager reported that at a twenty six story new building that was under construction, a worker was cutting rebar with a chop saw when a fragment of the rebar hit him in the face. The worker did not appear to suffer any cuts. The worker went to see a private doctor.				NB	121187447	Other Construction Related Incidents	HARLEM URBAN DVLPMNTCP	FLINTLOCK CONSTR SERV LLC
7/31/2018	Brooklyn	269	4 AVENUE	0		The Site Safety Manager reported that at the foundation level of a twelve story new building, a worker was loading in plywood material when he pinched his left pinky finger between plywood. The worker was found alert and conscious and was taken to Lutheran Hospital for treatment.	No Dispatch			NB	320596805	Other Construction Related Incidents	FIRST BUILDING ENTERPRISES LLC	NEW EMPIRE BUILDER CORP