



Bill Heizen
Acting Commissioner/Chair

Allan J. Fromberg
Public Affairs
frombera@tlc.nyc.gov

Rebecca Harshbarger
Public Affairs
harshbargerR@tlc.nyc.gov

**33 Beaver Street
22nd Floor
New York, NY 10004**

Notice: Reinspection Payments

Vehicles that fail their initial inspection must return to TLC's Woodside facility for a reinspection in order to remain licensed.

Beginning November 12, 2019, vehicle owners will no longer need to pay in advance for vehicle reinspections when they arrive at TLC's Woodside facility. Reinspection fees must be paid online after the reinspection at nyc.gov/lars.

A reinspection fee is only owed if a vehicle fails its initial inspection and is brought back and reinspected after making the necessary repairs. No reinspection fee is owed if a vehicle passes its initial inspection.

Vehicle owners will need the following information available when logging into LARS to make a payment:

1. Your TLC License Number
2. The mailing ZIP code associated with your license
3. The last 5 Digits of your EIN or SSN

Vehicle owners will now be responsible for the reinspection fee after the reinspection is done. The fee is owed regardless of whether the vehicle passes or fails a reinspection. The due date will be listed on your Vehicle Inspection Report (VIR). If you do not pay the fee, you will receive a summons. If found guilty, you may be fined \$300 and have your TLC license suspended.

Additional information about these changes can be found on our website at www1.nyc.gov/site/tlc/vehicles/vehicle-inspections.page