

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51633	12A0342CO	Sant-Tec Electric Inc. 305 East 110th Street New York NY 10029	Requested approval for the electric service equipment proposed to be installed	211 East 13th Street New York NY	Approved	\$0.00
Carry over December 12, 2012 meeting. 11/27/13 Swapped Rev 1C. 4/21/16 Swapped drawing 1-Revision 1D. 1/9/17 Swapped drawing #1-Revision 1E.						
51699	12A0345CO	New Phase Electrical Contractors, Inc. 725 East 136th Street Bronx NY 10454	Requested approval for the electric service equipment proposed to be installed	200 West 86th Street New York NY	Approved	\$0.00
Carry over from December 12, 2012 meeting. 1) Identify equipment connected to service switches 3 and 4 and how are they connected. 2) Show that circuit breakers and fuse are coordinated. Job finalized 7/11/13.						
51692	13A0006CO	Enterprise Electrical Systems, Inc. 502 Coney Island Avenue Brooklyn NY 11218	Requested approval for the electric service equipment proposed to be installed	291 Union Street Brooklyn NY	Approved	\$0.00
Provide grounding electrode conductors in service switches as per Section 250.63(D)(2). Job finalized 6/26/13.						
	13A0024CO	Forest Electric Corp. Two Pennsylvania Plaza, 4th Floor New York NY 10121	Requested approval for the electric service equipment proposed to be installed	Goldwater North 1879 Madison Avenue New York NY	Rejected	\$0.00
Carry over from January 9, 2013 meeting. 1) New panels main bus under size. 2) How many emergency generators will be installed in the future? 3) Show location of panel EPPK-2. 4) Clarify what emergency feed to ATS is, and show future feeder size. 7/29/13 job finalized. 7/18/14 Rejected New submittal required.						
	13A0093CO	Inter-Connection Electric, Inc. 6821 8th Avenue Brooklyn Brooklyn NY 11220	Requested approval for the electric service equipment proposed to be installed	180 Orchard Street New York NY	Administrative Closure	\$0.00
Carry over from March 13, 2013 meeting. 1) Verify conductor size to fire alarm service switch and fusing. 2) Provide load calculations as per the exception to 230.42(A)(2). 3) Service entrance to 2000 amp service switch not shown. 4) Fire pump feeders undersized and not shown to ATS. 5) Will 3 or 4 pole ATS be used? 6.) Two service conductors are undersized. 7) Service bus sizes under sized and/or missing. 8) Provide manufacturer's cuts indicating 700 sq. in. bus. 7/18/13-1) fire pump emergency fuse undersized. 2) Item #5 not addressed. 8/23/13 #5 not addressed. 1/10/14 job finalized. 5/24/16 There are 2 submittals for the same installation 13A0093-Approval #52069 which shows different service rooms Approval # 52069 is Denied. A new submittal is required showing the correct installation. 7/13/2016: THIS SUBMISSION NUMBER VOID IN LIEU OF SUBMISSION NO. 15A0336						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51737	13A0094	A. Ceriello Electric, Inc. 15 Carroll Street Brooklyn NY 11231	Requested approval for the electric service equipment proposed to be installed	1205 Manhattan Avenue Brooklyn NY	Approved	\$0.00
SANDY Verify bus size to existing 4000 amp service switch. Job finalized 7/19/13						
	13A0095	NYC Electrical Contracting Inc. 150 52nd Street Brooklyn NY 11232	Requested approval for the electric service equipment proposed to be installed	186 North 7th Street Brooklyn NY	Rejected	\$650.00
9/24/14 Rejected 1) Low voltage equipment not to be installed in service room. 2) Clarify size of fire alarm service switch.						
51632	13A0096	Gilston Electrical Contracting Corporation 338 East 95th Street New York NY 10128	Requested approval for the electric service equipment proposed to be installed	Douglass Houses-Bldg. #1 870 Columbus Avenue New York NY	Approved	\$650.00
52060	13A0097	Horsepower Electric 188 21st Street, 2nd Floor Brooklyn NY 11232	Requested approval for the electric service equipment proposed to be installed	312 Bergen Street Brooklyn NY	Approved	\$650.00
1) Provide size of main bonding jumpers. 2) Service bus feeding 3-600 amp service switches undersized need (4Bars). 12/16/3 job finalized.						
51741	13A0098	First Quality Electric Corp. 5120 Ft. Hamilton Parkway Brooklyn NY 11219	Requested approval for the electric service equipment proposed to be installed	2730-1209 DeKalb Avenue Brooklyn NY	Approved	\$650.00
Where is the location of the service entrance box in relation to the service equipment? 7//24/13 job finalized. 12/17/13 Swapped Revision 3's.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51742	13A0099	First Quality Electric Corp. 5120 Ft. Hamilton Parkway Brooklyn NY 11219	Requested approval for the electric service equipment proposed to be installed	408-422 West 52nd Street New York NY	Approved	\$650.00
1) Show size of main bonding jumper. 2) Equipment grounding conductor on load side of 2000 amp service switch is undersized. 7/24/13 job finalized.						
51781	13A0100	Lippolis Electric, Inc. 3396 East Tremont Avenue Bronx NY 10461	Requested approval for the electric service equipment proposed to be installed	503-511 Broadway New York NY	Approved	\$650.00
1) Correct fuse size on single line. 2) Verify location of pumps that are above grade. 7/29/13 job finalized.						
	13A0101	Striano Electric Co., Inc. 246 Park Avenue Garden City Park NY 11040	Requested approval for the electric service equipment proposed to be installed	Lenox Hill Hospital 20-40 7th Avenue New York NY	On Hold	\$650.00
1) Verify that switchboard has rear doors. 2) 3' clearance required on side of switchgear. 3) Physicals of service equipment and distribution do not 11 line layout, and bus sizes. 4) Distribution panels fed from ATS' not properly formatted. 5) Verify fire pump on sprinkler booster pump where is it located and verify feeder and service switch sizing. 6) Neutral to be installed in fire pump service switch and bond and ground switch. 7) ATS ratings don't coordinate with OCPD for normal and emergency. 8) Change breaker adequate interrupting rating per short circuit study.. 6/24/13- 1) Item #3 not addressed. 2) Item #4 not addressed. 3) Verify item #5. 4) Item #6 not addressed 5)Item #7 not addressed. 6) Item #8 not addressed.						
52029	13A0102	W.T.G. Electric, Inc. 115-14 Beach Channel Drive Rockaway Park NY 11694	Requested approval for the electric service equipment proposed to be installed	Beth Abraham Nursing Home 612 Allerton Avenue New York NY	Approved	\$650.00
1) Can fire pump service switch be relocated to comply with 230.64(B)(5)? 2) Provide cut sheet for replacement generator distribution panel. 3) Are existing ATS 3 or 4 pole types? 7/18/13- Remove neutral bond on generator 3 pole ATS' are being used. 11/22/13 job finalized.						
51785	13A0103	Roma Electric Corp. 30-75 14th Street Astoria NY 11102	Requested approval for the electric service equipment proposed to be installed	30 Washington Street Brooklyn NY	Approved	\$650.00
1) Verify that new switchgear has rear doors. 2) Show all clearances behind the switchgear. 3) Relocate MDP 5 and 6 to comply with 230.64(B)(5). 4) Verify that service room is mechanically ventilated. 5) Verify service bus sizes and some not shown load side of service switch. 6) Show length of taps. 7) Physicals of service switchboard not provided. 8) Secondaries of transformers to be grounded to building steel. 9) Coordination to comply with 3018.L. 8/1/13 job finalized.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51824	13A0109	Pinnacle Electric 130-45 91st Avenue Richmond Hill NY 11418	Requested approval for the electric service equipment proposed to be installed	25 Washington Avenue Brooklyn NY	Approved	\$650.00
Temporary installation and permanent installation require separate submittals. Provide sequence of operation. 8/16/13 job finalized. 1/17/14 Swapped page 1 of 3 Rev 2 and 2 of 3 Rev 2						
	13A0110	A.S.R. Electrical Contracting, Inc. 177-04 93rd Avenue Jamaica NY 11433	Requested approval for the electric service equipment proposed to be installed	432 Park Avenue New York NY	On Hold	\$650.00
1) Show how concrete encased service entrance conductors are routed from sub cellar #1 to sub cellar 2, Identify all concrete encased conduits. Are they installed in the middle of sub cellar service room 1? Show elevation drawing of service rooms, SEB 1 and 2 not identified. 3) Signage on front accessible equipment to read front access only. Do not remove covers. 4) Verify taps for jockey pumps, line side of ATS'. 5) Provide cutter for transformers. 6) Show cable support boxes for all conductors for their sizing. 7) Coordination study not provided. 8) Verify clearances in the generator cabinet, show floor plan. 9) Is generator a separately derived system, if not how will GF operate.						
51763	13A0111	Brandl Electric 1927 Mott Avenue Far Rockaway NY 11691	Requested approval for the electric service equipment proposed to be installed	Montefiore Medical Ctr 2058 Jerome Avenue Bronx NY	Approved	\$650.00
1) Fire alarm s.s. neutral bar not bonded to enclosure. 2) Grounding electrode not provide at fire alarm s.s. 3) Verify that switchboard has rear hinged doors. 7/25/13 job finalized.						
51753	13A0112	Jusler Electric Corp. 4543 21st Street Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	Sage Realty Sprinkler Work 767 Third Avenue New York NY	Approved	\$650.00
1) F.P. service entrance connection located inside enclosure of another s.s. Article 695.3(A)(1). 2) Verify step-up transformer size Article 695.5(c)(1). 3) 60 amps unfused disconnect switch remove. 4) Verify transformer XD bonded to enclosure or neutral is provided and bonded to disconnect switch Article 250.30. 5) Transformer is in reverse. 7/25/13 job finalized.						
51773	13A0113	KND Licensed Electrical Contracting International Airport, Bldg 141 Federal C Jamaica NY 11430	Requested approval for the electric service equipment proposed to be installed	CCNY-North Academic Ctr 138th Street at Convent Avenue New York NY	Approved	\$650.00
Supplemental grounding electrode not provide. 7/29/13 job finalized.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51873	13A0114	Brandl Electric 1926 Mott Avenue Far Rockaway NY 11691	Requested approval for the electric service equipment proposed to be installed	Citizen M. Hotel 218 West 50th Street New York NY	Approved	\$650.00
1) F.P. emergency c.b. under size(See Article 430.52). 2) Grounding electrode not provided at fire alarm s.s. 3) Verify neutral at fire alarm ATS not switched. 4) Grounding electrode not provided at s.s. #2. 5) Verify 120 amp service switch for fire pump. 8/16/13 #1, #3 and #5 not addressed. 9/17/13 job finalized.						
51747	13A0115	Amber Lite Electric Corp. 441 Wild Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	1000 Dean Street Brooklyn NY	Approved	\$650.00
1) Services with multiple disconnecting means enclosures no grounding electrode not provide (S.S. #3, S.S. #4 and fire alarm). 2) Verify that fire pump conductors are listed for wet locations. 7/25/13- Job finalized. 1/10/14 Swapped A-Rev 3, B-Rev 4.						
51748	13A0116	Glo Electric LLC 441 Wild Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	1133 Manhattan Avenue Brooklyn NY	Approved	\$650.00
1) Grounding electrode not provide at s.s. with multiple disconnecting means enclosures (F.P. and F.A.). 2) Verify copper buss at s.s.#2. 3) Verify 4 sets or single set of 350 KCMIL tap between house dist. pnl. Job finalized 7/25/13.						
51749	13A0117	Glo Electric LLC 441 Wild Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	26-14 Jackson Avenue Queens NY	Approved	\$650.00
1) Grounding electrode not provide at service with multiple disconnecting means enclosures. 2) Show coordination between 400 amp s.s & panel. Job finalized 7/29/13. 8/22/14 Swapped A-Rev 3 and B-Rev 2.						
51750	13A0118	Glo Electric LLC 441 Wild Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	250 Utica Avenue Brooklyn NY	Approved	\$650.00
1) Grounding electrode not provide at service with multiple disconnecting means enclosures. 2) AIC not shown. 3) Series rating between 400A ss and pnl. Job finalized 7/29/13.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51776	13A0119	Quantum Electric Corporation 36-24 34th Street Long Island City NY 11106	Requested approval for the electric service equipment proposed to be installed	105 East 17th Street New York NY	Approved	\$650.00
Make 110.26 condition 2 condition 1. 7/29/13 job finalized.						
51622	13A0120	Anthony G. Ferry Inc. 217a Fordham Street Bronx NY 10464	Requested approval for the electric service equipment proposed to be installed. OA	Kent Avenue Apartments 53 North Third Street Brooklyn NY	Approved	\$650.00
	13A0121	A & M Electrical Service, Inc. 617 Johnson Avenue Brooklyn NY 11237	Requested approval for the electric service equipment proposed to be installed. OA	210 Joralemon Street Brooklyn NY	Rejected	\$650.00
7/22/15 Rejected. Too many revisions made to this drawing requires complete review. Service entrance conductors on drawing changed without indications.						
51614	13A0122	Major Electric Inc. 41-30 37th Street Astoria NY 11101	Requested approval for the electric service equipment proposed to be installed. OA	23-88 31st Street Queens NY	Approved	\$650.00
9/18/14 Swapped A & B, Revision 2. 9/29/14 Swapped A and B, Revision 3. 3rd Swap.						
51625	13A0123	H & L Electric, Inc. 41-11 28th Street Long Island City NY	Requested approval for the electric service equipment proposed to be installed. OA	514 49th Street Brooklyn NY	Approved	\$650.00

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51620	13A0124	H & L Electric, Inc. 41-11 28th Street Long Island City NY	Requested approval for the electric service equipment proposed to be installed. OA	1335 6th Avenue New York NY	Approved	\$650.00
51765	13A0125	H & L Electric, Inc. 41-11 28th Street Long Island City NY	Requested approval for the electric service equipment proposed to be installed	Gagosian Gallery & Café 976 Madison Avenue New York NY	Approved	\$650.00
Tap conductors between DPA under size. 7/25/13 job finalized.						
51764	13A0126	Five Star Electric Corp. 101-32 101st Street Ozone Park NY 11416	Requested approval for the electric service equipment proposed to be installed	1 North 4th Place Brooklyn NY	Approved	\$650.00
1) Grounding electrode not provide at multiple enclosures service switches Article 250.64(D). 2) Verify service room mechanical ventilated. 3) Verify trough fill requirements. 4) Verify AIC rating for TVSS switch. 7/25/13 job finalized. 10/16/13 Swapped, "A" drawing Revision 2.						
	13A0127	E-J Electric Installation Co. 46-41 Vernon Blvd. Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	NYUMC Energy Building FDR 34th Street New York NY	Rejected	\$650.00
1) Bonding and grounding of the switchgear installed on the load side of the neutral link, size of main bonding jumper not shown. 2) Bus sizes on 1 line do not match physicals, show 12" off floor. 3) Equipment grounding conductors undersized. 4) Feeders overfused. 5) Show fusing sizes on normal side of ATS. 6) 1 short circuit study does not allow follow the 1 line drawing. 7/31/13-1) Item #1 not addressed, size of main bonding jumpers not shown; bonding jumper to be installed on the load side of each 4000 amp switch inside of the paralleling gear. 2) Item #6 not addressed. 9/10/13-1) Item #1 partially addressed. 2) Generators not to have ground fault protection due to bonding and grounding in the paralleling gear. 3) Drawings and installation to comply with Section 517.17 of the NYCEC. 12/20/13 Items 1,2 & 3 not addressed.						
	13A0128	Allran Electric of NY 120 Broadway, 36th Floor New York NY 10271	Requested approval for the electric service equipment proposed to be installed	Brittany Hall 55 East 10th Street New York NY	On Hold	\$650.00
1) Equipment grounding conductor #6 on supply side of fire alarm service under size Article 250.66. 2) Fire alarm emergency circuit at generator over fused. 3) Fire alarm emergency circuit equipment grounding conductor #6 under size Article 250.122. 4) Supplemental grounding electrode not provided. 5) Grounded conductor not provided with fire pump service entrance. 6) Equipment grounding conductor #3 on supply side of fire pump s.s./controller under size. 7) Fire pump emergency circuit equipment grounding conductor under size. 8) Grounding electrode not provided at all multiple service disconnecting means enclosures. Article 250.64(D). 9) Fire pump service conductor shall be installed per 230.6. 10) Partition f.p. station at em gen board.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51928	13A0129	E-J Electric Installation Co. 46-41 Vernon Blvd. Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	Jones Lang LaSalle Americas Inc. 1285 Avenue of the Americas New York NY	Approved	\$650.00
1) Verify that the equipment has met the requirements of 408.60(B) of the NYC Electrical Code. 2) Verify that switchboards have rear hinged doors. 10/7/13 job finalized. 7/22/14 Swapped FP40 1 of 1 Rev 2 AB40 2 of 2 Rev 4. 1/12/15 Swapped AB40 2 of 2 Revision 5.						
	13A0130	E-J Electric Installation Co. 46-41 Vernon Blvd. Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	Public Safety Answering Ctr II 350 Marconi Street Bronx NY	On Hold	\$650.00
1) Show how service entrance conductors will be routed to the 9th floor. 2) Verify that free standing switchboards will have rear hinged doors. 3) Verify 14 sets of 500MCM 7-4" raceways and 16 sets of 500 MCM in 8-4" raceways, after derating fusing oversized. 4) No emergency switch provided for fire pump, fire pump feeders are not fire rated, jockey pump feeder not shown. 5) Bus sizes for CMDS-A1, UPS-A1, CMDS-B1, UPS-B1 not shown. 6) Paralleling gear 1 line does not match ASCO physical. 7 Coordination study not submitted. 8) Verify conductor and conduit sizes. 9) Someone who know job to appear at next meeting.						
51634	13A0131	Litespeed Electric Inc. 135 West 29th Street, Suite #301 New York NY 10001	Requested approval for the electric service equipment proposed to be installed. OA	Ice Intercontinental Exchange 55 East 52nd Street New York NY	Approved	\$650.00
51761	13A0132	MF Electric Service Co., Inc. 3323 Merritt Avenue Bronx NY 10475	Requested approval for the electric service equipment proposed to be installed	Hutchinson Metro Ctr Tower 2 1250 Waters Place Bronx NY	Approved	\$650.00
1) Service entrance equipment grounding conductors #2 under size Article 250.66. 2) Supplemental grounding electrode not provide at service switches. 3) Main bonding jumper buss size not shown on drawing. 4) Main grounding electrode not provided at service with multiple disconnecting means (F.P. & F.A.). 5) Provide fuses in secondary of trans.for F.A. 7/25/13 job finalized.						
51623	13A0134	Katco Electric, Inc. 44-15 Barnett Avenue Long Island City NY 11104	Requested approval for the electric service equipment proposed to be installed. OA	189M 2580 Amsterdam Avenue New York NY	Approved	\$650.00
9/16/13 Drawings swapped Rev 0. 10/22/13 Swapped Rev 1.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51619	13A0159	SDM Metro 220 Maple Avenue, Suite 203 Rockville Centre NY 11570	Requested approval for the electric service equipment proposed to be installed. OA	35 Kent Avenue Brooklyn NY	Approved	\$650.00
9/13/13 No good for swap. Grounding electrode for transformer not shown on drawing to be swapped. 1/27/14 1) Clearances of equipment not shown in service room. 2) 3' clearance required in front of end box. 3) Verify that service equipment does not have rear doors. 4) Verify that service room is mechanically ventilated. 5) 30 and 60 am service switches to be grounded. 1/27/14 1) Clearances of equipment not shown in service room. 2) 3' clearance required in front of end box. 3) Verify that service equipment does not have rear doors. 4) Verify that service room is mechanically ventilated. 5) 30 and 60 amp service switches to be grounded. 4/14/14 Swap Rev 4s RL-01, E-0. 12/2/14 Swap E-01 and RL-01, Rev 5's.						
51834	13A0160	Five Star Electric Corp. 101-32 101st Street Ozone Park NY 11416	Requested approval for the electric service equipment proposed to be installed	P.S./I.S. 42Q 488 Beach 66th Street Queens NY	Approved	\$0.00
SANDY 1) Provide cut sheet for service end box. 2) Show location of service end box and routing of service entrance conductors to C.T. cabinet. 3) Bonding and Grounding to be installed on line side of the main neutral link. 4) Fire pump service switch neutral to be bonded and grounded. 5) Show size of emergency feeder to fire alarm system. 6) Fire alarm service switch to be grounded. 7) Verify AIC rating of 30 amp for TVSS. 8/22/13 job finalized						
51701	13A0181	Adco Electrical Corporation 201 Edward Curry Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	111 Wall Street New York NY	Approved	\$0.00
SANDY 1) Service room to be mechanically ventilated. 2) Verify that switchboards have rear hinged doors. 3) Bond from service switch to building steel to be 3/0 cu. Job finalized 7/16/13.						
51702	13A0182	Rainbow Electric Co. Inc. 76-18 Rockaway Blvd. Woodhaven NY 11421	Requested approval for the electric service equipment proposed to be installed	125 Maiden Lane New York NY	Approved	\$0.00
SANDY 1) Service room doors to open outwards 110.26(c)(3). 2) Service entrance box and routing of service entrance conductors not shown on room layout drawing. 3) Bus feeding 2000 amp service switches undersized. 4) Bonding jumpers to building steel to be 3/0 cu. 5) Sec's and feeders for fire alarm system not shown. 6) 600A TR fuse at switchboard not coordinated. 7) Fire alarm switch missing GEC. Job finalized 7/16/13.						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
53179	13A0183	Adco Electrical Corporation 201 Edward Curry Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	55 Water Street New York NY	Approved	\$0.00
SANDY 1) Service room doors to open outwards . 2) Service board LV-H to be moved back to provide access around switchboard. 3) Bus ties not shown on room layout. 4) Verify that switchboards have rear hinged doors. 5) Bonding jumpers to building steel to be 3/0 cu. 6) Fire rated cable is not listed fire pump. 7) 2nd fusing from switchboard LV-H not shown. 8) Bus to 3000 amp service switch undersized in switchboard LV-H. 9) Fire pump supply tapped from switchboard section that contains an overcurrent protective device. 10) Indicate Con Ed service entrance points on plans. 12/2/14 Rejected. 1) Item #2 not addressed. 2) Item 3 and 10 not addressed. 3) Item #9 not addressed. 8/17/15 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 5/18/16 Swapped drawing E-Revision 3.						
	13A0184	Hatzel & Buehler, Inc. 45 Broadway New York NY 10006	Requested approval for the electric service equipment proposed to be installed	32 Old Slip New York NY	On Hold	\$0.00
SANDY 1) Show how feeders are routed from load side of utility owned disconnect switches to CT cabinets, conductor support boxes not shown. Where is the location of the utility switch in relation to the CT cabinets? Will the conduits be concrete encased? See #5 item below. 2) Fire pump service switches not shown on room layout drawing. 3) MSC-F switchboard mislabeled on room layout drawing. 4) Service room to be mechanically ventilated. 5) Utility owned disconnect switches are wired from load to line and not bonded and grounded. 6) Bonding and grounding not shown for existing fire house service switch. 7) Bonding jumpers from service switches to building steel to be 3/0 cu. 8) 800 amp disconnect switch tapped from load side of 4600A ss in MSC-C not shown on room layout drawing and tapped conductors are undersized. 9) Existing fuse sizes and conductor sizes to ATS #2 not shown. 10) Verify if feeders are new or existing to existing panels. 11) Through bus undersized in MSCE. 12) Verify location on neutral link in MSCF. 13) PNL DP5 neutral bonded after s.s. 14) Fire rated conductors are not listed, fire pump. 15) Conductors from Con-ED to service equipment to comply with 215.2(A)(1). 16) Verify types of conduit to service equipment.						
51618	13A0186	M.K. Electrc Co., Inc. 10 Bay 22nd Street Brooklyn NY 11214	Requested approval for the electric service equipment proposed to be installed. OA	614 Sheepshead Bay Road Brooklyn NY	Approved	\$0.00
SANDY						
51626	13A0187	Stanco Systems Electrical Contracting 4061 Victory Boulevard Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed. OA	John Dewey HS 2475 Stillwell Avenue Brooklyn NY	Approved	\$0.00
SANDY						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51617	13A0188	Arcadia Electrical Company, Inc. 1005 Wyckoff Avenue Ridgewood NY 11385	Requested approval for the electric service equipment proposed to be installed. OA	Russo's on the Bay 162-45 Cross Bay Boulevard Queens NY	Approved	\$0.00
SANDY						
51616	13A0189	Goldstar Electrical 59-24 57th Street Maspeth NY 11378	Requested approval for the electric service equipment proposed to be installed. OA	99 Wall Street New York NY	Approved	\$0.00
SANDY 9/17/13 Drawings swapped Rev 1.						
	13A0190	E-J Electric Installation Co. 46-41 Vernon Blvd. Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	4 New York Plaza New York NY	On Hold	\$0.00
SANDY 1) Do ATS's in service room feed life safety equipment. 2) Install barrier behind left side of EDP-1 switchboard. 3) Service room doors to open outwards 50-01. 4) Fire pump feeders to be fire rated. 5) Indicate that service switches are ground fault protected. 6) Show the size of main bonding jumper in s.s. 7) Provide cut sheets for 4160 generators. 8) Provide Coordination study. 9) Show what the secondary of 4160 transformer is feeding, protection. 10) Verify neutral in existing generators. 11) Show where main service and transformer secondary grounding and bonding will be connected to. 12) Show approved plans for resistive grounding.						
	13A0226	Polo Electric Corp. 497 Canal Street New York NY	Requested approval for the electric service equipment proposed to be installed	180 Maiden Lane New York NY	On Hold	\$0.00
SANDY 1) Main bonding jumper buss size not shown drawing. 2) Switchboard equipment bonding buss under size S.S. #C & D. 3) Verify mechanical ventilation for service room. 4) Equipment that are flooded to be reused must be tested by Neta certified testing co. and will be allowed to be use for temp use only.						
51615	13A0227	Patriot Electric Corp. 96-06 220th Street Queens Village NY 11429	Requested approval for the electric service equipment proposed to be installed. OA	100 Maiden Lane New York NY	Approved	\$0.00
SANDY						

ADVISORY BOARD CALENDAR

April 17, 2013

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
51624	13A0228	Response Electric, Inc. 680 Lorimer Street Brooklyn NY 11211	Requested approval for the electric service equipment proposed to be installed. OA	18-20 West Street New York NY	Approved	\$0.00
SANDY						
51627	13A0229	Five Star Electric Corp. 101-32 101st Street Ozone Park NY 11416	Requested approval for the electric service equipment proposed to be installed. OA	95 Horatio Street New York NY	Approved	\$0.00
SANDY 10/16/13 Swapped, drawings 1 and 2 Rev 4.						
51628	13A0230	Atlas-Acon Electric Service Corp. 283 Hudson Street New York NY 10013	Requested approval for the electric service equipment proposed to be installed. OA	Trinity Real Estate 205 Hudson Street New York NY	Approved	\$0.00
SANDY						