


IMAGE KEY:



137 Hollywood Avenue,  
Douglaston Historic District

Docket No. WL15-0215

Installation of fence and awning at  
side/west patio without permit(s).





VIEW 1 - West Corner from driveway

Docket No. WL15-0215  
Installation of fence and awning at  
side/west patio without permit(s).





VIEW 2 - West Corner from Hollywood Avenue

Docket No. WL15-0215  
Installation of fence and awning at  
side/west patio without permit(s).





VIEW 3 - Detail of patio including fence and awning

Docket No. WL15-0215  
Installation of fence and awning at  
side/west patio without permit(s).





VIEW 4 - Detail of patio including fence and awning

Docket No. WL15-0215  
Installation of fence and awning at  
side/west patio without permit(s).






VIEW 5 - Detail of patio fence

Docket No. WL15-0215  
Installation of fence and awning at  
side/west patio without permit(s).



IMAGE KEY:



137 Hollywood Avenue,  
Douglaston Historic District

Docket No. WL15-0216

Installation of security cameras  
without permit(s).





VIEW 1 - West Corner from Hollywood Avenue

Docket No. WL15-0216  
Installation of security cameras  
without permit(s).





VIEW 2 - East Corner from Centre Drive

Docket No. WL15-0216  
Installation of security cameras  
without permit(s).





VIEW 3 - Detail at West corner including security cameras

Docket No. WL15-0216  
Installation of security cameras  
without permit(s).






VIEW 4 - Detail of East corner including security camera

Docket No. WL15-0216  
Installation of security cameras  
without permit(s).






VIEW 5 - Detail at East rear corner including security cameras

Docket No. WL15-0216  
Installation of security cameras  
without permit(s).



IMAGE KEY:



137 Hollywood Avenue,  
Douglaston Historic District

Docket No. WL15-0217

Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





**AT TIME OF VIOLATION**

**VIEW 1 - East Rear from Centre Drive**

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





**CONDITION AS OF SEPTEMBER 1, 2016**  
**VIEW 1 - East Rear from Centre Drive**

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 2 - Detail of wall

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 3 - Detail of pergola, awning and fencing

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).






VIEW 4 - Detail of awning

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).



IMAGE KEY:



137 Hollywood Avenue,  
Douglaston Historic District

Docket No. WL15-0217

Installation of walls, fencing, pergola and awning at rear of property without permit(s).





VIEW 1 - Pergola and Terrace seen from rear open porch

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 2 - Terrace seen from rear open porch

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 3 -View of Pergola

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 4 - Detail of lowered wall

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).





VIEW 5 - Pergola and Terrace seen from side lawn

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).






VIEW 6 - Terrace from side lawn

Docket No. WL15-0217  
Installation of walls, fencing,  
pergola and awning at rear  
of property without permit(s).



IMAGE KEY:







VIEW 1 - Front view from Hollywood Avenue

Docket No. WL15-0218  
Alterations to steps and posts at  
front porch without permit(s).





VIEW 2 - Entry steps at front porch

Docket No. WL15-0218  
Alterations to steps and posts at  
front porch without permit(s).





VIEW 3 - Detail at front porch including steps and post

Docket No. WL15-0218  
Alterations to steps and posts at  
front porch without permit(s).





VIEW 4 - Detail of East side of front porch including posts

Docket No. WL15-0218  
Alterations to steps and posts at  
front porch without permit(s).