


15. Alley Pond Park Bicycle Trail




From Street:	73 rd Avenue
To Street:	76 th Avenue
Length:	0.34 miles
Signs Condition: Observed: 2/12/07	No Data
Lane Marking Condition: Observed: 8/17/06	100% Good 0% Poor 0% Patches 0% No Marking
Symbols Condition: Observed: 8/17/06	No Symbols
Pavement Condition: Observed: 11/30/06	100% Good Condition 0% Fair Condition 0% Poor Condition Material: Asphalt
2005 Bicycle Accidents:	No bicycle accidents reported along the Alley Pond Park bicycle trail.
2005 Average Daily Bicycle Ridership:	N/A

Alley Pond Park Bicycle Trail: Pavement and Sign Condition



Alley Pond Park Bicycle Trail: Lane Marking and Symbol Condition




16. Astoria Shore Greenways




From Street:	27 Avenue
To Street:	33 Road
Length:	0.81 miles
Signs Condition: Observed:	No data
Lane Marking Condition: Observed: 8/11/06	0% Good 0% Poor 0% Patches 70% No Marking*
Symbols Condition: Observed: 8/11/06	No Symbols
Pavement Condition: Observed:	No data
2005 Bicycle Accidents:	No bicycle accidents reported along the Astoria Shore bicycle trails.
2005 Average Daily Bicycle Ridership:	N/A

* **Note:** 30% (1,296 ft) of the route was either under construction or inaccessible when the data was collected.

Astoria Waterfront Bicycle Trail: Pavement and Sign Condition



Astoria Waterfront Bicycle Trail: Lane Marking and Symbol Condition




17. Brookville Park (Conselyeas Pond) Bicycle Trail




From Street:	147 th Avenue
To Street:	South Conduit Avenue
Length:	1.43 miles
Signs Condition:	100% Good
Observed: 12/29/06	0% Fair
	0% Poor
	All signs clearly visible to users.
	Bike signs = 2 regulatory, 7 greenway
Lane Marking Condition:	54% Good
Observed: 12/29/06	0% Poor
	0% Patches
	46% No Marking
Symbols Condition:	No Symbols
Observed: 12/29/06	
Pavement Condition:	49% Good Condition
Observed: 12/29/06	51% Fair Condition
	0% Poor Condition
	Material: Asphalt
2005 Bicycle Accidents:	No bicycle accidents reported along the Brookville Park bicycle trail.
2005 Average Daily Bicycle Ridership:	N/A

Brookville Park Bicycle Trail: Pavement and Sign Condition



Brookville Park Bicycle Trail: Lane Marking and Symbol Condition




18. Cross Island Parkway/ Little Bay Park Bicycle Trail



From Street:	Utopia Parkway
To Street:	Northern Blvd
Length:	3.10 miles
Signs Condition:	100% Good
Observed: 7/12/06	0% Fair
	0% Poor
	All signs clearly visible to users.
	Bike signs = 6 informational, 40 greenway
Lane Marking Condition:	88% Good
Observed: 8/17/06	6% Poor
	0% Patches
	6% No Marking
Symbols Condition:	91% Acceptable
Observed: 8/17/06	9% Poor
	Symbols: (27 Bicyclist, 4 pedestrian, 27 Roller
	Bladder, 59 Arrow, 23 Other)
Pavement Condition:	42% Good Condition
Observed: 1/2/07	45% Fair Condition
	13% Poor Condition
	Material: Asphalt
2005 Bicycle Accidents:	No bicycle accidents reported along the Cross Island Parkway bicycle trail.
2005 Average Daily Bicycle Ridership:	N/A

Cross Island Parkway / Little Bay Park Bicycle Trail: Pavement and Sign Condition



Cross Island Parkway / Little Bay Park Bicycle Trail: Lane Marking and Symbol Condition

