

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54049	15A0710CO	Sure Power Electric Inc. 246-10 Francis Lewis Blvd. Queens NY 11422	Requested approval for the electric service equipment proposed to be installed	73 Sands Street Brooklyn NY	Approved	\$0.00
Carry over from November 18, 2015 meeting. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 11/28/16 Swapped drawings 1 and 2-Revision 3.						
54026	15A0837CO	Roz-A-Lite Electrical Contracting Inc. 159 20th Street, Ste #401 Brooklyn NY 11232	Requested approval for the electric service equipment proposed to be installed	325 Lexington Avenue Manhattan NY 10016	Approved	\$0.00
OR This submittal voids out submittal number 13A0169, Approval #52948. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54062	16A0155	USIS Electric Inc. 264 West 40th Street, Suite 1400 New York NY 10018	Requested approval for the electric service equipment proposed to be installed	277 West 10th Street New York NY	Approved	\$650.00
<p>This drawing is approved with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						
	16A0196CO2	Verde Electric Corp. 811 Whittier Street Bronx NY 10474	Requested approval for the electric service equipment proposed to be installed	500 West 33rd Street New York NY	On Hold	\$0.00
<p>Carry over from July 13, 2016 meeting. 1) Coordination study not provided. 2) How is the feeder between the generator and the 13KV secondary switchgear protected. 3) Is Co-gen listed or will it be field evaluated by a OSHA recognized testing laboratory with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0253	Walsh Electrical Contracting Inc. 15 Newark Avenue Staten Island NY 10302	Requested approval for the electric service equipment proposed to be installed	55B Richmond Terrace Staten Island NY	On Hold	\$650.00
<p>1) Service C tap conductor to 400 amp switch undersized. 2) Provide manufacturer's cut sheets of switchboards with listings. Show how bus is formed and provide calculations for distribution boards, cut sheets of bus. 3) Service B 2 set of 500 KCM overfused. 4) Fire alarm system #10 conductors overfused. 5) Verify that park metal switchgear is listed. 6) Provide emergency room layout. 7) Show service switch for fire pump B. 8) Show ATS room. 9) Generator cut sheet not provided. 10) Provide wiring method from generator to switchboard with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						
	16A0294CO	Lazen and Sawyer Environ. Eng's & Scientists 498 Seventh Avenue, 11th Floor New York NY 10018	See comments for requests and status	3701 Jerome Avenue Bronx NY		\$0.00
<p>Requesting permission as per attached drawings to: 1) Approve the power source for fire command and all data gathering panels as shown. Status: Denied-A dedicated ATS connected to primary and secondary power to be provided in a separate 2 hr enclosure. 2) Advisory Board concurrence that the automatic transfer switches are not in the same room as the power sources. Status: Denied-A dedicated ATS connected to primary and secondary power to be provided in a separate 2 hr enclosure. 3) Advisory Board approval to utilize #12 copper equipment grounding conductors on 15 ampere circuits for pre-action detection, clean agent, and dry chemical panels as per Table 250.122. Status: Approved. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
	16A0348	Adco Electrical Corporation 201 Edward Curry Avenue Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	530 East 74th Street New York NY	Pending	\$650.00
<p>1) Fire pump 1, 2 emergency side underfused. 2) ATS-2 #7 overfused on emergency side. 3) EMR-DS-23-D1, EMR-DS-23-C1 show conductors in split panel. 4) Show transformer secondary tap length PNL-LS VP-23-D. 5) Panels 5D-2-D1 and SD-2-C1 not shown on 1 Line or physical. 6) Coordination study not provided with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54037	16A0366	Unity Electric Co., Inc. 65-45 Fresh Meadow Lane Flushing NY 11365	Requested approval for the electric service equipment proposed to be installed	4 Chase Metrotech Center Brooklyn NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54051	16A0391	Hal Electrical Contractors Inc. 32 East 31st Street, Suite 812 New York NY 10016	Requested approval for the electric service equipment proposed to be installed	1776 Boston Road Bronx NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54136	16A0394	E & M Electrical NY Corp. 193-02 Northern Blvd. Flushing NY 11358	Requested approval for the electric service equipment proposed to be installed	34-37 36th Street Queens NY	Approved	\$650.00
The contractor paid twice for the same submittal number but one receipt was for 16A0394. Who will be performing bus bar installation on 4000 amp service switch to connect PV system. 10/6/16 Job finalized. With the stipulation that 1000 volt SMA Sunny Tripower 3000 TL inverters, and SMA connection units 1000-US combiner boxes can be installed Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54047	16A0398	Delco Electrical Corp. 241 West 37th Street, 700 New York NY 10018	Requesting permission to replace existing Federal Pacific circuit breaker interiors with Cutler-Hammer retro-fit interiors and covers on feed through panels and leave at present height 7'2" off the floor due to rigid conduits in concrete walls making it a hardship to lower the panels to 6'7" to the top circuit breaker in 23 apartments.	799 Park Avenue New York NY	Approved	\$0.00
With the stipulation that the fault current at the panels does not exceed 10,000 amp. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
	16A0403	Atlas-Acon Electric 283 Hudson Street New York NY 10013	Requested approval for the electric service equipment proposed to be installed	30 Rockefeller Plaza New York NY	Pending	\$650.00
Drawing AB-02 through bus on 1 Line has typo bus not complete.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54133	16A0404	M.C. Electrical NY, Inc. 835 Castleton Avenue Staten Island NY 10310	Requested approval for the electric service equipment proposed to be installed	515 West 39th Street New York NY	Approved	\$650.00
<p>Service bus between 1st and 2nd sections undersized with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 10/4/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54035	16A0473	W.T.G. Electric, Inc. 115-14 Beach Channel Drive Rockaway Park NY 11694	Requested approval for the electric service equipment proposed to be installed	145 4th Avenue New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54063	16A0480	Ace Electrical Expert Corp. 40-04 73rd Street, 2nd Floor Woodside NY 11377	Requested approval for the electric service equipment proposed to be installed	11-39 49th Avenue Long Island City NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54064	16A0490	Dal Electrical Corporation 218 52nd Street Brooklyn NY 11220	Requested approval for the electric service equipment proposed to be installed	156 William Street New York NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54134	16A0491CO	A.S.R. Electrical Contracting, Inc. 969 Third Avenue, Suite 4F New York NY 10022	Requested approval for the electric service equipment proposed to be installed	553 West 30th Street New York NY	Approved	\$0.00
<p>Carry over from July 13, 2016 meeting. Fused switch, not circuit breaker shall be installed remote from the emergency switchboard with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 10/3/16 Job finalized. This drawing is approved with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p> <p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54065	16A0492	Levis Electric 28-17 31st Street Long Island City NY 11102	Requested approval for the electric service equipment proposed to be installed	34-22 35th Street Queens NY	Approved	\$650.00
<p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						
	16A0499	Allan Briteway Electrical, Inc. 360 Lexington Avenue, Suite 601 New York NY 10017	Requested approval for the electric service equipment proposed to be installed	21 West End Avenue New York NY	Rejected	\$650.00
<p>Cut back concrete pad to clear egress path with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 10/3/16 1) Show bonding and grounding of existing service equipment. 2) Fire pump emergency breaker undersized. 3) Fire pump transition conductors undersized.</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0501	Pinnacle Electric 130-45 91st Avenue Richmond Hill NY 11418	Requested approval for the electric service equipment proposed to be installed	30-02 Queens Blvd. Long Island City NY	Pending	\$650.00
<p>1) Drawing 2-show Time Warner and Verizon feeders and switches. 2) Drawing 2-Fire alarm disconnect switch fed from Building A to be unfused. 3) Drawing 3-Equipment grounding conductor feeding fire pump controller undersized. 4) Drawing 5-Room layout does not match physical MSC-C-N and MBDP-C-N1. 5) Drawing 2 and 3 verify that the 3000 any feeders are ground fault protected with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						
	16A0515CO	FSG Electric Inc 494 8th Avenue New York NY 10001	Requested approval for the electric service equipment proposed to be installed	101 Pennsylvania Avenue Brooklyn NY	Rejected	\$0.00
<p>Carry over from July 13, 2016 meeting. Fire pump normal side equipment grounding conductor undersized with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 9/29/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 1/6/17 Rejected 1) Feeders and ECGs undersized. 2) SDS to be bonded in one location only. 3) Verify that neutral in Gen is bonded to the enclosure.</p>						
54290	16A0516	CSA Engineering Services, LLC 15 Trowbridge Drive Bethel CT 06801	Requested approval for the electric service equipment proposed to be installed	245 East 54th Street New York NY	Approved	\$650.00
<p>1) Wiring methods not shown on E.1.0AB. 2) Conductors feeding normal side of ATS' overfused. 12/22/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54066	16A0517	Forest Electric Corp. Two Pennsylvania Plaza, 4th Floor New York NY 10121	Requested approval for the electric service equipment proposed to be installed	200 Liberty Street New York NY	Approved	\$650.00
<p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54033	16A0518	Forest Electric Corp. Two Pennsylvania Plaza, 4th Floor New York NY 10121	Requested approval for the electric service equipment proposed to be installed	200 Liberty Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
	16A0520	Lano Electric Co., Inc. 1633 Williamsbridge Road Bronx NY 10461	Requested approval for the electric service equipment proposed to be installed	625 East Fordham Road Bronx NY	Denied	\$650.00
<p>1) Verify no emergency feeders are running through the service room. 2) Mechanical ventilation. 3) Emergency feeder switch on load side of ATS not permitted in service room as well as its feeders. 4) Emergency disconnect for 400A on load side of ATS not to be bonded or allowed in service room. 5) Emergency feeder for fire alarm to be taken from line side of generator switch. 6) Emergency switch for fire alarm can't be bonded with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						
	16A0541	Hatzel & Buehler, Inc. 230 Park Avenue, Suite 925 New York NY 10169	Requested approval for the electric service equipment proposed to be installed	719 Seventh Avenue New York NY	On Hold	\$650.00
<p>1) Short circuit study to be performed, signed and sealed by a P.E. 2) Verify that service entrance conductors are concrete encased from underground to 4th floor service room. 3) Show cable support boxes for the service entrance conductors. 4) Show Con-ED box on drawing 3. 5) Service entrance conductors undersized. 6) Derating is 70% for service entrance conductors. 7) Was service installed on ground floor and then moved to 4th floor?</p>						
	16A0543CO	Allan Briteway Electrical Contractors, Inc. 360 Lexington Avenue New York NY 10017	Requested approval for the electric service equipment proposed to be installed	25-70 Whitestone Expressway Queens NY	On Hold	\$0.00
<p>Carry over from July 13, 2016 meeting. 1) Provide sequence of operation. 2) Designer to appear at future meeting to explain installation, lack of information on submission.</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54050	16A0544CO	Forest Electric Corp. Two Pennsylvania Plaza, 4th Floor New York NY 10121	Requested approval for the electric service equipment proposed to be installed	11 Madison Avenue New York NY	Approved	\$0.00
Carry over from July 13, 2016 meeting. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54182	16A0548	Recon Electric 26 Bruckner Blvd. Bronx NY 10454	Requested approval for the electric service equipment proposed to be installed	500 West 21st Street New York NY	Approved	\$650.00
<p>1) Neutrals in Con-ED box to bonded to the enclosure. 2) Verify if generator is or not a separately derived system. 3) 3 or 4 pole ATS' being used. 4) Show short circuit current at fire pump controller, cut sheet not provided. 5) Is jockey pump controller service rated, show fault current at pump and provide cut sheet. 6) Fire pump CT to be 400A and 3 phase not single phase with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 11/1/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
	16A0574	Top Shelf Electric Corporation 4386 Victory Blvd. Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	55 Hudson Yards New York NY	On Hold	\$650.00
<p>1) Drawing 1-Fire pump emergency Board to be fed directly from line side of emergency switchboard. . 2) Drawing 1-show fuse size of normal supply to fire pumps. 3) Fire pump emergency feeders not fire rated. 4) Verify 120/208 volt fire pumps fed from 480V board. 5) Medium voltage feeders overfused. 6) Existing fusing for medium voltage feeders not shown on drawing. 7) Verify that there is a cutoff switch for the generator.</p>						
54067	16A0581	J.M.C. Electrical Corp. 172-02 39th Avenue Flushing NY 11354	Requested approval for the electric service equipment proposed to be installed	The Brooklyn Mirage 140 Stewart Avenue Brooklyn NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54185	16A0582	Litespeed Electric 135 West 29th Street New York NY 10001	Requested approval for the electric service equipment proposed to be installed	195 Broadway New York NY	Approved	\$650.00
1) Provide coordination study. 2) Provide main fuse type. 3) Provide cut sheet and rating for new devices. 11/116 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54173	16A0583	HIG Electric Associates NYC, Inc.. 25-26 50th Street Woodside NY 11377	Requested approval for the electric service equipment proposed to be installed	614 West 28th Street New York NY	Approved	\$650.00
Entrance to switchboard to comply with 110.26(c)(2) 24". 10/24/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54039	16A0587	RJ Russo Electric 45-57 Bell Blvd., Bayside ny 11361	Requested approval for the electric service equipment proposed to be installed	See comments for addressess and st	Approved	\$0.00
OR Job addresses 76 Pinehurst Avenue, 177 Wadsworth Avenue and 611 West 180th Street-Manhattan. Also, 350 Richmond Terrace-Staten Island. With the stipulation that Solar Edge Inverters. Models: SE5000 KUS, SE10KUS, SE20KUS, SE33.3 KUS, Solar Bos combiner boxes and Solar Edge Power Optimizer 1000 volt equipment be installed. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54032	16A0588	Nead Electric, Inc. 350 West 50th Street New York NY 10110	Requested approval for the electric service equipment proposed to be installed	Ziegfeld Theatre 141 West 54th Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54184	16A0589	Lippolis Electric, Inc. 3396 East Tremont Avenue Bronx NY 10461	Requested approval for the electric service equipment proposed to be installed	145 West Street New York	Approved	\$650.00
<p>1) Length of taps off of bus ducts not shown, 10'ok, 25' NG. 2) Equipment grounding conductors tapped from bus duct undersized 250.122(G). 3) 1 Line doesn't match physical 3000 amp service switch. 4) Fire pump service entrance conductors, feeders, and equipment grounding conductors to 125 HP fire pump undersized (Reversed). 5) Fire pump feeders not fire rated. 6) Separately derived generator to be bonded and grounded at generator, one location 250.30(A)(1). 7) Fire alarm service entrance equipment grounding conductor undersized. 8) Verify 16 sets of SEC's and EGC on each service. 9) Verify bus size feeding 1500 KVA transformer. 10) Bus off 1500 KVA transformer undersized. 11) 1500 KVA transformer secondary not bonded and grounded. 12) DPA-2-1 verify EGC between sections. 13) Feeder to panel DPA-1-1 overused with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 08/30/2016 1. Separately derived generator neutral to be bonded in location only</p> <p>2. Items 5, 6, & 13 not addressed with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 11/1/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54036	16A0595	John Stassi, Licensed Electrician 4347 Hyland Boulevard Staten Island NY 10312	Requested approval for the electric service equipment proposed to be installed	71 Broadway New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
	16A0596	Tru-Val Electric Corporation 2550 Park Avenue Bronx NY 10451	Requested approval for the electric service equipment proposed to be installed	222-11 56th Avenue Queens NY	On Hold	\$650.00
1) Generator overfused. 2) Which transformer from 16A0522 is feeding this switchboard? 3) Provide short circuit study performed, signed sealed and stamped by a P.E. 4) Typo on feeders supplying switchboard.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0597	Tru-Val Electric Corporation 2550 Park Avenue Bronx NY 10451	Requested approval for the electric service equipment proposed to be installed	222-25 56th Avenue Queens NY	On Hold	\$650.00
<p>1) Which transformer from 16A0522 is feeding switchboard. 2) Provide coordination study performed, signed and sealed by a P.E. 3) Tapped conductor to 400 amp device undersized with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						
	16A0598	Tru-Val Electric Corporation 2550 Park Avenue Bronx NY 10451	Requested approval for the electric service equipment proposed to be installed	222-05 56th Avenue Queens NY	On Hold	\$650.00
<p>1) Electrical room door to open outwards. 2) Which transformer on 16A0522 is feeding this switchboard? 3) coordination study performed, signed and sealed by a P.E. not provided. 4) There are only 2 transformers on 16A0522 that feed 3 switchboard, How? 5) Verify 130,000 short circuit current for switchboard.</p>						
54068	16A0600	Unity Electric Co., Inc. 65-45 Fresh Meadow Lane Flushing NY 11365	Requested approval for the electric service equipment proposed to be installed	3 Metrotech Center Brooklyn NY	Approved	\$650.00
<p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						
	16A0601	Fred Geller Electrical Inc. 54-15 38th Avenue Woodside NY 11377	Requested approval for the electric service equipment proposed to be installed	1133 Sixth Avenue New York NY	On Hold	\$650.00
<p>1) Show coordination emergency side. 2) Provide full size plan of generator and enclosure can't locate Gen PNL, transformers not show on 1 Line with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0602	Schimenti Construction Co. 622 3rd Avenue, 33rd Floor New York NY 10017	Requesting permission to leave as installed a 10 H.P. sprinkler booster pump installed in the basement without the feeder being fire rated.	H & M 129 Spring Street New York NY	Denied	\$350.00
54053	16A0603	Levinson & Santoro Electric 18-20 130th Street College Point NY 11356	Requested approval for the electric service equipment proposed to be installed	PS 42 488 Beach 66th Street Arverne NY	Approved	\$0.00
SANDY Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 11/29/16 Swapped drawings A and B-Revision 3.						
54083	16A0604	E D Electrical Inc. 5402 7th Avenue Brooklyn NY 11220	Requested approval for the electric service equipment proposed to be installed	324 West 44th Street New York NY	Approved	\$650.00
<p>1) Verify size of through bus in HCP distribution (X). 2) Show circuit breaker size and type feeding ATS. 3) Show coordination on emergency side from main breaker and panelboard with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 9/1/16 Job finalized. This drawing is approved with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54038	16A0606	John Stassi, Licensed Electrician 4347 Hylan Boulevard Staten Island NY 10312	Requested approval for the electric service equipment proposed to be installed	301 East 21st Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54069	16A0608	Eastern Electric Corp. of New York 511 East 233rd Street Bronx NY 10470	Requested approval for the electric service equipment proposed to be installed	2800 Victory Boulevard Staten Island NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54034	16A0609	Kleinknecht Electric Company, Inc. 252 West 37th Street, Suite 1402 New York NY 10018	Requested approval for the electric service equipment proposed to be installed	Sage Generator 437 Madison Avenue New York Ny	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54070	16A0612	E-J Electric Installation Co. 46-41 Vernon Blvd. Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	530 West 57th Street New York NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54071	16A0615	RGF Electric Corp. 2362 Westchester Avenue Bronx NY 10462	Requested approval for the electric service equipment proposed to be installed	229 Cherry Street New York NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54313	16A0616	Top Shelf Electric Corporation 4386 Victory Blvd. Staten Island NY 10314	Requested approval for the electric service equipment proposed to be installed	61 Bond Street Brooklyn NY	Approved	\$650.00
<p>1) Equipment grounding conductor off 2500 fusing undersized. 2) Coordination study performed signed and sealed by a P.E. not provided with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 1/12/17 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0617	Axcel Electric Company, Inc. 547 West 27th Street, Room 508 New York NY 10001	Requesting permission to leave as installed 2 hour Vitalink cable as a wiring method for fire pump wiring system.	310 East 67th Street New York NY	On Hold	\$0.00
	16A0618	RCM Technologies 99 Bauer Drive, Suite 101 Oakland NJ 07436	Requested approval for the electric service equipment proposed to be installed	19-39 20th Avenue Astoria NY	Denied	\$650.00
Submitted drawings are not in Advisory Board format, 2 sets of drawings are required.						
	16A0620	Zwicker Electric Co., Inc. 360 Park Avenue South New York NY 10003	Requested approval for the electric service equipment proposed to be installed	435 West 31st Street New York NY	On Hold	\$650.00

1) Switchboards misidentified on room layout. 2) 1 Line does not match physical MSA. 3) Fire pump panels not labeled on room layout. 4) Substations don't match physicals. 5) 36th floor substation door to open outwards. 6) Substation panels not identified as per physicals. 7) Fuse types not shown on 1 Line WT-1, WT-2. 8) C-3 bus on load side of transformer undersized. 9) Feeder to 36-2 substation overfused. 10) Fire alarm service equipment neutral to be bonded and grounded. 11) Note types of ATS being installed after 2nd fuses. 12) Feeder to 36-5 substation overfused. 13) Bus in 36-5 and C-4 substations undersized. 14) Is generator separately derived? Stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.
NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. Review Stopped.

With the stipulation:

Fire Rated Enclosure's must comply with the following:

1. A P.E. or R.A. must file a PWI as an AIT 3.
2. A Special Inspection TRI form must be submitted by a licensed fire inspection agency to sign off on the fire proofing installation.
3. The fire proofing must be performed by a certified fire proofing installer.

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54309	16A0621	W.T.G. Electric, Inc. 115-14 Beach Channel Drive Rockaway Park NY 11694	Requested approval for the electric service equipment proposed to be installed	53 West 72nd Street New York NY	Approved	\$650.00
1) Verify that service switches 1,2 and3 comply with 408.60(F). 2) Provide series rating chart 2000, 600 amp service switches to 2nd fusing. 3) Provide short circuit study and coordination. 1/10/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54040	16A0622	QEC Electrical Service Corp. 31-10 37th Avenue, Suite 500 Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	880 Bergen Street Brooklyn NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54041	16A0623	RM Electric Co., Inc. 9602 Glenwood, #318 Brooklyn NY 11236	Requested approval for the electric service equipment proposed to be installed	136-140 West 42nd Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54072	16A0624	Reliant Electrical Contracting Inc. 628 Classon Avenue Brooklyn NY 11238	Requested approval for the electric service equipment proposed to be installed	233 Landing Road Bronx NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54042	16A0625	FSM Electrical Corp. 36-08 9th Street Long Island City NY 11106	Requested approval for the electric service equipment proposed to be installed	88-11 165th Street Jamaica NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54073	16A0626	A Perfect Goldman Electrl Contrs. 2522 East Tremont Avenue Bronx NY 10461	Requested approval for the electric service equipment proposed to be installed	444 10h Avenue New York NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						
54044	16A0629	Response Electric, Inc. 36 Frost Street Brooklyn NY 11211	Requested approval for the electric service equipment proposed to be installed	630 Park Avenue New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54043	16A0630	NY Electrical & Maintenance Corp. 29-19 39th Avenue Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	112 West 34th Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54045	16A0631	Allstate Electrical Contracting, Inc. 120 West 31st Street, 7th Floor New York NY 10001	Requested approval for the electric service equipment proposed to be installed	5 East 59th Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 9/29/16 Swapped drawing 1-Revision 1.						
54074	16A0632	Cogen Electrical Services Inc. 528 Craven Street Bronx NY 10474	Requested approval for the electric service equipment proposed to be installed	422 Fulton Street Brooklyn NY	Approved	\$650.00
With the stipulation that signage is provided o the rear of the switchboards "Do not remove covers" Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54129	16A0633	Delco Electrical Corp. 241 West 37th Street, Suite 700 New York NY 10018	Requested approval for the electric service equipment proposed to be installed	Essex Crossing, Suite 700 115 Delancey Street New York NY	Approved	\$650.00
<p>1) Block rear of switchboards. 2) MDB-RES Section 3 does not match room layout and 1Line. 3) MDB1 switchboard overfused. 4) Remove 2nd switch feeding fire alarm transformer. 5) Fire pump emergency feeder not fire rated. 6) Verify amount of sets of conductors feeling C-M1-M. 7) Roll up generator to comply with 700.6(G). 8) Feeders to distribution 1-DB overfused. 9/20/16 This submittal had incorrect submittal number 16A0663 which belongs to another submitter. 9/30/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						
54132	16A0634	V-Mar Electric Ltd. 408 Grand Street Brooklyn NY 11211	Requested approval for the electric service equipment proposed to be installed	218 West 35th Street New York NY	Approved	\$650.00
<p>1) Service switch #A3, line and load side bus reversed. 2) Verify neutral conductors for fire pump emergency feeders. 3) Feeders to PNL EMDB1 not shown and size of PNL not shown with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review. NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. With the stipulation:</p> <p>Fire Rated Enclosure's must comply with the following:</p> <ol style="list-style-type: none"> 1. A P.E. or R.A. must file a PW1 as an AIT 3. 2. A Special Inspection TRI form must be submitted by a licensed fire inspection agency to sign off on the fire proofing installation. 3. The fire proofing must be performed by a certified fire proofing installer. 10/3/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements. 						
54075	16A0635	Power Surge Electric, Inc. 122-20 Montauk Street Springfield Gardens NY 11413	Requested approval for the electric service equipment proposed to be installed	2183 3rd Avenue New York NY	Approved	\$650.00
<p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54076	16A0636	Ideal Electric & HVAC Co., Inc. 235 India Street Brooklyn NY 11222	Requested approval for the electric service equipment proposed to be installed	740 Park Avenue New York NY	Approved	\$650.00
Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements						

	16A0637	Egg Electric Inc. 35 West 45th Street New York NY 10011	Requested approval for the electric service equipment proposed to be installed	7 West 34th Street New York NY	Pending	\$650.00
--	---------	---	--	-----------------------------------	---------	----------

1) 1 set of 350 KCM copper overfused. 2) Genset cut sheets showing listing not provided with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.
NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.

With the stipulation:

Fire Rated Enclosure's must comply with the following:

1. A P.E. or R.A. must file a PWI as an AIT 3.
2. A Special Inspection TRI form must be submitted by a licensed fire inspection agency to sign off on the fire proofing installation.
3. The fire proofing must be performed by a certified fire proofing installer.

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54228	16A0638	Soleire Electric Contracting Corp. 2424 49th Street Astoria NY 11103	Requested approval for the electric service equipment proposed to be installed	218 West 50th Street New York NY	Approved	\$650.00
<p>1) Room need to be mechanically ventilated. 2) Verify 225 KVA transformer secondary feeder size with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. 11/29/16 Job finalized. This drawing is approved with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p> <p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.</p>						
54077	16A0640	Aps Electric Inc. 2550 West 13th Street Brooklyn NY 11223	Requested approval for the electric service equipment proposed to be installed	550 West 29th Street New York NY	Approved	\$650.00
<p>This drawing is approved with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review. The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						
54078	16A0643	Atlas-Acon Electric 283 Hudson Street New York NY 10013	Requested approval for the electric service equipment proposed to be installed	601 Lexington Avenue New York NY	Approved	\$650.00
<p>Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements</p>						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
54046	16A0644	OM Electric, Inc. 262 West 38th Street New York NY 10018	Requested approval for the electric service equipment proposed to be installed	26 Little West 12th Street New York NY	Approved	\$650.00
OR Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54127	16A0645	Tri-tech Electrical East, Inc. 42-44 13th Street Long Island City NY 11101	Requested approval for the electric service equipment proposed to be installed	47-22 Pearson Place Long Island City NY	Approved	\$650.00
1) Section bus for S.S. 1,2 and 3 undersized. 2) Section bus for S.S. 4,5 and 6 undersized. 3) Vertical bus for S.S. 5 and 6 undersized. 9/29/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54130	16A0646	Pac Electric Corporation 124-20 Liberty Avenue Richmond Hill NY 11419	Requested approval for the electric service equipment proposed to be installed	123 Varick Avenue Brooklyn NY	Approved	\$650.00
Bus on load side of 1500 KVA transformers undersized. 10/3/16 Job finalized. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						
54048	16A0647	Five Star Electric Corp. 101-32 101st Street Ozone Park NY 11416	Requesting permission to utilize Vitalink 2 hour fire rated cable for fire alarm wiring due to structural, mechanical plumbing and electrical systems making it almost impossible to run conduit for the fire alarm system. The Vitalink will be installed in several location SC1, SC2, SC3, 1 mezzanine and 9th floor.	605 West 129th Street New York NY	Approved	\$0.00
With the stipulation that fire conductor to be installed as per manufacturers installation instruction. Disclaimer: Advisory Board approval is limited to materials received and reviewed by the Board. Contact Con-Edison regarding Blue Book requirements.						

ADVISORY BOARD CALENDAR

August 17, 2016

Approval #	Submission #	Applicant Name and Address	Type of Request	Installation Location	Status	Fee
	16A0648	Anthony G. Ferry Inc. 1916 Park Avenue New NY 10037	Requested approval for the electric service equipment proposed to be installed	303 West 46th Street New York NY	On Hold	\$650.00
<p>1) Section bus in TSQ-DP-1 undersized. 2) Verify that fire rated RHW-2 can be run in conduit instead of EMT for 40 HP fire pump. 3) Ground generator frame, is generator a separately derived system. 4) Add note under generator whether 3 or 4 pole ATS' will be installed. 5) Provide full size generator floor plan, plan submitted is confusing. 6) Verify address of job, doesn't match key plan. 7) Coordination study performed, signed and sealed by a P.E. not provided. 8) 1 Line drawing should have been made into 2 sheets confusing to read with the stipulation that the generator, feeders, switchgear, and enclosure (if installed) are listed as a complete assembly from the manufacturer bearing the listing label, section 110.3, and 110.2. The listing documentation is to be kept on site for inspector's review.</p> <p>The other option is for the equipment to be field evaluated and listed as a complete assembly by an OSHA recognized "Nationally Recognized Testing laboratory" (NRTL) bearing the listing label prior to DOB electrical inspection, the NRTL field evaluation report is to be kept on site for inspector's review.</p> <p>NOTE: Only NRTL authorized manufacturers can build, test, and list the equipment. It is the responsibility of the submitter to ensure compliance with section 110.2(A)(1), 110.2(A)(2), and 110.3 of the 2011 NYC Electrical Code.</p>						