



Photo 24: Looking south toward Storage Building (1961) which was clad in white brick in 1970, obscuring original facade arrangement.



Photo 25: View north along path toward relocated black granite columns in park area, southwest of West Battery.



Photo 26: Close-up of black granite columns which originally flanked main entry to Pump and Blower Building (1938). Columns were relocated to park following renovation of Pump and Blower Building in the 1970s.



Photo 27: Looking east toward Digesters from Preliminary Settling Tanks in East Battery. Note dome-shaped roofs pierced by multiple pipes.



Photo 28: Looking north toward Digester Tank No. 4. Asphalt-clad roof is in poor condition.



Photo 29: Looking west toward Digester Tank No. 2. Note Plexiglas roof light situated between four tanks.