

# Stuyvesant Park Area

## Pedestrian Access Improvements




### Background

- Community request for additional crossings around Stuyvesant Square Park
- Traffic controls denied at E 15<sup>th</sup> St through E 17<sup>th</sup> St between Rutherford Pl and Nathan D. Perlman Pl in April 2015

### Location

- Stuyvesant Park



### Improvements

- Enhanced crossings E 15<sup>th</sup> St, E 16<sup>th</sup> St and E 17<sup>th</sup> St at Nathan D. Perlman Pl, and at E 17<sup>th</sup> St and Rutherford Pl

### Benefits

- Safer pedestrian crossings